

GLO11052

COVE FORT SULPHURDALE UNIT #31-33

INDEX

Preface: Organization of Work

Chapter 1: Well Summary

Chapter 2: Geologic Report

Chapter 3: Well History

Chapter 4: Fishing Operations

Chapter 5: Time - Depth Progress Graph

Chapter 6: Logging Data

Chapter 7: Bit Record

Chapter 8: Cementing

Chapter 9: Drilling Fluid Summary (Magcobar)

Chapter 10: Corrosion Analysis

Chapter 11: Fluid Analysis

Chapter 12: Temperature - Pressure Surveys

Chapter 13: H₂S Safety Procedures

COVE FORT SULPHURDALE UNIT #31-33

PREFACE

Organization of Report

This report presents the technical details involved in the drilling of Union Oil Company's Cove Fort-Sulphurdale Unit Well #31-33. The report consists of the eleven chapters listed in the Index, as well as the well logs taken by Schlumberger, Geotex, and R. F. Smith. The contents of each chapter is summarized in the following. All depths in the report refer to rotating kelly bushing (R.K.B.) unless otherwise indicated. This is 20' above ground level (G.L.).

Chapter 1 presents a summary of the operations required to drill and complete CFSU #31-33. A listing of contractors used is also presented.

Chapter 2 summarizes what was learned about the hydrothermal system encountered by CFSU #31-33. This includes data on formation lithologies, fluid chemistries, and other geological information.

Chapter 3 contains a well history describing the day to day operations during the drilling of CFSU #31-33. Also included is a detailed description of the casing strings, and a listing

of deviation surveys with the corresponding maximum reading thermometer results.

The two fishing operations engaged in while drilling this well are described in Chapter 4.

A time-depth progress graph is presented in Chapter 5. This graph also indicates the occurrence of events of major technical interest while drilling CFSU #31-33.

Chapter 6 lists the various kinds of logging data taken during the drilling of CFSU #31-33. Copies of each of the individual logs are supplied with the report. Maximum reading thermometer temperature surveys taken at various times when the hole had been static for two or more hours are also listed here.

Chapter 7 presents technical information about the drill bits used in CFSU #31-33.

Chapter 8 describes cementing operations carried out during casing jobs, while trying to control lost circulation, and while abandoning the lower section of the hole.

Chapter 9 is a technical summary of the drilling fluids used in drilling this well. This section was prepared by Baroid, the sales, service and engineering company responsible for the drilling fluids program.

Chapter 10 contains a summary of tubular goods corrosion which occurred while using aerated water as a drilling medium, as well as Union's attempts to maintain control.

Chapter 11 describes the equipment and procedures used on the wellsite to protect personnel from the potential danger of H₂S gas.

COVE FORT SULPHURDALE UNIT #31-33

OUTLINE

- I. General Information
 - A. Well Record
 - B. Contractors Used
- II. Drilling Operations
 - A. Rig Information
 - B. Preparation of Location and Setting of Conductor to 52' (R.K.B.)
 - C. 26" Hole: 52' to 289' (20" Casing Set to 280')
 - D. 17-1/2" Hole: 289' to 1735' (13-3/8" Casing Set to 1733')
 - 1. General Description of Hole Drilled
 - 2. Problems Encountered and Their Resolution
 - a. Parted Shock Sub at 711'
 - b. Complete Loss of Circulation: 1236' to 1276'
 - c. Complete Loss of Circulation at 1564'
 - d. Complete Loss of Circulation at 1735'
 - E. 12-1/4" Hole: 1735' to T.D. at 5221' (Hole Plugged Back to 2600')
 - 1. General Description of Hole Drilled
 - 2. Problems Encountered and Their Resolution
 - a. Complete Loss of Returns at 2015': Rig Up for Aerated Water Drilling

- b. Intermittent Returns to Surface: 2015' to 4832'
- c. Parted Shock Sub at 2920'
- d. No Returns to Surface: 4832' to T.D. at 5221'
- 3. Coring Efforts 5015' to 5021'
- 4. Logging Efforts
- 5. Plugging Back to 2600'
- F. Well Completion

III. Post-Drilling Operations

COVE FORT SULPHURDALE UNIT #31-33

I. GENERAL INFORMATION

UNION OIL CO. OF CALIFORNIA
GEOHERMAL DIVISION

A. WELL RECORD

LEASE <u>Cove Fort Sulphurdale Unit</u> WELL # <u>31-33</u> FIELD <u>Cove Fort</u> LOCATION <u>N89°28'W 1092.23 and South 479.21'</u> <u>from the South 1/4 corner of Section 28,</u> <u>T25S, R6W, SLM. (The well is located</u> <u>in Section 33, T25S, R6W, SLM.)</u> B.H.L. _____ DEPTH: T.D. <u>5221'</u> T.V.D. <u>5165'</u> E.T.D. <u>2600'</u> COMPANY ENGINEER <u>Harold Moss</u>	SPUD DATE <u>5/24/78</u> COMP. DATE <u>7/27/78</u> CONTRACTOR <u>Loffland Brothers Company</u> RIG # <u>5</u> ELEVATIONS: GROUND <u>6480'</u> K.B. TO GROUND <u>20'</u> K.B. TO LOWER CASING HEAD _____ TYPE WELL: EXPL. <u>XX</u> DEV. _____ STM <u> </u> HOT WTR <u>XX</u> INJ _____ DRY HOLE _____ APPROVED <u><i>Harold Moss</i></u>
---	--

CASING RECORD

SIZE	WEIGHT	GRADE	THREAD	TOP	BOTTOM	REMARKS
30"	.375" wall	H-40	Welded	G.L.	32' below G.L.	cemented surface to 32'
20"	94#/ft	H-40	Buttress	20' K.B.	280' K.B.	cemented surface to 280'
13-3/8"	54.5#/ft	K-55	Buttress	20' K.B.	1733' K.B.	cemented surface to 1733'
2-7/8"	6.4#/ft	K-55	EUE 8RD	20' K.B.	2579.53'	hanging tubing with bottom joint perforated

WELL HEAD ASSEMBLY

	MAKE	TYPE	SIZE	PRESSURE RATING
CASING HEAD SPOOL	WKM	S.O.W.	13-3/8"x12"	3000#
SPOOL	Midway Fishing Tool	Tubing Hanger	12"x6"	3000#
ADAPTER	WKM	Double Studded	6"x3"	3000#/2000#
CASING HEAD VALVES	WKM	Gate	3"	2000#
HANGER SPOOL VALVES	Midway Fishing Tool	Blind Flange	2"	3000#
SWAB VALVE	WKM	Gate	3"	2000#

STEAM ENTRIES:	<u>DEPTH</u>	<u>LBS. INCREASE</u>
-----------------------	--------------	----------------------

Not Applicable

SLOTTED LINER	SLOTS		BLANK	
	FROM	TO	FROM	TO
2-7/8" EUE 8RD Tubing	2550.11	2579.53	G.L.	2550.11

TEST DATA	<u>ORIFICE SIZE</u>
<u>RIG TEST DATE</u>	<u>POUNDS/HOUR</u>
<u>WHP</u>	
<u>FLP</u>	
<u>TEMP</u>	

REMARKS: Total Cost of Well = \$1,270,000

Cost Per Foot = \$243.25

B. CONTRACTORS USED

Baroid

Basin Mud Service

B&W, Inc.

Christensen Company

Cove Fort Service

Del Mar Construction

Donham Oil Tool

Dresser Industries

Francis Engine Service

Geotex

Grant Oil Tool

Duane Hall Trucking

Halliburton

HOMCO

Howard Construction

Hughes Tool Company

Marion Kessler

La Sal Oil Company

Loffland Brothers

Mac's Welding

Bill Martin Rathole Service

Midway Fishing Tool

Mountain States Inspection

Oilwell Supply

Pipe Sales Company

B. CONTRACTORS USED (cont'd)

San Juan Casing Service

Schlumberger

R. F. Smith Corporation

Smith Tool Company

Thatcher Chemical

West Coast Oil Tool

W-K-M Wellhead Systems

COVE FORT SULPHURDALE UNIT #31-33

II. DRILLING OPERATIONS

A. RIG INFORMATION:

Loffland Brothers Rig #5 is an Ideco 1000 Portable Mast and 20' substructure with an Ideco H-1000 Drawworks. The rig is rated to drill to a depth of 12,000'. It is powered with two V12 GMC Diesel Engines rated at 434 INT. h.p. each at 1800 RPM. The telescoping Mast is 112' in height. The rotary table is an Ideco 27-1/2". The rig is limited to a 350,000# casing capacity.

B. PREPARATION OF LOCATION AND SETTING OF CONDUCTOR

TO 52' (R.K.B.):

At the end of 1977, various operations were conducted to prepare the location for drilling. The location, sump and roads were built to specifications laid out in the "Approved Unit Plan of Operations:.. A 36" conductor hole was drilled to 32' G.L. (52' R.K.B.) by Bill Martin Rathole Service. Thirty inch (30") conductor pipe was run and cemented from surface to 32' G.L. (52' R.K.B.) with Ready-Mix Cement.

C. 26" HOLE: 52' to 289': (20" Casing Set to 280')

Loffland Rig #5 moved in, rigged up, and was placed on day rate at 1200 hours, 5/24/78. Drilled mouse and rat holes. The well was spudded in at 2000 hours on 5/24/78, and 17-1/2"

C. Continued -

hole was drilled to 301' (recent alluvium to 180', andesite below). The hole was opened to 26" from 52' to 295'.

Two hundred-ninety four feet (294') of 20", 94#/ft K-55 buttress casing was set and cemented to surface. The 20" and 30" casing were cut off to ground level. A 20" Hydril GK and Double Shaffer blowout preventer was installed and tested to U.S.G.S. specifications.

D. 17-1/2" HOLE: 289' to 1735': (13-3/8" Casing Set to 1733')

1. General Description of Hole Drilled

The 17-1/2" hole was drilled from 289' to 1733' (open hole and fill, 280' - 301'; andesite beginning at 301') with severe lost circulation problems. A parted shock sub while drilling at 711' necessitated a fishing job at this depth.

Complete loss of circulation occurred numerous times over the interval 1236' to 1276' while drilling dolomitic limestone and dolomite. Nineteen lost circulation plugs (total volume of 4193 ft³ cement) were set during the eight days required to drill this section. A total of 340 bbls mud were lost while drilling continued in dolomitic limestone and dolomite from 1276' to 1564', at which depth complete loss of circulation occurred. Circulation was partially gained with the placement of

D. Continued -

cement plug #20. A total of 410 bbls mud were lost while drilling occurred in the same formation from 1564' to 1735'. Complete loss of circulation occurred at this depth while circulating and conditioning mud to run 13-3/8" casing. Five more lost circulation plugs were set (558 ft³ cement) before circulation was regained.

1,733' of 13-3/8", 54.5 #/ft, K-55 buttress casing was set and cemented to surface. The 13-3/8" casing was cut off to surface, and 12" - 3000# B.O.P. equipment was installed and tested to U.S.G.S. specifications.

2. Problems Encountered and Their Resolution

a. Parted Shock Sub at 711'

A shock sub parted while drilling at 711'. The lost tools were recovered on first run with an overshot fishing tool.

b. Complete Loss of Circulation: 1236' to 1276'

Complete loss of circulation occurred at 1236', but drilling continued to 1241'. The hole made H₂S while pulling the drill string, and H₂S alarms were set off at a level of 10 ppm.

Seven cement plugs (total volume = 1925 ft³) were set in an attempt to plug the lost circulation zone. The formation accepted all the cement, but

2. b. Continued -

the H₂S flow and an initial seep of methane were completely eliminated after the fifth plug.

A 17-1/2" drilling assembly was run to clean out a bridge from 1236' to 1241', and to drill from 1241' to 1252', with no drilling fluid returns. 500 bbls mud was lost while drilling at a rate of 20' - 30' per hour. There was no evidence of torquing, additional fractures, or running dolomite from 1241' to 1252'.

Five additional cement plugs (total volume 1090 ft³) were set through open ended drill pipe at 1250'±.

The fluid level in wellbore was located at 600' using a wireline and wooden float, but there was no cement to be found in the hole.

Cement plug #13 (166 ft³) was set through open ended drill pipe at 1250'±. The top of the cement was located at 1160'. The cement was drilled with a 17-1/2" drilling assembly from 1160' to 1252'.

Complete loss of circulation occurred at 1236'.

New 17-1/2" hole was drilled from 1252' to 1257' with no drilling fluid returns.

Four additional cement plugs (total volume = 662 ft³) were set in an attempt to plug the lost circulation

2. b. Continued -

zone. Cement was located at 1221' following plug #17.

Firm cement was drilled out from 1221' to 1247' at which depth complete loss of circulation occurred.

Cement plug #18 (235 ft³) was then set. Preceding the injection of cement, three separate attempts were made to plug up the lost circulation zone by injecting 90 ft³ amounts of a water/polymer lost circulation compound. We were unable to fill the hole following each attempt.

The top of the cement from plug #18 was located at 1183'. Firm cement was drilled out from 1183' to 1257', drilling continued in dolomitic limestone and dolomite from 1257' to 1276'. Complete loss of returns occurred at 1274'.

At this depth cement plug #19 (115 ft³) was preceded by a 112 ft³ mixture of water/polymer lost circulation compound. The top of the cement was located at 1230'.

c. Complete Loss of Circulation at 1564'

Fluid returns were lost completely at 1564' after having lost a total of 340 bbls mud over the interval

2. c. Continued -

1380' to 1564'. The drill pipe became stuck while pulling out of the hole, but was worked free in four hours.

Cement plug #20 was then set (115 ft³), but was preceded by 95 ft³ of water/polymer lost circulation compound.

The top of the cement was found at 1487'. Cement was cleaned out to 1500' with full drilling fluid returns. Circulation was lost completely at 1500', but was regained with 500 bbls of water.

The hole was then cleaned out to 1564'.

d. Complete Loss of Circulation at 1735'

A 17-1/2" hole was drilled in dolomite from 1564' to 1735', while losing a total of 410 bbls mud.

While circulating and conditioning mud in preparation for running 13-3/8" casing, drilling fluid returns were lost completely.

Five additional cement plugs were set (nos. 21-25, total volume = 594 ft³), three of which were preceded by the water/polymer lost circulation compound

(total volume = 316 ft³). Following the last plug, the hole was cleaned out to 1735' with no loss of

2. d. Continued -

mud, and the 13-3/8" casing was successfully run and cemented.

E. 12-1/4" HOLE: 1735' to T.D. at 5221' (Hole Plugged Back to 2600')

1. General Description of Hole Drilled

The 12-1/4" hole was drilled from 1735' to total depth at 5221' with continued lost circulation problems (1735' to 2770' in dolomitic limestone and limestone, 2770' to 4787' in siltstone and sandstone, and 4787' to 5221' in dolomite). After complete loss of circulation occurred at 2015', the remainder of the hole was drilled with chemically treated aerated water. There were intermittent returns to the surface from 2015' to 4832', and none from 4832' to total depth at 5221'.

A parted shock sub required fishing at 2876'.

Coring was attempted from 5015' to 5021' with only limited recovery. Various Schlumberger and Geotex well logs were run to 5200'±.

Efforts to abandon the lower portion of the hole were then begun. The 12-1/4" hole was plugged back to 2600' after setting 15 cement abandonment plugs.

E. 2. Problems Encountered and Their Resolution

- a. Complete Loss of Returns at 2015': Rig Up for Aerated Water Drilling

After circulation was lost completely at 2015', drilling continued with chemically treated aerated water.

While rigging up for drilling with air, a bottom hole temperature of 210°F was measured. The hole had been static for 12 hours.

- b. Intermittent Returns to Surface: 2015' to 4832'

A 12-1/4" hole was drilled in dolomite from 2019' to 2672' using the chemically treated aerated water.

Cuttings or liquid returns were not obtained while drilling this interval. Intermittent returns of water and cuttings were obtained from 2151' to 2550', while no returns were obtained from 2550' to 2672'.

Intermittent returns by heads were obtained every three to four hours while drilling from 2672' to 2920', at which depth a shock sub parted, requiring fishing.

Drilling continued, from 2920' to 3250'. Some intermittent cold water returns were experienced with temperatures from 50°F to 171°F. A 12-1/4" hole was drilled to 3765' and additional jet subs were added to the drill string to aid in lifting fluid and sodium nitrate was added to the injection water to control the increasing severe corrosion rate of 42.8 lbs/ft/year.

E. 2. b. Continued -

The 12-1/4" hole continued to be drilled to 4832' with intermittent fluid returns to surface. Temperature surveys at 4675' indicated 292°F after five hours static, and 292°F at 4735' after 18 hours static.

c. Parted Shock Sub at 2920'

At 2876', the shock sub failed, required fishing, and was recovered on the first attempt.

d. No Returns to Surface: 4832' to T.D. at 5221'

A 12-1/4" hole was drilled to 5009', without returns to surface.

Formation voids were noted at 4852' and 4858'.

Drill cutting fill impaired drilling and caused drill string sticking.

Continual replenishment of the drill water supply was hampered due to lack of available tank trucks, although four in use.

An attempt to consolidate formation fill and regain partial returns was made by displacing a sodium silicate-calcium chloride solution, followed by cement-Perlite-silica flour-gel plugs and the hole filled to 4753'.

A 12-1/4" drilling assembly was run and cement drilled

E. 2. d. Continued -

from 4753' to 4926', a void from 4926' to 4935' and fill was encountered from 4935' to 5009', with no fluid returns to surface. 12-1/4" hole was drilled to 5221'.

3. Coring Efforts - 5015' to 5021'

An attempt was made to obtain two cores of the formation, without success and only 8" of core, a highly fractured dolomite was recovered.

4. Logging Efforts

Two Schlumberger temperature logs, a DIL-8 and CNL-FDC, and a 4-arm Dipmeter with Caliper log were run. They indicated dolomite from 1735' to 2770', siltstone and sandstone from 2770' to 4782' and dolomite from 4782' to 5221'. Maximum reading thermometer temperatures were 282°F.

A Geotex Temperature Log, water aquifer locator and radioactive tracer were run, indicating cross flow of fluid, up and down the hole. The previous temperature were confirmed.

5. Plugging Back to 2600'

Lower hole section abandonment operations consisted of: cement plugs with lost circulation material; modified formation consolidation treatments; and the installation

E. 5. Continued -

of two Halliburton EZSV 13-3/8" plugs. These operations resulted in the establishment of a plug from 5221' to 4728', and from 2750' to 2552'. The upper plug was drilled out to 2600'. The plugs were installed by U.S.G.S. direction in order to eliminate possible commingling of formation fluids.

F. WELL COMPLETION

A 2-7/8" EUE 8RD 6.4#/ft tubing temperature survey string was hung in a Shaffer tubing head at the surface. The bottom joint of tubing, 30', was perforated and orange peeled with a 3/4" hole in the bottom. The bottom tubing joint is located at 2558', ground level.

The purpose of this completion arrangement was to facilitate the execution of future temperature surveys in the upper portion of the hole.

The Loffland Brothers Company rig, #5, was released at 1800 hours, 7/27/78.

COVE FORT SULPHURDALE UNIT #31-33

III. POST DRILLING OPERATIONS

Current plans are to continue monitoring temperatures in the upper portion of the hole. Union personnel carried out a temperature survey of the completed zone on August 9, 1978.

GEOLOGIC REPORT ON THE
COVE FORT-SULPHURDALE UNIT #31-33
MILLARD COUNTY, UTAH

LITHOLOGY

The CFSU 31-33 well was drilled to a total depth of 5221 feet where a sequence of soft dolomitic shale and brecciated and fractured dolomite is present. The sequence of rock units encountered in the 31-33 well differs from that found in the CFSU 42-7 well, indicating that the local subsurface structure has considerably altered the normal stratigraphic sequence in the area. Those rock units that are present in both wells show significant variation in degree of alteration and metamorphism.

The following is a description and discussion of the rock types encountered in CFSU 31-33 from the surface to the total depth. The descriptions are based on examination of the well cuttings by binocular microscope and one x-ray diffractometer analysis.

Recent alluvium is present from the surface to approximately 180 feet. The alluvium consists of hydrothermally altered volcanic pebbles, gravel, and sand with abundant limonite staining.

Interval.....180-1005'
Formation.....Bullion Canyon Volcanics
Age.....Oligocene and Miocene(?)
Lithology.....Andesite

The well penetrated 825 feet of Mid-Tertiary extrusive volcanics, the majority of which were characterized by extensive chloritic and argillic alteration. The volcanics can be divided into two major units based on the texture and composition of the samples. The upper unit (180-530 feet) consists of a greenish to reddish-gray porphyritic andesite and a minor greenish-gray aphanitic andesite. The fine to medium-grained phenocrysts are predominately feldspar, with trace pyroxene, and trace to rare biotite, calcite and quartz. In most cases, the pyroxene and biotite have been bleached or chloritized and some feldspar phenocrysts have been altered to kaolinite. The chloritization appears to increase with depth.

The lower unit (530-1005 feet) is characterized by the appearance of abundant pyrite and siliceous fracture-filling material. The volcanics of this unit consist of a gray, fine-grained porphyritic andesite and a chloritized and silicified greenish-gray, medium-grained porphyritic andesite. The phenocrysts consist mainly of white, subhedral feldspar, chloritized biotite and pyroxene, trace magnetite, and trace to rare calcite. Quartz

phenocrysts are generally absent in the lower unit. Minor amounts of a pale reddish-orange welded tuff are present from 690-700 feet. The base of the volcanics is characterized by decreasing amounts of pyrite and siliceous fracture-filling material, and increasing amounts of calcite and greenish to reddish-gray porphyritic andesite. This andesite is similar to the andesite of the upper unit. Some of the volcanics from 730-1005 feet appear to be brecciated. Two fracture zones were encountered at 530-550 feet and 620-650 feet.

Interval.....1005-1150'
Formation.....Claron(?)/North Horn(?) formation
Age.....Upper Cretaceous(?) to Paleocene(?)
Lithology.....Siltstone

An unconformity between the Bullion Canyon Volcanics and the Claron formation was penetrated at 1005 feet.

The Claron formation consists of a poorly-sorted red siltstone with fine to medium-grained subrounded quartz and quartzite clasts and medium to coarse-grained limestone clasts in a clayey red matrix cemented with calcite. The siltstone is moderately well-cemented and contains minor calcite-filled fractures. The quartz and limestone clasts become coarser-grained near the base of the formation as the siltstone becomes conglomeratic in part. This 145-foot section of red siltstone is generally hard and unfractured, with very low porosity.

and secondary sulphide minerals is similar to an interval described as Lower Permian Pakoon dolomite in the CFSU 42-7 well. However, a prominent sandstone marker bed in the Pakoon dolomite is absent in the CFSU 31-33 well.

The dolomite below the cherty interval is predominately dark grayish-brown, fine to medium-grained and slightly calcareous with minor brecciated calcite and siliceous veins. Rare crinoid stems are present from 1570 to 1590 feet. The dolomite becomes more calcareous with depth, accompanied by an increase in brecciation and calcite veining. This interval of dark gray crystalline calcareous dolomite could be tentatively correlated with the Pennsylvanian Callville (Oquirrh) formation.

A second major lost circulation zone was encountered at 2010 feet. Minor amounts of hydrogen sulphide gas were present at 2080 feet. Sample returns were minimal throughout the interval 2010-3030 feet, but generally consisted of brecciated crystalline dolomite.

The dipmeter log was run from 1733' to the total depth. The dips of the carbonate in this interval are extremely erratic, indicating the presence of many cavities and fractures.

The age and correlation of the carbonates in the interval 1150-2770 feet is uncertain. Dolomitization may have destroyed

Minor fractures are present in the red siltstones, but most fractures are filled with calcite. The white to pale red sandstones vary from being moderately well-cemented with silica and calcite to friable and poorly-cemented.

Formation dips obtained from the dipmeter log are fairly consistent throughout the Red Beds. The strike of the Red Beds ranges from E-W to N46W, averaging N75W. The dips range from 20° NE to 42° NE, averaging 22° NE. Variations in the strike and dip generally occur at the transitions between sandstone and siltstone beds and at minor fracture zones in the siltstones.

Interval.....4787-5221'
Formation.....Unknown
Age.....Pre Triassic
Lithology.....Dolomite

A major lost circulation zone was encountered at 4787 feet. The only sample return was obtained from the interval 4790-4800 feet. This sample consists of a medium gray to black very fine-grained, loosely-consolidated, slightly calcareous shale or siltstone. A powder x-ray diffractometer analysis was run at the University of Utah to determine the bulk composition of the sample. The three major constituents of the sample are quartz, K-mica, and dolomite.

Two cores were cut at 5015 to 5018 feet and at 5018 to 5021 feet. There was eight-inch recovery on the first core.

Core #1 is a medium to dark gray fractured and brecciated dolomite. There was no recovery of Core #2.

The drill rates in this interval were very erratic, ranging from 150 feet/hour to 5 feet/hour. Several cavities and fracture zones one-to-two-feet thick were encountered.

The dips obtained from the dipmeter log in this unit are not quite as consistent as those in the Triassic Red Beds, and there were several intervals in which no dips were recorded. The average strike of the dolomite unit is N50W. The average dip is 22° NE. The contact with the Red Beds appears to be a fault or disconformity.

It is difficult to determine the formation and age of this unit because of the slight returns and brecciated nature of the dolomite. If the contact with the Red Beds is a thrust fault or disconformity, then the dolomite could belong to any of the pre-Triassic carbonates such as the Kaibab limestone, Pakoon dolomite, or Callville limestone. Detailed micro-paleo examination of the core might aid in the correlation of this unit.

GEOCHEMISTRY

While drilling with aerated water from 2021 to 5221 feet, formation water entered the borehole and circulated to the surface with the injected water. In order to determine the geochemistry of the system, flowline samples were collected during periods in which there were substantial fluid returns with relatively high temperatures and low pH compared to the injected water.

It was shown by a tracer survey run by GeoTex Corp. that fluid from the interval ~~4800-5000~~ feet was flowing upward to 2010 feet at a rate of greater than 500 bbls/hr. It was also found that fluid was flowing downward to 5175 feet at the rate of 10 to 20 bbls/hr. A sample of the fluid flowing up the wellbore was collected by entering the hole with drill pipe that had an inverted float sub on the bottom and a jet sub three stands above the float sub. The drill pipe was lowered to approximately 3000 feet. Fluid entered the drill pipe through the inverted float sub which allows fluid movement in only one direction. As the drill pipe was pulled up, the 90 feet of fluid between the float sub and jet sub was trapped and brought up to the surface.

The chemical analyses of the water samples were done by Ford Chemical Laboratory, Inc. in Salt Lake City. The results of these analyses are included in the appendix. Figures 1 and 2 are graphs of significant chemical constituents

plotted against the depth when the samples were collected.

The maximum salinity attained in the flowline discharge was 10,000 ppm at 4170 feet. The marked decrease in salinity at 4800 feet to 1320 ppm is probably due to lower salinity water flowing into the borehole after the dolomitic shale and dolomite breccia were penetrated at 4787 feet.

Tables 1 and 2 contain data based on the silica and Na-K-Ca geothermometer calculations of the flowline discharge and fluid from the 4800-5000 foot interval. The equation used for the silica calculations was: $t^{\circ}\text{C} = (1315/5.205 - \log \text{SiO}_2) - 273.15$.

The equation used for the Na-K-Ca calculations was:

$t^{\circ}\text{C} = (1647/\log(\text{Na}/\text{K}) + 3 \log(\sqrt{\text{Ca}}/\text{Na}) + 2.24) - 273.15$. * Silica temperature estimates were calculated for both diluted and undiluted samples for each sample interval.

The most reliable silica temperature estimate, 379°F, is from the diluted sample collected at 4170 feet. This sample reached the laboratory within four days and was collected when the TDS were at a maximum.

The Na-K-Ca reservoir temperature estimates were very high and

*Proceedings of the Second UN Symposium on Development and Use of Geothermal Resources, Vol. I, p. lxxiii (1975).

less believable than the estimates from the silica calculations. The best Na-K-Ca temperature estimate, 495°F, is from the sample collected at 4170 feet. This sample probably has the least contamination and dilution of all the flowline samples because of its high salinity.

The flowline sample collected at 4170 feet probably best represents the geochemistry of the geothermal reservoir because of its high salinity and chemical similarity to water believed to represent the reservoir in the CFSU 42-7 well. The sample from 4170 feet is also the last flowline sample collected before lower salinity fluid entered the borehole around 4800 feet.

The borehole water sample from 4800 feet is more similar in chemistry to meteoric water than to the formation water samples collected at the flowline while drilling. This lower salinity fluid is probably local ground water. According to the free water level in the well measured after the zone at 4800 feet was plugged, the ground water table is approximately 1400 feet below the surface. The permeable dolomites in the interval 4800 to 5000 feet could intersect a part of the water table that had been faulted up to a level above 1400 feet, or the dolomite could be in fault communication with near-surface meteoric water several hundred feet above the deep ground water. The

dolomite would act as a conduit through which the water would flow down dip. The Red Beds above the dolomite form an effective aquiclude. When the 4800 to 5000 feet zone was penetrated during drilling, the difference in head would cause the water to flow upward.

DISCUSSION

Figure 3 is a graph of the temperature profiles from surveys taken after reaching the total depth. The temperature profiles show the presence of a thermal conductive zone in the Bullion Canyon volcanics from the surface to approximately 1000 feet. Temperature gradients in this zone range from 6° to 20°F/100 feet. An isothermal zone is present from 1000 feet to about 1600 feet in red siltstone and dolomitic limestones. There is a small temperature increase around 1400 feet, which corresponds to the free water level in the well. A second conductive zone is present from 1600 feet to 2000 feet in brecciated dolomite. Temperature gradients in this zone range from 5° to 26°F/100 feet. A nearly isothermal zone occurs in the dolomite and Red Beds from 2000 feet to 4800 feet. Below 4800 feet, there is a temperature reversal to 5200 feet.

The isothermal zone in the interval 2000 to 4800 feet is probably the result of low salinity fluid from 4800 feet flowing up the wellbore and out into the formation to about 2010 feet. Tempera-

tures recorded by maximum-reading thermometers during deviation surveys range from 210°F at 2000 feet to 294°F at 4700 feet (Table 3). After penetrating the zone at 4800 feet, the temperatures recorded by maximum-reading thermometers were consistently 291-294°F, above 5000 feet. The hole had been static (no circulation of injected water) for two hours when the reading was taken at 4700 feet. After a static time of 18 hours, the reading at 4735 feet was also 293°F. Normally, after 18 hours of static time, a temperature build-up at this depth would be expected. Therefore, the fluid flowing up the wellbore may have had a slight cooling effect on the zone above 4800 feet, or the maximum temperature at 4735 feet could be 293°F.

The temperature reversal from 4800 to 5200 feet could have resulted from several factors. It could be a temporary reversal within the reservoir while drilling through the descending (cold) limb of a convection cell. If that is the case, then a positive gradient would be encountered by drilling deeper. The reversal could also indicate that the well had penetrated the edge of a geothermal system and then drilled out of it into the cooler rock below.

It is difficult to determine the reservoir characteristics of this geothermal system because of the cooling effect of the fluid flowing up the wellbore from 4800 feet and the lack of sub-

stantial fluid and rock sample returns while drilling. Samples of warm formation fluid were obtained from 2455 to 4170 feet. However, it is not known whether these fluids exist in isolated fractures or in an interconnecting fracture system forming a liquid-dominated convective reservoir.

The Bullion Canyon volcanics and Claron formation were not as thick as expected in the CFSU 31-33 well, and as a result, dolomite and dolomitic limestones were encountered above the water table. However, unlike the unconsolidated ("sanded") dolomite that occurred above the water table in the Forminco #1 well, dolomite samples in the 31-33 well showed no signs of sanding. A minor dolomitic siltstone was present above the lost circulation zone at 1233-1270 feet where H₂S was encountered, but it did not resemble the unconsolidated crystalline dolomite from the Forminco #1 well. The samples below that first lost circulation zone in the 31-33 well are hard, crystalline to aphanitic dolomitic limestones and dolomites. These dolomites are above the water table and show no signs of sanding.

A P P E N D I X





Figure 1

56



Chemistry of Flowline and Borehole Water Samples

Figure 2

K&E
 10 X 10 TO 3/4 INCH 7 X 10 INCHES
 KEUFFEL & ESSER CO. MADE IN U.S.A.

46 1320

Depth in ft.




Figure 3

Temperature Surveys

CFSU 31-33

	DATE	STATIC TIME	CONTRACTOR
x-----x	July 18, 1978	5 hours	Schlumberger
-----o	July 19, 1978	24 hours	Schlumberger
-----A	August 9, 1978	21 days	Union
-----o	July 19, 1978	30 hours	GenTex Corp.

Estimation of Subsurface Temperatures from
the Silica Content of Water from the Flowline
Discharge and Borehole Water Samples, CFSU 31-33
Millard Co., Utah

TABLE 1

Depth, ft	Temperature of Flowline, °F	pH	TDS	SiO ₂ of diluting water	SiO ₂ of diluted sample	Volumetric Ratio of Dilution: Fresh wtr/sample	Calculated SiO ₂ of sample	SiO ₂ of undiluted sample	Estimated temperature from SiO ₂ , °F (diluted sample)	Estimated temperature from SiO ₂ , °F (undiluted sample)
2455	138	8.77	7600	5.0	15.0	9:1	105	77.5	284	254
2825	79	7.38	7655	5.4	22.0	9:1	171.4	25.5	337	163
3720	155	7.94	8000	5.4	26.0	9:1	211.4	64	362	237
4170	102	9.79	10,000	5.4	29.0	9:1	241.4	79	379	256
4800	?	7.44	1320	22.5	34.5	9:1	142.5	64.5	316	237

Estimation of Subsurface Temperatures from the
 Empirical Na-K-Ca Geothermometer for Flowline
 Discharges and Borehole Water Samples, CFSU 31-33
 Millard Co., Utah

TABLE 2

Depth, ft	Temperature of Flowline °F	TDS	Na	K	Ca	Estimated Temperature from Na-K-Ca $\beta = 1/3$ °F
2455	138	7600	2530	423	5.6	554
2825	79	7655	2475	452	200	482
3720	155	8000	2916	465	62.4	497
4170	102	10,000	4000	443	14.4	495
4800	?	1320	355	56.2	74.4	407

COVE FORT - SULPHURDALE #31-33
 MAXIMUM READING THERMOMETER TEMPERATURE SURVEYS

TABLE 3

<u>DATE</u>	<u>TIME SINCE CIRCULATION STOPPED</u>	<u>THERMOMETER READING</u>	<u>DEPTH</u>
05-28-78	<30 min.	103°F	262'
06-02-78	<30 min.	108°F	445'
06-03-78	<30 min.	118°F	608'
06-04-78	<30 min.	120°F	733'
06-05-78	<30 min.	139°F	899'
06-05-78	<30 min.	138°F	987'
06-06-78	<30 min.	150°F	1080'
06-15-78	15 min.	122°F	1332'
06-16-78	15 min.	118°F	1400'
06-27-78	15 min.	133°F	1945'
06-28-78	12 hours	210°F	2000'
06-30-78	15 min.	138°F	2354'
07-04-78	1.3 hours	234°F	3250'
07-05-78	1.2 hours	260°F	3625'
07-08-78	2.2 hours	285-290°F	4090'
07-08-78	14.5 hours	283°F	4440'
07-10-78	5 hours	292-294°F	4675'
07-10-78	2 hours	292-294°F	4700'
07-10-78	10.5 hours	291-292°F	4727'
07-10-78	18 hours	293°F	4735'
07-17-78	19.5 hours	244-249°F	5035'

GEOCHEMICAL DATA

WELL: Union Oil Company of California
 Cove Fort-Sulphurdale Unit #31-33
 Millard County, Utah

Sample Information

Source..... Flowline
 Collection Date and Time..... 6-30-78, 1200 Hrs.
 Depth of Well at Time of Collection.... 2455
 Temperature of Sample..... 138°F
 Date Analysis Begun..... Received by lab 7-11-78

Turbidity	<u>150.0</u> NTU	Lithium as Li	<u>12.05</u> mg/l
Conductivity	<u>11,700</u> umhos/cm	Total Hardness as CaCO ₃	<u>24.0</u> mg/l
pH	<u>8.77</u> Units	Iron as Fe (Total)	<u>3,200</u> mg/l
TDS at 180°C	<u>7,600</u> mg/l	Iron as Fe (Filtered)	<u>0.347</u> mg/l
Alkalinity as CaCO ₃	<u>836.0</u> mg/l	Lead as Pb	<u>0.345</u> mg/l
Arsenic as As	<u>0.970</u> mg/l	Magnesium as Mg	<u>2.40</u> mg/l
Bicarbonate as HCO ₃	<u>888.16</u> mg/l	Manganese as Mn	<u>0.249</u> mg/l
Barium as Ba	<u>0.07</u> mg/l	Mercury as Hg	<u><0.0002</u> mg/l
Boron as B	<u>0.15</u> mg/l	Nickel as Ni	<u>0.685</u> mg/l
Cadmium as Cd	<u>0.004</u> mg/l	Nitrate as NO ₃ -N	<u>0.04</u> mg/l
Calcium as Ca	<u>5.60</u> mg/l	Nitrite as NO ₂ -N	<u><0.01</u> mg/l
Carbonate as CO ₃	<u>64.8</u> mg/l	Potassium as K	<u>423.0</u> mg/l
Chloride as Cl	<u>3,440</u> mg/l	Selenium as Se	<u><0.001</u> mg/l
Chromium as Cr (Total)	<u><0.001</u> mg/l	Silica as SiO ₂	<u>77.50</u> mg/l
Chromium as Cr (Hex)	<u><0.001</u> mg/l	Silver as Ag	<u>0.026</u> mg/l
Copper as Cu	<u>0.065</u> mg/l	Sulfate as SO ₄	<u>272.0</u> mg/l
Surfactants MBAS	<u><0.05</u> mg/l	Sodium as Na	<u>2,530</u> mg/l
Fluoride as F	<u>3.10</u> mg/l	Zinc as Zn	<u>0.084</u> mg/l

GEOCHEMICAL DATA

WELL: Union Oil Company of California
 Cove Fort-Sulphurdale Unit #31-33
 Millard County, Utah

Sample Information

Source..... Flowline
 Collection Date and Time..... 7-1-78, 1100 Hrs.
 Depth of Well at Time of Collection.... 2825
 Temperature of Sample..... 79°F
 Date Analysis Begun..... Received by lab 7-11-78

Turbidity	<u>260.0</u> NTU	Lithium as Li	<u>12.46</u> mg/l
Conductivity	<u>11,780</u> umhos/cm	Total Hardness as CaCO ₃	<u>560.0</u> mg/l
pH	<u>7.38</u> Units	Iron as Fe (Total)	<u>8.786</u> mg/l
TDS at 180°C	<u>7,655</u> mg/l	Iron as Fe (Filtered)	<u>1.920</u> mg/l
Alkalinity as CaCO ₃	<u>394.0</u> mg/l	Lead as Pb	<u>0.350</u> mg/l
Arsenic as As	<u>0.379</u> mg/l	Magnesium as Mg	<u>14.40</u> mg/l
Bicarbonate as HCO ₃	<u>480.68</u> mg/l	Manganese as Mn	<u>2.084</u> mg/l
Barium as Ba	<u>0.29</u> mg/l	Mercury as Hg	<u><0.0002</u> mg/l
Boron as B	<u>0.30</u> mg/l	Nickel as Ni	<u>0.680</u> mg/l
Cadmium as Cd	<u>0.006</u> mg/l	Nitrate as NO ₃ -N	<u>0.03</u> mg/l
Calcium as Ca	<u>200.0</u> mg/l	Nitrite as NO ₂ -N	<u><0.01</u> mg/l
Carbonate as CO ₃	<u><0.01</u> mg/l	Potassium as K	<u>452.0</u> mg/l
Chloride as Cl	<u>3,550</u> mg/l	Selenium as Se	<u><0.001</u> mg/l
Chromium as Cr (Total)	<u><0.001</u> mg/l	Silica as SiO ₂	<u>25.50</u> mg/l
Chromium as Cr (Hex)	<u><0.001</u> mg/l	Silver as Ag	<u>0.032</u> mg/l
Copper as Cu	<u>0.049</u> mg/l	Sulfate as SO ₄	<u>720.0</u> mg/l
Surfactants MBAS	<u><0.05</u> mg/l	Sodium as Na	<u>2,475</u> mg/l
Fluoride as F	<u>3.20</u> mg/l	Zinc as Zn	<u>0.231</u> mg/l

GEOCHEMICAL DATA

WELL: Union Oil Company of California
Cove Fort-Sulphurdale Unit #31-33
Millard County, Utah

Sample Information

Source..... Flowline
Collection Date and Time..... 7-5-78, 1200 Hrs.
Depth of Well at Time of Collection.... 3720
Temperature of Sample..... 155°F
Date Analysis Begun..... Received by lab 7-11-78

Turbidity	<u>200.0</u> NTU	Lithium as Li	<u>11.62</u> mg/l
Conductivity	<u>12,300</u> umhos/cm	Total Hardness as CaCO ₃	<u>188.0</u> mg/l
pH	<u>7.94</u> Units	Iron as Fe (Total)	<u>11.100</u> mg/l
TDS at 180°C	<u>8,000</u> mg/l	Iron as Fe (Filtered)	<u>8.660</u> mg/l
Alkalinity as CaCO ₃	<u>210.0</u> mg/l	Lead as Pb	<u>0.345</u> mg/l
Arsenic as As	<u>1.131</u> mg/l	Magnesium as Mg	<u>7.68</u> mg/l
Bicarbonate as HCO ₃	<u>256.2</u> mg/l	Manganese as Mn	<u>0.328</u> mg/l
Barium as Ba	<u>0.16</u> mg/l	Mercury as Hg	<u><0.0002</u> mg/l
Boron as B	<u>0.25</u> mg/l	Nickel as Ni	<u>0.688</u> mg/l
Cadmium as Cd	<u>0.007</u> mg/l	Nitrate as NO ₃ -N	<u>0.02</u> mg/l
Calcium as Ca	<u>62.4</u> mg/l	Nitrite as NO ₂ -N	<u><0.01</u> mg/l
Carbonate as CO ₃	<u><0.01</u> mg/l	Potassium as K	<u>465.0</u> mg/l
Chloride as Cl	<u>3,410</u> mg/l	Selenium as Se	<u><0.001</u> mg/l
Chromium as Cr (Total)	<u>0.048</u> mg/l	Silica as SiO ₂	<u>64.0</u> mg/l
Chromium as Cr (Hex)	<u><0.001</u> mg/l	Silver as Ag	<u>0.030</u> mg/l
Copper as Cu	<u>0.077</u> mg/l	Sulfate as SO ₄	<u>1,000</u> mg/l
Surfactants MBAS	<u><0.05</u> mg/l	Sodium as Na	<u>2,916</u> mg/l
Fluoride as F	<u>2.90</u> mg/l	Zinc as Zn	<u>0.051</u> mg/l

GEOCHEMICAL DATA

WELL: Union Oil Company of California
Cove Fort-Sulphurdale Unit #31-33
Millard County, Utah

Sample Information

Source.....Flowline
Collection Date and Time.....7-7-78, 0600 Hrs.
Depth of Well at Time of Collection....4170
Temperature of Sample.....102°F
Date Analysis Begun.....Received by lab 7-11-78

Turbidity	<u>390.0</u> NTU	Lithium as Li	<u>13.31</u> mg/l
Conductivity	<u>15,380</u> umhos/cm	Total Hardness as CaCO ₃	<u>20.0</u> mg/l
pH	<u>9.79</u> Units	Iron as Fe (Total)	<u>10.600</u> mg/l
TDS at 180°C	<u>10,000</u> mg/l	Iron as Fe (Filtered)	<u>0.108</u> mg/l
Alkalinity as CaCO ₃	<u>1,440</u> mg/l	Lead as Pb	<u>0.420</u> mg/l
Arsenic as As	<u>5.707</u> mg/l	Magnesium as Mg	<u>3.36</u> mg/l
Bicarbonate as HCO ₃	<u>658.8</u> mg/l	Manganese as Mn	<u>0.016</u> mg/l
Barium as Ba	<u>0.47</u> mg/l	Mercury as Hg	<u>0.0007</u> mg/l
Boron as B	<u>0.50</u> mg/l	Nickel as Ni	<u>0.975</u> mg/l
Cadmium as Cd	<u>0.045</u> mg/l	Nitrate as NO ₃ -N	<u><0.01</u> mg/l
Calcium as Ca	<u>14.40</u> mg/l	Nitrite as NO ₂ -N	<u><0.01</u> mg/l
Carbonate as CO ₃	<u>540.0</u> mg/l	Potassium as K	<u>443.0</u> mg/l
Chloride as Cl	<u>3,900</u> mg/l	Selenium as Se	<u>0.007</u> mg/l
Chromium as Cr (Total)	<u>0.006</u> mg/l	Silica as SiO ₂	<u>79.0</u> mg/l
Chromium as Cr (Hex)	<u><0.001</u> mg/l	Silver as Ag	<u>0.037</u> mg/l
Copper as Cu	<u>0.166</u> mg/l	Sulfate as SO ₄	<u>760.0</u> mg/l
Surfactants MBAS	<u><0.05</u> mg/l	Sodium as Na	<u>4,000</u> mg/l
Fluoride as F	<u>3.60</u> mg/l	Zinc as Zn	<u>0.041</u> mg/l

GEOCHEMICAL DATA

WELL: Union Oil Company of California
 Cove Fort-Sulphurdale Unit #31-33
 Millard County, Utah

Sample Information

Source..... Extract through inverted float sub
 into drill pipe
 Collection Date and Time..... 7-20-78
 Depth of Well at Time of Collection.. 5221
 Temperature of Sample..... -
 Date Analysis Begun..... 7-26-78

Turbidity	<u>80.0</u> NIU	Lithium as Li	<u>1.164</u> mg/l
Conductivity	<u>2,035</u> umhos/cm	Total Hardness as CaCO ₃	<u>266.0</u> mg/l
pH	<u>7.44</u> Units	Iron as Fe (Total)	<u>2.154</u> mg/l
TDS at 180°C	<u>1,320</u> mg/l	Iron as Fe (Filtered)	<u>1.976</u> mg/l
Alkalinity as CaCO ₃	<u>200.0</u> mg/l	Lead as Pb	<u>0.006</u> mg/l
Arsenic as As	<u>2.991</u> mg/l	Magnesium as Mg	<u>19.20</u> mg/l
Bicarbonate as HCO ₃	<u>244.0</u> mg/l	Manganese as Mn	<u>0.043</u> mg/l
Barium as Ba	<u>0.15</u> mg/l	Mercury as Hg	<u><0.0002</u> mg/l
Boron as B	<u>0.20</u> mg/l	Nickel as Ni	<u><0.001</u> mg/l
Cadmium as Cd	<u>0.040</u> mg/l	Nitrate as NO ₃ -N	<u>0.45</u> mg/l
Calcium as Ca	<u>74.40</u> mg/l	Nitrite as NO ₂ -N	<u><0.01</u> mg/l
Carbonate as CO ₃	<u><0.01</u> mg/l	Potassium as K	<u>56.20</u> mg/l
Chloride as Cl	<u>502.0</u> mg/l	Selenium as Se	<u><0.001</u> mg/l
Chromium as Cr (Total)	<u><0.001</u> mg/l	Silica as SiO ₂	<u>64.5</u> mg/l
Chromium as Cr (Hex)	<u><0.001</u> mg/l	Silver as Ag	<u><0.001</u> mg/l
Copper as Cu	<u>0.914</u> mg/l	Sulfate as SO ₄	<u>187.0</u> mg/l
Surfactants MBAS	<u><0.05</u> mg/l	Sodium as Na	<u>355.0</u> mg/l
Fluoride as F	<u>1.03</u> mg/l	Zinc as Zn	<u>0.104</u> mg/l

Well History
Union Oil Company of California



COMPANY Union Oil Company of California		TYPE WELL (Geothermal)		Hot Water	
LEASE Cove Fort Sulphurdale Unit		SEC 33	T 25S	R 6W	M SLM
LOCATION N89°28'W 1092.23 and South 479.21' from			COUNTY Millard		
AREA Cove Fort - Sulphurdale			the South ¼ corner of Section 28, T25S, R6W, SLM		
ELEVATION 6480' GR	SPUD 5/24/78	COMP. 7/27/78	ABAND. --	TOTAL DEPTH 5221'	PLUG 2600'
HOLE DEVIATION <input type="checkbox"/> 660' maximum possible			B.H.L.		
CASING RECORD				WELL DATA	
SIZE	EMB.	DEPTH	ft³ cmt	W.S.O. - PERFS. - REMARKS	ELEC. LOG 1735' - 5207'
30"		52' K.B.	100		DIPMETER 1735' - 5207'
20"		280' K.B.	767		CORE RECORD
13-3/8"		1733' K.B.	2827		HISTORY
2-7/8"		2579' K.B.	--	Hanging Tubing	CORE ANALYSIS
					PALEO. LETTER

MARKERS - HORIZONS

DATE	DEPTH	PROGRESS HISTORY
5-24-78	[54']	Moved in and rigged up Loffland Bros. Co. rig No. 5. Placed rig on day rate at 1200 hours, 5-24-78. Mixed mud. Drilled rat hole and mouse hole. Spudded 26" hole with a 26" pilot hole opener at 2000 hours. Center punched hole from 52' to 54'. Laid down hole opener. Ran 17-1/2" bit.
5-25-78	[123']	Drilled 17-1/2" hole from 54' to 79'. Repaired mud pump. Drilled 17-1/2" hole from 79' to 86'. Continued pump repairs. Unable to keep hole clean with one pump. Drilled 17-1/2" hole to 123'. Placed rig on repair rate. Repaired both mud pumps.
5-26-78	[144']	Continued mud pump repairs. Ran 17-1/2" bit at 2000 hours, following pump repairs. Cleaned out fill in hole from 103' to 123'. Drilled 17-1/2" hole from 123' to 144'.
5-27-78	[282']	Drilled 17-1/2" hole from 144' to 282'.
5-28-78	[301']	Drilled 17-1/2" hole from 282' to 301'. Opened 17-1/2" hole to 26" hole from 52' to 77'. Repaired mud pump. Opened 17-1/2" hole to 26" hole from 77' to 167'. Repaired and re-dressed 26" hole opener with new cutters.

- 5-29-78
[301']
Opened 17-1/2" hole to 26" hole from 167' to 289'. Circulated hole until clean. Measured drill pipe and tools out of hole. Made 5' correction. Repaired no. 1 pump. Opened 17-1/2" hole to 26" hole from 289' to 295'. Laid down 26" hole opener.
- 5-30-78
[301']
Rigged up and ran 7 joints, 20", 94 lb. per foot, H-40, buttress casing, total 294'. Casing stopped at 281'. Hung 20" casing with Halliburton Duplex Float shoe at 281'. Ran 9 joints, 4-1/2" drill pipe with Halliburton Duplex mandrel, stabbed into Duplex Float shoe. Circulated through float shoe to surface and conditioned mud. Halliburton mixed and pumped 767 ft³ class "B" cement through drill pipe and shoe with 2% CaCl₂. Displaced cement slurry with 12 ft³ mud. Had good cement returns to surface during cementing operation. Pulled drill pipe out of float shoe. Cement in place at 1330 hours. Waited on cement. Placed rig on repair time from 1600 hours to 2200 hours. Cut off 30" casing at 2200 hours.
- 5-31-78
[301']
Cut off 30" casing, and 20" casing. Welded on 20" - 2000 psi rated flange. Installed 20" Double Shaffer blow-out preventor and 20" Hydril "GK" blow-out preventor.
- 6-01-78
[315']
Completed installation of blow-out preventor actuating lines. Installed choke manifold. Tested blind rams to 500 psi with water for thirty minutes. Tested Hydril "GK" with water to 500 psi for thirty minutes. Tested Kelley cock to 800 psi. All tests were witnessed and approved by John Reeves, U.S.G.S. representative. Ran 17-1/2" bit and drilling assembly. Drilled cement from 272' to casing shoe at 280' and cement to 282'. Cleaned out fill from 282' to 301'. Drilled 17-1/2" hole from 301' to 315'. Plugged bit. Pulled out of hole. Removed junk from drill collar float.
- 6-02-78
[507']
Repaired no. 1 pump. Ran 17-1/2" bit and drilling assembly with two added stabilizers. Drilled 17-1/2" hole from 315' to 507'.
- 6-03-78
[711']
Drilled 17-1/2" hole from 507' to 674'. Repositioned shock sub in drilling assembly for better stabilization. Drilled 17-1/2" hole from 674' to 711'. Shock sub failed, parted in spline. Pulled out of hole. Top of fish or drilling assembly at 662'. Left 17-1/2" bit, 17-1/2" stabilizer, bit sub, 8" drill collar, and broken shock sub in hole.

- 6-04-78
[844'] Ran 11-3/4" overshot with extension. Located and engaged fish. Recovered fish. Made up drilling assembly. Drilled 17-1/2" hole from 711' to 844'.
- 6-05-78
[1040'] Drilled 17-1/2" hole from 844' to 1040'.
- 6-06-78
[1241'] Drilled 17-1/2" hole from 1040' to 1236'. Lost circulation while drilling at 1236'. Drilled without returns from 1236' to 1241'. H₂S alarms sounded, indicating 10 PPM H₂S. Pulled out of hole.
- 6-07-78
[1241'] Ran open-end drill pipe to 1230'. Displaced lost circulation plug no. 1 through drill pipe as follows: 375 ft³, class "B" cement with perlite in a 1:1 ratio, with 40% silica flour, 3% gel and 0.5% CFR-2. Cement in place at 1605 hours. Pulled out of hole. Waited on cement 5 hours. Ran drill pipe to 1241', no fill located. Pulled drill pipe to 1230'. Displaced lost circulation plug no. 2 through drill pipe as follows: 350 ft³, class "B" cement with perlite in a 1:1 ratio, 40% silica flour, 3% gel and 0.5% CFR-2. Cement in place at 2050 hours. Pulled out of hole. Waited on cement. Gas flow stopped for twenty minutes and slowly returned at a low flow rate.
- 6-08-78
[1241'] Ran drill pipe to 1241', no fill located. Pulled drill pipe to 1230'. Displaced lost circulation plug no. 3 through drill pipe as follows: pumped 20 bbls thick gel mud mixed with lost circulation material ahead of 240 ft³ class "B" cement with perlite in a 1:1 ratio with 40% silica flour, 3% gel and 0.5% CFR-2. Cement in place at 1010 hours. Pulled drill pipe to 280'. No H₂S emission from hole, but small amount of methane gas emission. Waited on cement 5 hours. Ran drill pipe to 1230', no fill located. Displaced lost circulation plug no. 4 as follows: 125 ft³ class "B" cement with perlite in a 1:1 ratio with 40% silica flour, 3% gel, 0.5% CFR-2 with 15% lost circulation material. Cement in place at 1510 hours. Waited on cement 5 hours. Ran drill pipe to 1230', no fill located. Displaced lost circulation plug no. 5 through drill pipe at 1230' as follows: 225 ft³ class "B" cement with perlite in a 1:1 ratio, 40% silica flour, 3% gel, 0.5% CFR-2 and 15% lost circulation material. Cement in place at 2145 hours. Waited on cement.
- 6-09-78
[1241'] Waited on cement 3 hours. Ran drill pipe to 1230', no fill located. Mixed 100 bbls thick gel mud with

6-09-78

Continued-----

25% lost circulation material, and displaced lost circulation plug no. 6 behind mud and LCM as follows: 305 ft³ class "B" cement with perlite in a 2:1 ratio with 40% silica flour and 3% gel. Cement in place at 1400 hours. Pulled out of hole. Waited on cement 5 hours. Ran drill pipe to 1230', no fill located. Displaced lost circulation plug no. 7 through drill pipe at 1230' as follows: 305 ft³ class "B" cement with perlite in a 2:1 ratio with 40% silica flour and 3% gel. Cement in place at 1915 hours. Pulled out of hole with drill pipe. Waited on cement.

6-10-78
[1252']

Ran drill pipe to 1230', no fill located. Pulled out of hole. Ran 17-1/2" drilling assembly to 1236', circulated with returns and cleaned out rocks and formation fill from 1236' to 1241'. Lost returns and drilled 17-1/2" hole from 1241' to 1252'. Lost 500 bbls drilling mud while drilling from 1241' to 1252' at a 20 to 30 ft per hour rate. No evidence of torque, indicating fractures or running dolomite in the 11' of newly drilled hole. Pulled drilling assembly. Ran drill pipe to 1230'. Displaced lost circulation plug no. 8 as follows: 230 ft³ class "B" cement with perlite in a 1:1 ratio with 40% silica flour, 3% gel and 15% lost circulation material. Cement in place at 0830 hours. Waited on cement 5 hours. No fill located. Displaced lost circulation plug no. 9 through drill pipe at 1230' as follows: 230 ft³ class "B" cement with perlite in a 1:1 ratio with 40% silica flour, 3% gel and 20 to 30% lost circulation material. Cement in place at 1345 hours. Waited on cement 4 hours. No fill from plug. Displaced lost circulation plug no. 10 through drill pipe at 1230' as follows: 210 ft³ class "B" cement with perlite in a 1:1 ratio with 40% silica flour, 3% gel, 20% lost circulation material and 20% CaCl₂. Cement in place at 1915 hours. Waited on cement 4 hours. No fill from plug. Displaced plug no. 11 through drill pipe at 1230' as follows: 210 ft³ class "B" cement with perlite in a 1:1 ratio, with 40% silica flour, 3% gel, 2% CaCl₂ and 20% lost circulation material. Cement in place at 2400 hours.

6-11-78
[1257']

Waited on cement 4 hours. Ran drill pipe to 1230'. No fill located. Displaced lost circulation plug no. 12 through drill pipe as follows: 210 ft³ class "B" cement

6-11-78 Continued-----

with perlite in a 1:1 ratio with 40% silica flour, 3% gel, 2% CaCl₂ and 20% lost circulation material. Cement in place at 0530 hours. Pulled out of hole. Ran home-made lumber (2" x 4") float on wire line to locate fluid level in hole, indicated at 600'+. Waited on cement 5 hours. Ran drill pipe to 1241', no fill located. Displaced lost circulation plug no. 13 through drill pipe as follows: 166 ft³ HOWCO, Thix-Set cement, with 25 lbs Gelsonite per sack of cement and 5 lbs Flo-Cele per sack of cement, .5 lbs nut plug per sack of cement and 2% CaCl₂. Cement in place at 1130 hours. Pulled out of hole. Waited on cement 4 hours. Ran drill pipe and located top of cement at 1160'. Filled hole with 175 bbls mud. Ran 17-1/2" drilling assembly. Drilled cement from 1160' to 1236'. Lost circulation. Drilled with no mud returns to surface from 1236' to 1257'.

6-12-78
[1257']

Pulled out of hole. Ran drill pipe to 1230'. Displaced lost circulation plug no. 14 through drill pipe as follows: 166 ft³ class "B" cement with 2% CaCl₂, 25 lbs Gilsonite per sack of cement, .5 lbs Flo-Cele per sack of cement and .5 lbs nut plug per sack of cement. Cement in place at 0115 hours. Pulled out of hole. Waited on cement 4 hours. Ran drill pipe and located top of cement at 1236'. Pulled drill pipe to 1230'. Displaced lost circulation plug no. 15 through drill pipe as follows: 210 ft³ class "B" cement with perlite in a 1:1 ratio with 40% silica flour, 3% gel and 0.5% CFR-2. Cement in place at 0715 hours. Waited on cement 5 hours. Ran drill pipe to 1236'. No fill up was gained from plug no. 15. Ran drill pipe to 1230'. Displaced lost circulation plug no. 16 through drill pipe as follows: 86 ft³ class "B" cement with perlite in a 1:1 ratio, 40% silica flour, 3% gel and 3% CaCl₂. Cement in place at 1400 hours. Waited on cement. No fill up from plug no. 16. Displaced lost circulation plug no. 17 through drill pipe at 1230' as follows: 200 ft³ class "B" cement with perlite in a 1:1 ratio, 40% silica flour, 3% gel and 3% CaCl₂. Cement in place at 2000 hours. Waited on cement. Pulled out of hole.

6-13-78
[1257']

Ran drill pipe to top of cement at 1221'. Filled hole with mud. Ran 17-1/2" drilling assembly. Drilled firm

6-13-78 Continued-----

cement from 1221' to 1247'. Lost mud returns at 1247'. Pulled out of hole. Ran drill pipe to 1230'. Displaced lost circulation Pal Mix plug no. 1 through drill pipe as follows: 90 ft³ Pal Mix 110-R, displaced with 100 ft³ H₂O. Waited 1 hour. No success in filling hole. Displaced additional Pal Mix plug no. 2 as follows: 90 ft³ Pal Mix 110-R, through drill pipe at 1230', displaced with 100 ft³ H₂O. Waited 1 hour. No success in filling hole. Displaced no. 3 Pal Mix plug as follows: 90 ft³ Pal Mix 110-R, displaced with 100 ft³ H₂O. Waited 1 hour. No success in attempting to fill hole. Displaced lost circulation plug no. 18 through drill pipe at 1230' as follows: 125 cubic feet Gel-Gilsonite 1:1 ratio high viscosity mixture, followed by 235 ft³ class "B" cement, sand and perlite, mixed in equal amounts. Displaced with 67 ft³ H₂O. Cement in place at 2000 hours. Waited on cement. Pulled drill pipe.

6-14-78
[1276']

Ran drill pipe and located top of cement at 1183'. Filled hole with water. Mixed mud. Pulled drill pipe. Ran 17-1/2" drilling assembly. Drilled firm cement from 1183' to 1257'. Drilled 17-1/2" hole from 1257' to 1276'. Lost returns to surface at 1274'. Pulled out of hole. Ran drill pipe to 1260'. Displaced lost circulation plug no. 19 through drill pipe as follows: 112 ft³ H₂O with 700 lbs Pal Mix 110-R (Pal Mix plug no. 4). Waited 1 hour. Pumped 115 ft³ class "B" cement with sand and perlite in equal amounts. Displaced with 67 ft³ H₂O. Cement in place at 1700 hours. Pulled out of hole. Waited on cement 4 hours. Ran drill pipe. Located top of cement at 1230'. Filled hole with mud and mixed mud. Pulled out of hole.

6-15-78
[1400']

Ran 17-1/2" drilling assembly. Drilled firm cement from 1230' to 1261'. Drilled 17-1/2" hole from 1276' to 1400', with no fluid loss.

6-16-78
[1529']

Drilled 17-1/2" hole from 1400' to 1529'. Lost 60 bbls drilling mud at 1513'.

6-17-78
[1564']

Drilled 17-1/2" hole from 1529' to 1564'. Lost 250 bbls mud while drilling from 1530' to 1564'. Lost circulation completely at 1564'. Stuck drill pipe and tools. Worked pipe and tools until free. Required 4 hours. P.O.H. Ran drill pipe to 1535'. Displaced lost circulation plug #20 thru drill pipe as follows: 95 ft³ Pal Mix 110-R

6-17-78 Continued-----

(Pal Mix plug no. 5) displaced with 120 ft³ H₂O. Waited 30 minutes. Displaced 115 ft³ class "B" cement with perlite and sand in equal amounts. Displaced with 92 ft³ H₂O. Cement in place at 1945 hours. Pulled out of hole. Waited on cement.

6-18-78
[1623']

Ran drill pipe. Located top of cement at 1487'. Pulled out of hole. Ran 17-1/2" drilling assembly. Drilled cement with full returns from 1487' to 1500', lost returns. Regained returns after pumping 500 bbls H₂O into hole. Ran tools to 1564' with no restrictions. Drilled 17-1/2" hole from 1564' to 1623'. Lost 100 bbls mud while drilling from 1564' to 1623'.

6-19-78
[1730']

Drilled 17-1/2" hole from 1623' to 1730'. Lost 60 bbls mud from 1646' to 1656', 200 bbls mud from 1683' to 1691' and 50 bbls mud from 1696' to 1720'.

6-20-78
[1735']

Drilled 17-1/2" hole from 1730' to 1735'. Circulated and conditioned hole for casing. Lost complete returns. Pulled out of hole. Mixed mud. Ran drill pipe and found 2' fill at 1733'. Unable to fill hole with mud. Hung drill pipe at 1649'. Displaced lost circulation plug no. 21 through drill pipe as follows: 100 ft³ Pal Mix 110-R (Pal Mix plug no. 6), displaced with 140 ft³ H₂O, followed by 104 ft³ class "B" cement with 2% CaCl₂, 25 lbs gilsonite per sack of cement, .5 lbs Flo-Cele per sack of cement and .5 lbs nut plug per sack of cement. Displaced with 112 ft³ H₂O. Cement in place at 1415 hours. Pulled drill pipe to 1229'. Waited one hour. Displaced lost circulation no. 22, 104 ft³ class "B" cement with 2% CaCl₂, 25 lbs gilsonite, .5 lbs Flo-Cele per sack of cement and .5 lbs nut plug per sack of cement. Cement in place at 1630 hours. Waited on cement to 2000 hours. Ran drill pipe to 1732'. No fill located. Displaced lost circulation plug no. 23 through drill pipe as follows: 112 ft³ Pal Mix 110-R (Pal Mix plug no. 7), displaced with 134 ft³ H₂O.

6-21-78
[1735']

Waited 1 hour. Displaced remainder of lost circulation plug no. 23 through drill pipe at 1610' as follows: 104 ft³ class "B" cement with perlite in a 1:1 ratio with 40% silica flour, 3% gel and 0.5% CFR-2. Displaced slurry with 112 ft³ H₂O. Cement in place at 0100 hours. Waited on cement. Pulled out of hole.

6-21-78

Continued-----

Ran drill pipe to top of cement at 1638'. Filled hole with 230 bbls mud. Fluid level dropped out of sight after 10 minutes. Displaced lost circulation plug no. 24 through drill pipe at 1550' as follows: 104 ft³ Pal Mix 110-R displaced with 128 ft³ H₂O (Pal Mix plug no. 8), followed after 1 hour by 101 ft³ class "B" cement, with perlite in a 1:1 ratio with 40% silica flour, 3% gel and 0.5% CFR-2. Displaced slurry with 112 ft³ H₂O. Cement in place at 1030 hours. Waited on cement 4 hours. Ran drill pipe to 1638'. No fill located. Displaced lost circulation plug no. 25 through drill pipe at 1580' as follows: 145 ft³ class "B" cement, with perlite in a 1:1 ratio, with 40% silica flour, 3% gel and 2% CaCl₂. Displaced with 112 ft³ H₂O. Had mud returns to surface while pumping last 20 ft³ of displacement H₂O.

6-22-78

[1735']

Pulled drill pipe. Ran 17-1/2" drilling assembly. Cleaned out (suspected cement stringers) from 1197' to 1515'. Drilled firm cement from 1515' to 1580'. Passed through void from 1580' to 1638'. Cleaned out soft cement from 1638' to 1675'. Passed through void from 1675' to 1735'. No fluid loss experienced. Circulated and conditioned mud and hole. Pulled drilling assembly. Ran 45 joints 13-3/8" 54.5 lb/ft, K-55, buttress casing, total length less threads, 1734'. Landed casing with Halliburton 13-3/8" float shoe at 1733', B&W insert float at 1697' and Halliburton "DV" collar at 1115'. Mixed and pumped 100 ft³ H₂O, followed by 100 ft³ H₂O mixed with 70 lbs FR-20 flushing agent and silica flour, followed by 53 ft³ H₂O mixed with 30 ft³ sodium silicate, followed by 200 ft³ H₂O through casing shoe at 1733'. Followed pre-flush with cement slurry as follows: 795 ft³ class "B" cement with perlite in a 1:1 ratio, 3% gel, 40% silica flour and 0.5% CFR-2, followed by 326 ft³ class "B" cement with 40% silica flour and 0.5% CFR-2. Displaced slurries with 1520 ft³ mud. Did not bump top cement plug on insert float. Cement in place, first stage cement job at 2230 hours. Dropped "DV" cementer opening bomb. Opened "DV" at 1115' at 2240 hours. Circulated mud through "DV", received 392 ft³ cement slurry to surface from above "DV".

- 6-23-78
[1735'] Circulated mud through "DV" with no fluid loss for four hours. Performed second stage cement job as follows: mixed and pumped through "DV" cementer at 1115', 168 ft³ H₂O, followed by 1611 ft³ class "B" cement, with Perlite in a 1:1 ratio, with 40% Silica Flour, 3% Gel and 0.5% CFR-2, followed with "DV" closing and wiper plug, and then 174 bbls mud. Closed "DV" cementer with 1000 psi. Released pressure. No indication of bleed back from "DV". C.I.P. at 0445 hours. Had complete and full returns to surface during stage #1 and partial returns to surface during stage #2. 50 ft³ cement slurry estimated to surface during second stage. W.O.C. 4 hours. Removed B.O.P.'s. Cut off 20" casing and 13-3/8" casing. Located top of second stage cement at 180' in annulus between 13-3/8" and 20" casing. Filled annulus to surface with 95 ft³ class "B" cement with Perlite in a 1:1 ratio, 40% Silica Flour, 3% Gel and 0.5% CFR-2, all pumped through 1" pipe. Installed 12" - 900 series S.O.W. casing head.
- 6-24-78
[1735'] Installed 12" - 900 series Double Shaffer and Hydril "GK" B.O.P.'s and banjo box. Installed choke manifold and kill and choke lines. Tested B.O.P.'s, pipe rams, blind rams and Hydril to 1500 psi for 30 minutes. Tested banjo box to 500 psi for thirty minutes. Tested Kelly cock to 2000 psi for 15 minutes. All tests witnessed and approved by John Reeves of the U.S.G.S..
- 6-25-78
[1770'] Ran 12-1/4" drilling assembly. Drilled through Halliburton "DV" cementer at 1115' and insert float at 1697'. Drilled cement from 1697' to 1733'. Drilled Halliburton 13-3/8" float shoe at 1733' and cement from 1733' to 1735'. P.O.H. Ran bit #7 on 12-1/4" drilling assembly. Drilled 12-1/4" hole from 1735' to 1770'.
- 6-26-78
[1902'] Drilled 12-1/4" hole from 1770' to 1800'. P.O.H. Stabilized drilling assembly. Drilled 12-1/4" hole from 1800' to 1902'. 60 bbl increase in mud volume at 1830'.
- 6-27-78
[2019'] Drilled 12-1/4" hole from 1902' to 2015'. Lost all fluid returns.. Drilled 12-1/4" hole without returns to surface from 2015' to 2019'. Pumped 400 bbls mud into hole. Unable to fill hole. Pulled drilling assembly out of hole. Rigged up to air drill.
- 6-28-78
[2019'] Installed Grant rotating drilling stripper. Ran 12-1/4" drilling assembly to 2000'. Ran temperature survey (#1) after hole static for 12 hours, indicating 210°F. Pulled and magnafluxed drilling assembly. Continued to install air drilling equipment.

- 6-29-78
[2322'] Ran 12-1/4" drilling assembly to 2019', no obstructions. Circulated with 195 psi air pressure through drill pipe. No fluid indicated to be in hole. Injected 200 gpm H₂O co-mingled with 1200 cfm air. Partial air returns to surface without fluid or cuttings experienced while drilling 12-1/4" hole from 2019' to 2151'. Had intermittent returns of water and drill cuttings to surface from 2151' to 2322'.
- 6-30-78
[2672'] Drilled 12-1/4" hole from 2322' to 2672'. Had intermittent fluid returns to surface with drill cuttings while drilling from 2322' to 2350'. No returns to surface while drilling below 2550'. No fill on bottom.
- 7-01-78
[2920'] Drilled 12-1/4" hole from 2672' to 2920' with aerated water. Had intermittent returns by heads every three to four hours. Shock sub parted. P.O.H. Shock sub mandrel parted, leaving 12-1/4" bit, stabilizer, bit sub, drill collar stabilizer and shock sub mandrel in hole. Top of fish at 2876'. Made up 11-3/4" Bowen overshot fishing tool and ran in hole.
- 7-02-78
[2920'] Worked overshot over top of fish and engaged mandrel. Circulated with intermittent returns through the fish with aerated water. Unable to pull fish. Released from fish and pulled out of hole with fishing tool. Installed jars and bumper sub above overshot. Re-engaged fish and jarred tools free. Recovered entire fish. (Jars and bumper sub not on location for first run.)
- 7-03-78
[3161'] Laid down all tools. Ran in hole with 12-1/4" drilling assembly. Reamed 12-1/4" hole from 2876' to 2920'. Drilled 12-1/4" hole from 2920' to 2940'. P.O.H. and installed corrosion ring in drill collars. Drilled 12-1/4" hole from 2940' to 3161'. Received some intermittent heads of cold water, 50°F, while drilling from 2920' to 3161'.
- 7-04-78
[3550'] Drilled 12-1/4" hole from 3161' to 3348'. Surveyed at 3250', 234°F temperature after 80 minutes. Drilled 12-1/4" hole from 3348' to 3550'. Had intermittent returns to surface at temperatures ranging from 50°F to 171°F.
- 7-05-78
[3765'] Drilled 12-1/4" hole from 3550' to 3728'. Changed bit. Mixed sodium nitrate for corrosion control. Drilled 12-1/4" hole from 3728' to 3765'. Corrosion rates indicated to be severe as indicated by rings contained within the drill collars. Indicated rates = 42.8 #/ft/yr, while drilling from 3550' to 3728'.

- 7-06-78
[4070'] Drilled 12-1/4" hole from 3765' to 3865'. Pulled drill pipe and assembly. Added a jet sub, changed jet sub placements to 379' and 946' above the bit. R.I.H. Drilled 12-1/4" hole from 3865' to 4070'. Received air/fluid returns during first 80 minutes following the addition and placement change of jet subs, but no additional returns. Continuous returns were experienced prior to adding jet sub, while drilling from 3950' to 4070'. Water volume injected with air stream approximates slightly more than that returning to surface.
- 7-07-78
[4500'] Drilled 12-1/4" hole from 4070' to 4500'. Water rate to sump approximates 40 bbls/hr.
- 7-08-78
[4578'] Drilled 12-1/4" hole from 4500' to 4540'. Attempted to run directional and temperature survey without success. Pulled drill string. Replaced 12-1/4" bit and two stabilizers. Changed position of jet subs, now placed at 750' and 1140' above the bit. R.I.H. to 4460'. Ran survey at 4460'. Indicated 14° angle and 282°F temperature after 15 hours without injection of aerated water. Washed and reamed with 12-1/4" drilling assembly from 4465' to 4540'. Stuck drill string at 4530'. Worked tools free after two hours. Drilled 12-1/4" hole from 4540' to 4578'.
- 7-09-78
[4794'] Drilled 12-1/4" hole from 4578' to 4636'. Pulled drill string to reposition jet subs to improve fluid returns. Placed jet subs at 385' and 950' above the bit. Ran drilling assembly to 4494'. Cleaned out fill while pumping aerated water from 4494' to 4636'. Drilled 12-1/4" hole from 4636' to 4794'. Had very fast drilling from 4782' to 4794'. Hole cleaning impossible with recurring fill from 4782' to 4794'. One air compressor failed.
- 7-10-78
[4826'] Removed drill pipe string float. Ran #2 temp. survey at 4700', indicated to be 292°F after 2 hours without injection. Ran #3 temp. survey at 4675' after 5 hours static, indicating 292°F. Ran #4 temp. survey at 4675', 10-1/2 hours static, indicated 292°F. Ran temp. survey #5 after 18 hours static at 4735', indicated 292°F. Repaired air compressor. P.O.H. Levelled derrick. Removed jet subs from drilling assembly.
- 7-11-78
[4882'] Ran 12-1/4" drilling assembly. Washed out fill from 4800' to 4826'. Drilled 12-1/4" hole from 4826' to 4882', while pumping only water through bit. No fluid returns to surface. A possible formation change was indicated at 4853' and one foot voids at 4852' and 4858'. P.O.H. Placed jet subs in drilling assembly, 385' and 950' above bit. R.I.H. Cleaned out fill from 4785' to 4847' with aerated water. Unable to keep hole clean.

7-11-78 Continued -

from 4832' to 4847'. No fluid returns to surface. Pulled assembly up 315' and attempted to circulate with air only. Fluid flowed back through drill pipe, 100% water, for 25 minutes, indicating a fluid level. P.O.H. Removed jet subs.

7-12-78
[5009']

Ran 12-1/4" drilling assembly to top of fill at 4785'. Cleaned out fill from 4785' to 4882' while pumping only water through bit, with no returns to surface. Drilled 12-1/4" hole from 4882' to 4958'. Pulled bit to 4785'. Replenished water supply. R.I.H. to 4890'. Cleaned out fill, pumping water, from 4890' to 4950'. Stuck pipe and tools. Worked pipe and tools free after 90 minutes. Cleaned out to 4958'. Drilled 12-1/4" hole from 4958' to 5009' while pumping only water through bit, with no returns to surface. Pulled drill string to 4270'. Waited on water trucks to replenish supply.

7-13-78
[5009']

R.I.H. to 4910', with drilling assembly. Pumped water down drill pipe and washed to 4950'. Mixed and pumped a modified formation consolidation treatment through the 12-1/4" bit at 4930' as follows: 76 bbls sodium silicate - calcium chloride solution. Pulled bit to 4785'. Pumped an additional, 76 bbls, modified formation consolidation treatment through the 12-1/4" bit, consisting of sodium silicate and calcium chloride solution. P.O.H. Ran drill pipe to 4926' and displaced lost circulation plug #26 through the drill pipe as follows: 112 ft³, class "B" cement with Perlite mixed in a 1:1 ratio, with 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 381 ft³ H₂O. Pulled drill pipe to 4170'.

7-14-78
[5009']

Waited two hours. Located top of cement plug at 4840', with drill pipe. Displaced lost circulation plug #27 through drill pipe hung at 4833', as follows: 125 ft³ class "B" cement with Perlite in a 1:1 ratio with 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 369 ft³ H₂O. C.I.P. at 0300 hours. Pulled drill pipe to 4475'. Waited five hours. Ran drill pipe to obstruction at 4753'. P.O.H. R.I.H. with 12-1/4" drilling assembly. Drilled firm cement at 2100 hours, with aerated water from 4770' to 4790'. Encountered a void with no cement from 4790' to 4805', firm cement from 4805' to 4830' and cement stringers from 4830' to 4900'. Firm cement was drilled from 4900' to 4926' and a void to fill from 4926' to 4935'. Cleaned out

- 7-14-78 Continued -
fill from 4935' to 5009'. No fluid returns to surface while drilling and/or cleaning out.
- 7-15-78
[5018'] Drilled 12-1/4" hole while injecting water with both mud pumps, from 5009' to 5015', with no fluid returns to the surface. Had fill on bottom 4979' to 5009'. P.O.H. with drilling assembly. R.I.H. with Christensen 8-3/4" x 6-3/4" diamond core barrel to 4985'. Washed through fill from 4985' to 5015'. Cored from 5015' to 5018'. Core barrel jammed. Pulled core barrel.
- 7-16-78
[5068'] Recovered 8" of highly fractured dolomite from core barrel, Core #1. Re-ran core barrel. Washed through fill from 5003' to 5018'. Cut Core #2 from 5018' to 5021'. P.O.H. No recovery. Ran 12-1/4" drilling assembly. Reamed core run from 4985' to 5021'. Drilled 12-1/4" hole from 5021' to 5068' while pumping water through drill pipe with no returns to surface.
- 7-17-78
[5121'] Drilled 12-1/4" hole from 5068' to 5121' while pumping water through drill pipe with no returns to surface until water supply temporarily exhausted. Pulled bit to 1720'. Four trucks continued to haul water. Ran bit to obstruction at 5040'. Ran #6 temperature and deviation survey at 5035', indicating a 13°15' angle and a 249°F temperature after 19-1/2 hours with no fluid injection.
- 7-18-78
[5221' TD] Pumped water down drill pipe. Washed with 12-1/4" drilling assembly through fill from 5040' to 5121'. Drilled 12-1/4" hole from 5121' to 5221' with no returns. P.O.H. Ran Schlumberger Temperature Log from surface to 4858', tool stopped. Maximum temperature indicated was 342°F suspected to be malfunctioning as maximum reading thermometers only indicated 279°F and 281°F. Ran Schlumberger Dipmeter and four arm Caliper from 5207' to 1735'. Maximum recording thermometers indicated 276°F, 279°F and 282°F. Formations were indicated from logs as follows: Pennsylvanian Dolomite; surface to 2770'; Triassic Redbeds, 2770' to 4782'; Permian Dolomite, 4782' to 5221'.
- 7-19-78
[5221' TD] Ran Schlumberger DIL-8 Log from 5207' to 1735', with maximum reading thermometers indicating 282°F, 281°F and 276°F. Ran Schlumberger CNL-FDC Log from 5206' to 1735' and a repeat log section from 2000' to 1735'. Three Maximum reading thermometers indicated 278°F. Re-ran Schlumberger Temperature Log with replacement read-out panel, that indicated a malfunction of the #1 or first

7-19-78 * Continued -

temperature log run and corresponded to the maximum reading thermometers. Rigged down Schlumberger equipment. Rigged up Geotex equipment. Ran temperature log, corresponded to other temperature logs, plus spinner, water aquifer and radioactive tracer surveys. Rigged down Geotex. Logs indicated crossflow of fluid up and down, leaving the wellbore. Ran drill pipe to 5009'. Displaced a cement abandonment plug #28 through drill pipe as follows: 312 ft³ class "B" cement with Perlite in a 1:1 ratio with 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 364 cu. ft. H₂O. C.I.P. at 2000 hours. No fill from plug #28.

7-20-78
[5221' TD]

Pulled drill pipe to 5009'. Displaced cement abandonment plug #29 through drill pipe as follows: 139 ft³ class "B" cement with Perlite in a 1:1 ratio, with 40% Silica Flour, 3% Gel, 0.5% CFR-2 and 50# cedar pulp. Displaced slurry with 364 ft³ H₂O. C.I.P. at 0100 hours. W.O.C. No fill from plug #29. Displaced cement abandonment plug #30 through drill pipe at 5009' as follows: 162 ft³ class "B" cement with Perlite in a 1:1 ratio, 40% Silica Flour, 3% Gel, 0.5% CFR-2 and 50# cedar pulp. Displaced slurry with 350 ft³ H₂O. C.I.P. at 0700 hours. Pulled drill pipe to 4350'. W.O.C. Pumped modified formation consolidation treatment through drill pipe at 5009' consisting of sodium silicate and calcium chloride, followed by cement abandonment plug #31 as follows: 162 ft³ class "B" cement with Perlite, 40% Silica Flour, 3% Gel, and 0.5% CFR-2. Displaced slurry with 300 ft³ H₂O. C.I.P. at 1445 hours. Plugged bottom joint of drill pipe to make sample catcher with jet sub 90' above bottom. Ran drill pipe to 3000'. P.O.H. Recovered 90' of produced fluid. Removed jet sub and plug. Ran drill pipe to 5009'. No cement plug fill up. Displaced 200 bbls lost circulation material ahead of plug #32 and displaced cement slurry through drill pipe at 5009' as follows: 187 ft³ class "B" cement with Perlite in a 1:1 ratio with 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 300 ft³ H₂O. C.I.P. at 2400 hours.

7-21-78
[5221' TD]

Pulled drill pipe to 1700'. W.O.C. Ran drill pipe to 5009'. No fill from plug #32. Displaced 100 bbls gel and lost circulation material through drill pipe, followed by cement abandonment plug #33, as follows:

7-21-78 Continued -

162 ft³ class "B" cement with Perlite in a 1:1 ratio, 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 310 ft³ H₂O. C.I.P. at 0945 hours. P.O.H. Ran 12-1/4" drilling assembly to 5011'. No cement fill up from plug #32. P.O.H. Ran Halliburton 13-3/8" EZSV plug to 1608' on drill pipe. Plug stuck. Released from plug. P.O.H.

7-22-78
[5221' TD]

Ran 12-1/4" drilling assembly. Drilled and pushed plug down the hole from 1608' to 4947'. P.O.H. Ran drill pipe to 4935'. Displaced cement lost circulation plug #34, through drill pipe as follows: 84 ft³ class "B" cement with 15# Gilsonite per sack of cement and .25# Flo-Cele per sack of cement. Displaced slurry with 397 ft³ H₂O. C.I.P. at 1445 hours. P.O.H. Waited four hours. Ran drill pipe to 4937', located top of cement plug #34. Displaced cement abandonment plug #35 through drill pipe at 4935' as follows: 82 ft³ class "B" cement with 15# Gilsonite per sack cement and .25# Flo-Cele per sack of cement. Displaced slurry with 385 ft³ H₂O. C.I.P. at 1930 hours. P.O.H. R.I.H. with Halliburton 13-3/8" EZSV plug #2 on drill pipe.

7-23-78
[5221' TD]

Set 13-3/8" EZSV at 4750'. Displaced cement abandonment plug #36 through drill pipe at 4735' as follows: 86 ft³ class "B" cement with 15# Gilsonite per sack and .25# Flo-Cele per sack. Displaced slurry with 352 ft³ H₂O. C.I.P. at 0145 hours. P.O.H. W.O.C. Ran drill pipe to bridge plug, no cement fill. Displaced cement abandonment plug #37 through drill pipe at 4742' as follows: 150 ft³ class "B" cement, with Perlite in a 1:1 ratio, 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 355 ft³ H₂O. C.I.P. at 0900 hours. P.O.H. Waited four hours. Ran drill pipe to top of plug at 4750', no cement fill, plug #37. Repaired Halliburton equipment.

7-24-78
[5221' TD]

Displaced cement abandonment plug #38 through drill pipe at 4745' as follows: 221 ft³ class "B" cement with Perlite in a 2:1 ratio, 40% Silica Flour, and 3% Gel. Displaced slurry with 347 ft³ H₂O. C.I.P. at 0100 hours. P.O.H. No cement fill from plug #38. Displaced cement abandonment plug #39 through drill pipe at 4745' as follows: 71 ft³ class "B" cement with 15# Gilsonite per sack of cement and .25# Flo-Cele per sack of cement. Displaced slurry with 340 ft³ H₂O. C.I.P. at 0845 hours. Waited four hours. Ran drill pipe to 4728' top of cement. P.O.H. Ran Halliburton 13-3/8" EZSV plug #3

7-24-78 Continued -

and set at 2750'. Pumped cement plug #40, for abandonment of lower zone, through drill pipe as follows: 157 ft³ class "B" cement with Perlite in a 2:1 ratio, 40% Silica Flour and 3% Gel, followed by 218 ft³ class "B" cement with Perlite in a 1:1 ratio, 40% Silica Flour, 3% Gel and 0.5% CFR-2 pumped through and below EZSV plug. Displaced slurry with 230 ft³ H₂O. Pulled setting tool out of 13-3/8" EZSV to 2740'. Displaced cement abandonment plug #41 through drill pipe as follows: 62 ft³ class "B" cement with 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 202 ft³ H₂O. C.I.P. at 1800 hours. Laid down 62 joints of drill pipe.

7-25-78
[5221' TD]

Ran drill pipe to 2750', top of EZSV, no cement fill. Displaced cement lower zone abandonment plug #42 through drill pipe at 2740' as follows: 75 ft³ class "B" cement with 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 200 ft³ H₂O. C.I.P. at 0100 hours. P.O.H. Ran drill pipe and located obstruction at 2574'. P.O.H. Ran 12-1/4" bit and drilling assembly. Drilled cement from 2574' to 2745'. P.O.H. Pushed Halliburton 13-3/8" rubber casing wiper plug to 1775' with drill pipe. P.O.H. Ran 12-1/4" drilling assembly and pushed wiper plug to 2745'. P.O.H. Ran drill pipe to 2745'. Displaced cement plug #43 through drill pipe at 2745' as follows: 164 ft³ class "B" cement with Perlite in a 1:1 ratio, 40% Silica Flour, 3% Gel and 0.5% CFR-2. Displaced slurry with 112 ft³ H₂O. C.I.P. at 2130 hours. P.O.H.

7-26-78
[2600'
Plug back
depth]

Ran drill pipe and located top of cement at 2552'. P.O.H. Ran 12-1/4" drilling assembly to firm cement at 2552'. Drilled firm cement to 2600'. Laid down 88 joints drill pipe and drill collars. Disassembled B.O.P.'s and allied equipment.

7-27-78
[2600' PBD]

Continued to disassemble B.O.P.'s. Installed 12" 900 series x 6" 900 series tubing landing head. Ran 85 joints 2-7/8" EUE 8RD thread tubing. Bottom joint of tubing orange peeled to a point with a .75" hole. Slotted tubing for fluid entry at 3' intervals. Slot size approximates 4" in length by .75" in width. Landed tubing on donut-pack off hanger in 6"-900 series tubing head 21' below RKB at 2579.53'. Released Loffland Bros. Company rig #5 at 1800 hours, 7/27/78.

CFSU 31-33

RKB to Cellar Floor = 24.00'
 RKB to Ground Level = 20.00'
 RKB to 12" Casing Head = 22.50'

CASING DETAIL

<u>NO.</u> <u>JTS.</u>	<u>DESCRIPTION</u>	<u>LENGTH</u> <u>FEET</u>	<u>BOTTOM</u> <u>FEET</u>	<u>TOP</u> <u>FEET</u>
<u>30" CASING</u>				
1	30", 3/8" Wall H-40 Casing	27.50	52.00	Cellar Floor
1				
<u>20" CASING</u>				
7	20" HOWCO Duplex Float Shoe	2.10	280.00	277.90
7	20", 94#/ft H-40 Buttress Casing	289.90	277.90	-0-
7	Total:	292.00		
	Landed Above Zero or KB	12.00		
		280.00		
<u>13-3/8" CASING</u>				
16	13-3/8" HOWCO Float Shoe	2.05	1733.00	1730.95
16	13-3/8", 54.50#/ft K-55 Buttress Casing	614.85	1730.95	1116.10
29	13-3/8" HOWCO "DV" Cementer	3.35	1116.10	1112.75
29	13-3/8", 54.50#/ft K-55 Buttress Casing	1112.95	1112.75	-0-
45	Total:	1733.20		
	Landed Above Zero or KB	.20		
		1733.00		
	Cut Off RKB to Casing Head	23.00		
		1710.00		
	12" - 900' Casing Head to Shoe	1710.00		
<u>2-7/8" TUBING</u>				
1	2-7/8" EUE 8RD Tubing with Slots and Bullnose with 3/4" Hole	29.42	2579.53	2550.11
84	2-7/8" EUE 8RD K-55 Tubing	2529.11	2550.11	-0-
85	Total:	2558.53		
	Landed in Tubing Hanger Below Zero or KB	21.00		
		2579.53		
	Tubing Head to Bottom of Slotted Joint	2579.53		

Cove Fort Sulphurdale Unit Well #31-33

DEVIATION SURVEYS

<u>MEASURED DEPTH</u>	<u>DRIFT ANGLE</u>	<u>TRUE VERTICAL DEPTH</u>	<u>MAXIMUM POSSIBLE COURSE DEVIATION</u>	<u>TEMPERATURE MAXIMUM-READING THERMOMETER</u>
140'	0°30'	139.99'	1.22'	---
262'	0°45'	161.99'	2.82'	103°F
445'	1°15'	444.94'	6.81'	108°F
608'	1°45'	607.86'	11.79'	118°F
733'	1°00'	732.85'	13.97'	120°F
899'	1°45'	898.77'	19.04'	139°F
987'	1°00'	986.75'	20.58'	138°F
1080'	1°30'	1079.72'	23.01'	150°F
1332'	5°00'	1330.76'	44.97'	122°F
1400'	4°30'	1398.55'	50.31'	118°F
1587'	4°30'	1584.98'	64.98'	---
1800'	5°45'	1796.91'	86.32'	---
1945'	4°45'	1941.41'	98.33'	133°F
2354'	6°00'	2348.17'	141.08'	138°F
2731'	6°00'	2723.10'	180.49'	---
3250'	8°00'	3237.05'	252.72'	234°F
3625'	9°45'	3606.64'	316.22'	260°F
4090'	10°15'	4064.21'	398.97'	280,290,325°F
4440'	13°30'	4404.54'	480.67'	283°F
5035'	13°15'	4983.70'	617.05'	249°F
**5221' T.D.	13°15'	5164.75'	659.68'	---

**No survey was taken at total depth of 5221' so the previous drift angle of 13°15' was used to extrapolate to total depth.

COVE FORT - SULPHURDALE #31-33

LOGGING DATA (*)

<u>DATE</u>	<u>TYPE OF LOG RUN</u>	<u>LOGGED INTERVAL</u>	<u>TOTAL DEPTH</u>
	<u>Schlumberger</u>		
7/18/78	Temperature Log (malfunction suspected) [two maximum reading thermometers run simultaneously]	0' - 4858'	4858'
	Dipmeter and Four Arm Caliper [three maximum reading thermometers run simultaneously]	5207' - 1735'	5207'
7/19/78	Dual Induction - Laterolog [three maximum reading thermometers run simultaneously]	5207' - 1735'	5207'
	Compensated Neutron - Formation Density [three maximum reading thermometers run simultaneously]	5206' - 1735'	5206'
	Temperature Log	0' - 4858'	4858'
	<u>Geotex</u>		
7/19/78	Temperature, Spinner and Water Aquifer Log	0' - 4858'	4858'
	Radioactive Tracer and Spinner Log	0' - 4858'	4858'
	<u>R. F. Smith Corporation</u>		
5/24/78 to 7/24/78	Geothermal Data Log (includes engineering data related to drilling, geological, and other data)	52' - 5221'	5221'

(*) Copies of all these logs will be supplied with the Technical Report.

COVE FORT - SULPHURDALE #31-33

LOGGING DATA (*)

<u>DATE</u>	<u>TYPE OF LOG RUN</u>	<u>LOGGED INTERVAL</u>	<u>TOTAL DEPTH</u>
	<u>Schlumberger</u>		
7/18/78	Temperature Log (malfunction suspected) [two maximum reading thermometers run simultaneously]	0' - 4858'	4858'
	Dipmeter and Four Arm Caliper [three maximum reading thermometers run simultaneously]	5207' - 1735'	5207'
7/19/78	Dual Induction - Laterolog [three maximum reading thermometers run simultaneously]	5207' - 1735'	5207'
	Compensated Neutron - Formation Density [three maximum reading thermometers run simultaneously]	5206' - 1735'	5206'
	Temperature Log	0' - 4858'	4858'
	<u>Geotex</u>		
7/19/78	Temperature, Spinner and Water Aquifer Log	0' - 4858'	4858'
	Radioactive Tracer and Spinner Log	0' - 4858'	4858'
	<u>R. F. Smith Corporation</u>		
5/24/78 to 7/24/78	Geothermal Data Log (includes engineering data related to drilling, geological, and other data)	52' - 5221'	5221'

(*) Copies of all these logs will be supplied with the Technical Report.

BIT RECORD

FORM NO. FM-683B



SECURITY DIVISION
Dresser Industries, Inc.
 OILFIELD PRODUCTS GROUP
 P. O. BOX 6504 HOUSTON, TEXAS 77005 (713) 784-6011

CONTRACTOR LOFFLAND BROS.	RIG NO. 5	RIG MAKE IDECO	DC. OD X ID X LENGTH (HOLE SIZE) 8" x 30 x	MO./ DAY/ YEAR 5 / 24 / 78	PAGE 1 OF 1
COMPANY UNION OIL CO. OF CAL.	FIELD COVE FORT	RIG SIZE 1000	7" x 30 x	SPUD: 5 / 24 / 78	SALESMAN
LEASE COVE FORT	WELL NO. CFSU 31-33	PUMP NO. 1 D500	x x	U.S.: 1 / 1	BUYER
STATE UTAH	COUNTY MILLARD	PUMP NO. 2 D500	D.P. SIZE/T.J.: 4 1/2" X HOLE	INTER: 1 / 1	RIG PERSONNEL
SEC./T'SHIP/RANGE	MUD COMPANY MAGCOBAR		TD: 65	TOTAL DAYS: 65	TOTAL ROT. HRS:
				FUEL SOURCE DIESEL	WATER SOURCE SPRING

RUN NO.	SIZE	TYPE	SERIAL NO.	JETS - 32NDS REG. R. OR R.O.			DEPTH OUT	FEET	HOURS	FEET PER HOUR	CUM. HRS.	WT. 1000 LBS.	R.P.M.	PUMP PRESS.	MUD PROPERTIES						VER. DEV.	DULL COND 1/4-1/8				REMARKS	DATE	DEPTH.											
				1.	2.	3.									WT.	W.L.	P.V.	PV YP	% SOL	T		B	G	RG															
1	12 1/4	STC DGS	567 PP	18	18	18																											DRLO RAT HOLE DRLO MOUSE HOLE						
2	17 1/2	REED DJS	831265	16	16	16	301	244	33 1/2	7.4	33 1/2	12	55	500	6	56		64	35	1	1				3	2	I					CONE LOCKED							
HO 1	26	SEC PILOT	68674	18	18	18	167	167	9 1/2	17.5	43	15	55	500	6	56	5 1/2	58	68	10	63	26/23	6											CONE LOCKED					
HR 26		SEC PILOT	68674	18	18	18	295	128	16 1/2	7.8	59 1/2	15	55/65	600	6	56	5 1/2	58	68	10	63	26/23	TR		2	2	I												
3	17 1/2	STC DGS	186JN	16	16	16	502	201	17	11.8	26 1/2	30	60	1100	6	52	5 1/2	44	67	36	45	10/16	5	1 1/4	3	4	I												
4	17 1/2	SEC SATS	679196	15	16	20	711	209	14 1/2	14.4	91	35	60	1000	6	54	5 1/2	48	66	37	37	6/9	5	1 3/4	4	5	1/8												
5	17 1/2	REED SATS	417430	16	16	16	1276	545	58 3/4	9.3	149 3/4	30	45/60	600	6	58		65	41	32	5/4	1	1	3	6	1/4													
6	17 1/2	SEC SATS	973NJ	20	20	20	1735	459	83 1/2	5.5	253 1/4	15/30	35/50	800	6 1/2	52	5 1/2	46	64	36	39	5/8	2	4 1/2	4	4	1/8							LOST CIRCULATION CLEAN OUT CEMENT					
HR 3	17 1/2	STC DGS	186JN	20	20	20																			3	4	I												
7	12 1/4	REED SATS	828782	14	14	14	2920	1185	101	11.7	339 1/4	30	60	200/300	6 1/2	26			/	/	/	/	/	6	6	6	1/8								AIR/WATER				
8	12 1/4	STC SATS	719 LR	0	0	0	3728	808	46 1/4	17.4	350 1/2	30	60/80	200	6 1/2	27			/	/	/	/	/	9 3/4	2	8	1/8									AIR/WATER			
9	12 1/4	STC SATS	234 PP	0	0	0	4540	812	47 1/2	17.0	428	30	65	400	6 1/2	26			/	/	/	/	/	14	3	6	1/4									AIR/WATER			
10	12 1/4	SEC SATS	626827	0	0	0	5009	469	24	19.5	452	10/30	60	700	6 1/2	44	5 1/2	40	/	/	/	/	/		3	6	1/4									AIR/WATER			
11	12 1/4	HTC DJS	122449	0	0	0	5015	6	1	6.0	453	15/20	40	650	6 1/2	47 1/2	41	/	/	/	/	/		5	4	I										AIR/WATER			
12	12 1/4	STC SATS	397 HR	0	0	0	5221	206	15 1/2	13.3	467 1/2	30	60	450	6 1/2	53	5 1/2	34	/	/	/	/	/	13 1/4	3	3	I									AIR/WATER			
13	12 1/4	STC SATS	279 PD	0	0	0																			6	4	I										AIR/WATER DRLO CMTS AND PLUG		
1	8 3/4	CHRISTENSEN DIAMOND					5015/5018	3	8	/		10/20	30	650	6 1/2	47																					CORE No. 1 JAMMED CORE		
2	8 3/4	CHRISTENSEN DIAMOND					5018/5021	3	10	/		10/20	30	650	6 1/2	47																					CORE No. 2 JAMMED CORE		

* DENOTE BY (N) - NO. (L) - LIGHT (M) - MEDIUM OR (H) - HEAVY ROUNDING OF GAGE
 ** 1. SALESMAN 2. ENGINEER 3. RIG PERSONNEL
 SUBJECT TO PROVISIONS ON REVERSE SIDE

COVE FORT - SULPHURDALE #31-33

MAXIMUM READING THERMOMETER TEMPERATURE SURVEYS

<u>DATE</u>	<u>TIME SINCE FLUID INJECTION</u>	<u>THERMOMETER READING</u>	<u>DEPTH</u>
6/28/78	12 hours	210°F	2000'
7/10/78	2 hours	294°F±	4700'±
	5 hours	294°F±	4700'±
	10½ hours	293°F±	4700'±
	18 hours	293°F±	4700'±
7/17/78	19½ hours	249°F	5035'

NOTE: Maximum reading thermometer temperature measurements run in conjunction with deviation surveys are listed with the deviation surveys in the Well History section of this report.

COVE FORT SULPHURDALE UNIT #31-33

CEMENTING OPERATIONS

Introduction

Two major kinds of cementing operations were carried out during the drilling of CFSU #31-33. The first type of operation involved attempts to seal off lost circulation zones to enable casing to be set and competently cemented, and the abandonment of the well. The second type of operation was the cementing of the 20" and 13-3/8" casing strings.

A total of 7440 ft³ of cement was mixed, pumped and set in 43 separate plugs while attempting to plug lost circulation zones. These efforts occupied approximately 21 days of rig time, and accounted for a total cost of approximately \$320,000. These efforts are discussed below.

The cementing of the 20" and 13-3/8" casing strings required an additional 3594 ft³ cement. These efforts are described in a separate section below.

Lost Circulation Control Efforts

A significant amount of effort was required in attempting to plug lost circulation zones prior to running the 13-3/8" casing. These efforts were necessary in order to ensure that the 17-1/2" x 13-3/8" annulus would contain a column of cement without loss

to the formation. In the lower part of the hole efforts were aimed at plugging it back to 2600' (abandonment of the lower section). Table 1 presents a comprehensive description of all cement operations carried out while attempting to control lost circulation in CFSU #31-33. Table 2 presents a summary and description of cement additives used on CFSU #31-33.

Cement of API classification, "Class B", was employed in all but one instance. This Portland cement is intended for use from surface to a depth of 6000' when conditions require moderate to high sulfate resistance. One cement plug (#13) used Halliburton Thix-Set Cement. This cement forms a thixotropic slurry which is designed to rapidly develop high viscosity and gel strength when in a static state. These properties make the cement particularly suited for plugging the highly fractured or vugular zones encountered in CFSU #31-33. However, great care is required in order to prevent cementing the drill pipe into the hole.

Eight plugs of a patented water/polymer lost circulation compound were also used with limited success while attempting to control the lost circulation condition. This compound, Pal Mix 110-R, is a specially processed material which remains a nonviscous slurry for about 45 minutes after mixing, and then sets into a tough plastic plug.

Table 3 summarizes cementing operations associated with running casing. The 30" casing was cemented in place using ready mix

cement poured between the 30" casing and the hole wall prior to the start of drilling operations.

The 20" casing was successfully cemented through drill pipe engaged with the 20" duplex casing float shoe to reduce the volume of cement required, allowing additional cement to be added. The 13-3/8" casing was successfully cemented in two stages to reduce the hydrostatic head or pressure on the formation allowing the first stage to partially set and support the weight of the second stage thereby reducing the chance of fluid loss to the formation. While waiting on cement after the second stage cementation, the cement level in the 13-3/8" x 20" annulus fell 180'. This annulus was filled with cement using 1" pipe inserted into the void.

0 min and slowly returned at a low rate.

but small amount of CH₄ emission continued.

600' +.
at 1236' while drilling out cement. Continued drilling to 1257'.

17' while drilling firm cement.

hole.

hole.

hole.

it with full returns.

it with full returns.

while drilling firm cement. Regained circulation after pumping.
Open hole to 1564'.

to locate cement.

of cement only, with no loss = 1672'. Implies 57 ft³ water in hole below cement. 1291 ft³ mud. Theoretical volume to fill hole from 1638' to surface = 2774 ft³. Volume to fill 4½" drill pipe from surface to 1638' = 131 ft³. Fluid level dropped after 10 minutes.

surface during last 20 ft³ of displacement water. Capacity of 4½" drill pipe from 1515' to 1580' = 126 ft³. Firm cement from 1515' to 1580'. Theoretical volume of firm cement at cement from 1638' to 1675'. No fluid loss experienced. Theoretical volume of 12 ft³.

17' of 12½" hole.

Volume of cement plug = 4977'.

4770' to 4790', 4805' to 4830', 4900' to 4926'. Cement stringers 4830' to 4900'. 109'. No fluid returns to surface.

t 5011'. Attempted to set Halliburton EZSV plug #1. Plug stuck, released, and

om of cement = 5039'.

EZSV plug #2 at 4750' following cement plug #35.

e plug.

e plug.

e plug.

EZSV plug #3 at 2750'.

ool out of EZSV plug #3 to 2740'.

f EZSV plug #3 at 2750'.

l pipe = 219 ft³. Drilled out cement from 2574' to 2745'. Theoretical volume
ed - 140 ft³.

cement from 2552' to 2600'.

TABLE 2
SUMMARY AND DESCRIPTION OF CEMENT ADDITIVES USED ON CFSU 31-33

ADDITIVE	DESCRIPTION	FUNCTION OF ADDITIVE			REMARKS
		LIGHTEN SLURRY WEIGHT	ACCELERATE SETTING TIME	CONTROL LOST CIRCULATION	
Perlite (expanded)	treated volcanic material	X			absorbs water under high pressure
Silica Flour	finely powdered silicon dioxide				prevents loss of strength at high temperatures
Gel	Wyoming-type bentonite	X		X	increases suspension of particulate additives; maintains even distribution of other additives; reduces slurry weight
CaCl ₂	in powder or flake form		X		accelerates early strength
CFR-2 (*)	a naphthalene polymer		X		a cement dispersant to reduce viscosity and a friction loss reducer
Gilsonite	particulated naturally occurring asphaltite	X		X	inert - does not absorb water; high cement strength; resists corrosion; granular lost circulation additive
Flo-Cele (*)	cellulose flakes			X	lost circulation additive
Nut-Plug (**)	walnut shells			X	granular lost circulation additive
LCM	any mixture of lost circulation materials			X	mixture of gilsonite, cellulose flakes, and walnut shells

(*) Halliburton trademark

(**) Magcobar trademark

TABLE 3

SUMMARY OF CASING CEMENTING OPERATIONS

CFSU #31-33

<u>DATE</u>	<u>CASING SIZE</u>	<u>HOLE SIZE</u>	<u>DEPTH OF OPEN HOLE</u>	<u>CASING FLOAT SHOE AT</u>	<u>OTHER CASING ACCESSORIES</u>	<u>MATERIAL INJECTED</u>	<u>COMPOSITION</u>	<u>VOLUME</u>	<u>REMARKS</u>
12/77	30"	36"	32' G.L.	32' G.L.		cement slurry	•ready mix cement	3½ yd ³	Bill Martin Rathole Service
5/30/78	20"	26"	289' K.B.	280' K.B.		cement slurry	•class "B" cement 2% CaCl ₂ by weight	767ft ³	80% excess volume
						displacement fluid	•drilling mud	12ft ³	injected through 4½" drill pipe stabbed into shoe. Good cement returns to surface. Located cement at 272'. Theoretical cement location = 274.3'.
6/22/78	13-3/8"	17-1/2"	1735' K.B.	1733' K.B.	Insert float collar at 1697'. Multiple-stage "DV" cementing collar at 1115'	Flush #1	•water	100ft ³	Begin First Cementing Stage
						Flush #2	•water FR-20 flush- ing agent and Silica Flour	100ft ³ 70#	
						Flush #3	•water sodium sili- cate	53ft ³ 30ft ³	
						Flush #4	•water	200ft ³	

Summary of Casing Cementing Operations - CFSU #31-33

Page Two

<u>DATE</u>	<u>CASING SIZE</u>	<u>HOLE SIZE</u>	<u>DEPTH OF OPEN HOLE</u>	<u>CASING FLOAT SHOE AT</u>	<u>OTHER CASING ACCESSORIES</u>	<u>MATERIAL INJECTED</u>	<u>COMPOSITION</u>	<u>VOLUME</u>	<u>REMARKS</u>
						cement slurry followed by wiper plug	•class "B" cement, 1:1 Perlite, 40% Silica Flour, 0.5% CFR-2	795ft ³	70% excess volume
						displacement fluid	•drilling mud	1520ft ³	Did not bump top cement plug on insert float collar. Theoretical displacement volume to bump = 1473ft ³ . Opened "DV" collar and circulated cement through it. Received 392ft ³ cement slurry from above "DV" collar. Theoretical excess volume = 331ft ³ . Circulated mud through "DV" collar four hours without fluid loss.
						Flush #1	•water	168ft ³	Begin Second Cementing Stage
						cement slurry	•same as first stage	1611ft ³	90% excess, followed by "DV" closing and wiper plug.
						displacement fluid	•drilling mud	977ft ³	"DV" collar closed. Theoretical displacement volume = 968ft ³ . Partial cement returns to surface ~50ft ³ . Theoretical returns = 746ft ³ . 93% of excess lost to formation. Cement level in annulus fell 180' while waiting on cement. Filled with cement using 1" pipe. Located top of cement in casing at 1697'.



MAGCOBAR DIVISION, DRESSER INDUSTRIES, INC. 475 17TH STREET SUITE 1600 DENVER, COLORADO 80202

MAGCOBAR MUD COST SUMMARY

for

UNION OIL OF CALIFORNIA
CFSU 31-33
Section 31, 25 South - 6 West
Millard County, Utah

<u>NUMBER OF UNITS</u>	<u>PRODUCT DESCRIPTION</u>	<u>AMOUNT</u>
60.00	Magco bar	\$ 363.60
1,714.00	Magcogel	8,467.16
5.00	Kwik Thik	28.25
140.00	Magco Dustless	691.60
3.00	Spersene	85.17
64.00	Tannathin	649.09
141.00	Chip Seal	1,680.12
12.00	Cottonseed Hulls	149.52
76.00	Mud Fiber	1,067.04
9.00	Nut Plug Fine	120.87
8.00	Nut Plug Medium	107.44
5.00	Aluminum Stearate	300.50
10.00	Magconol	607.90
15.00	Calcium Chloride	264.15
546.00	Caustic Soda	12,110.28
15.00	Lime	90.90
449.00	Miscellaneous Products	26,827.75
55.00	Zinc Carbonate	5,247.00
15.00	Sodium Bicarbonate	763.41
51.00	OS 1	1,512.15
2.00	SI-1000	1,158.46
	State Sales Tax	2,483.10
	Sundry Rebill	7,405.98
	Utah County Tax	470.18
	TOTAL MUD COST	\$ 72,436.74

(Above retyped from Magco bar Mud Cost Summary issued 8/21/78)/

MAGCOBAR WELL SUMMARY

DATE: 8/1/78

COMPANY: Union Oil of California CONTRACTOR/RIG #: Loffland 5
 WELL NAME: CFSU 31-33 SPUD DATE: 5-24-78
 LEGAL DSCRIP: Sec. 31, 25S-6W COMPLETION DATE: 7-23-78
 COUNTY/STATE: Millard, Utah MUD ENGINEER(S): Ralph W. Bowie
 TOTAL DEPTH: 5221' ETD 2600' MAG STOCK POINT(S): Milford, Utah
 TOTAL DAYS: 60 TOTAL COST: _____

CASING/BIT INFORMATION

INTERVAL...	HOLE SIZE	BIT SIZE	CASING SIZE	# BITS USED
<u>0</u> ' to <u>280</u> ' ,	<u>28"</u>	<u>17 1/2/26"</u>	<u>20"</u>	<u>2</u>
<u>280</u> ' to <u>1735</u> ' ,	<u>17 1/2"</u>	<u>17 1/2"</u>	<u>13 3/8"</u>	<u>4</u>
<u>1735</u> ' to <u>5221</u> ' ,	<u>12 1/4"</u>	<u>12 1/4"</u>	<u>OPEN HOLE</u>	<u>7</u>
' to ' ,				

DRILLING FLUID INFORMATION

MUD UP AT: SURFACE ' ,

INTERVAL...	MUD TYPE	MUD WEIGHT (low-high)	DAYS	COST	COST/FT
<u>0</u> ' to <u>280</u> ' ,	<u>SPUD MUD</u>	<u>8.7 - 9.1</u>	<u>6</u>	<u>\$ 2,050.13</u>	<u>\$ 7.32</u>
<u>280</u> ' to <u>2100</u> ' ,	<u>FLOCCULATED</u>	<u>8.4 - 9.0</u>	<u>29</u>	<u>18,472.14</u>	<u>10.15</u>
<u>2100</u> ' to <u>5221</u> ' ,	<u>AERATED WATER</u>		<u>27</u>	<u>51,914.47</u>	<u>16.63</u>
' to ' ,					

SUMMARY OF COMMENTS/PROBLEMS

(indicate depth interval on left)

See Interval Breakdown and Daily Drilling
Log for more information.

GEOLOGIC INFORMATION

FORMATION	DEPTH
<u>Andesite Surface Debris</u>	<u>205</u> ' ,
<u>Competent Andesite</u>	<u>300</u> ' ,
<u>Altered Andesite</u>	<u>520</u> ' ,
<u>Andesite with quartz veins and sulfides</u>	<u>920</u> ' ,
<u>Red Silt Stone and intermittent Grey Dolomite</u>	<u>1740</u> ' ,
<u>No returns</u>	<u>5221</u> ' ,
<u>No actual formation tops logged.</u>	

MAGGOGAR FINAL REPORT

OPERATOR: Union Oil of California WELL NAME: CFSU 31-33
 LEGAL DSCRIP: Sec. 31, 25S-6W COUNTY, STATE: Millard, Utah
 Interval: 0 ' to 280 ' Mud Properties....
 Footage: 280 Weight: 8.7 - 9.1 Cl⁻: 600
 Days: 6 Vis: 45 Solids: 2-6%
 Ft/Day: 46.5 F/L: 15 Oil: 0
 Mud Cost: \$ 2,050.00 pH: 11.0 LCM: 0
 Cost/Day: \$ 7.32

MATERIALS....

<u>Product</u>	<u>Units</u>	<u>Cost</u>	<u>Units/Day</u>	<u>Cost/Day</u>
Magcogel	207	\$ 4.94	34 1/2	\$ 170.43
Caustic Soda	8	22.18	1 1/3	29.57
Lime	3	6.06	1	6.06

REMARKS....

This interval was drilled with a flocculated mud having sufficient viscosity
(45-55 sec/qt) to clean the hole. No problems were encountered during the drilling
of this interval. A 17 1/2" hole was drilled to 282' and opened to 26". 20"
surface casing was run to 280' and cemented without any trouble.

MAGCORAR FINAL REPORT

OPERATOR: Union Oil of California WELL NAME: CFSU 31-33
 LEGAL DSCRIP: Sec. 31, 25S-6W COUNTY, STATE: Millard, Utah
 Interval: 280 ' to 1735 ' Mud Properties....
 Footage: 1455 Weight: 8.4 - 9.0 Cl⁻: 900
 Days: 29 Vis: 32 - 40 Solids: 4%
 Ft/Day: 50.2 F/L: 40 Oil: 0
 Mud Cost: \$ 18,724.84 pH: 10.5 - 11.5 LCM: 0
 Cost/Day: \$ 645.68

MATERIALS....

<u>Product</u>	<u>Units</u>	<u>Cost</u>	<u>Units/Day</u>	<u>Cost/Day</u>
Magcogel	1425	\$ 4.94	49.14	\$ 242.74
Caustic Soda	85	22.18	2.93	65.01
Tannathin	59	10.49	2.03	21.34
Lime	13	6.06	.45	2.72
Sodium Bicarbonate	26	23.77	.9	21.31
Zinc Carbonate	38	95.00	1.07	101.55
Mud Fiber	31	14.04	1.07	15.02
Chip Seal	20	11.32	.69	7.81
SI-1000	2	579.23	.03	19.97
Aluminum Stearate	4	60.10	.14	8.29
Magconol	5	60.79	.17	10.48

MAGCOBAR FINAL REPORT

OPERATOR: Union Oil of California WELL NAME: CFSU 31-33
 LEGAL DSCRIP: Sec. 31, 25S-6W COUNTY, STATE: Millard, Utah
 Interval: 1735 ' to 5221 ' Mud Properties....
 Footage: 3486 Weight: 8.5 - 9.0 Cl⁻: 700
 Days: 27 Vis: 30 - 36 Solids: 1 1/2 to 4%
 Ft/Day: 129 F/L: N/C - 40 Oil: 0
 Mud Cost: \$51,914.47 pH: 10.5 - 11.5 LCM: 0
 Cost/Day: \$ 1,922.75

MATERIALS....

<u>Product</u>	<u>Units</u>	<u>Cost</u>	<u>Units/Day</u>	<u>Cost/Day</u>
Sodium Nitrite	531	\$ 59.75	19.67	\$ 1,175.08
Caustic Soda	424	22.18	15.70	348.31
OS-1	46	29.65	1.7	50.51
Calcium Chloride	15	17.17	.56	9.54
Magcogel	45	4.94	1.67	8.23
Mud Fiber	65	14.04	2.41	33.80
Chip Seal	20	11.32	.74	8.39
Nut Plug	5	13.43	.19	2.55

Operator Union Oil of California
 Well CFSU 31-33
 Contractor Loffland 5
 Engineer R.W. Bowie

Location Sec. 31, 25S-6W
 County Millard
 State Utah
 Elevation _____

MAGCOBAR DIVISION
DRILLING MUD LOG
 Page 1 of 3

Hole Size	Casing Size	Interval Length
26 inch	20 inch	280 ft.
17 1/2 inch	13 3/8 inch	1455 ft.
12 1/4 inch	OPEN inch	3486 ft.
inch	inch	ft.

Spud Date 5-25-78
 Under Surface Date 6-2-78
 Finish Date 7-21-78
 Total Depth 4221 ft.
 Mud Cost \$ 72,436.74

DATE	DEPTH	MUD PROPERTIES															MATERIALS						COST		REMARKS																				
		WT. LBS./GAL.	SAMPLE TEMP.	VISC. SEC./QT.	PLASTIC VISC.	YIELD POINT	GELS	PH	FILTRATE API	HTHP API	Alkalinity Pm	Alkalinity Pt	Alkalinity Mt	Chloride ppm	Calcium ppm	Sand % Vol.	Solids % Vol.	Oil % Vol.	#/bbl. Bentonite	#/bbl. Drill Solids	L.C.M. #/bbl.	W' Value	MAGCOBAR	MAGCOGEL		SPERSENE	CAUSTIC SODA	TANNATHIN	Lime	Sodium Bicarbonate	Zinc Carbonate	FLR PNY	TC RATE												
5-25		SURFACE																																			881	881							
5-26	123	8.7	60	36	16	8	8	12	9.0	12	1.0	.2	.4500	0	Tr234	14	10							56	1										566	1447									
5-27	182	9.0	65	40	17	13	13	21	11.5	12	1.2	.7	.7400	1/2	5	10	35						56	1											314	1761									
5-28	301	8.8	65	39	14	11	5	10	11.0	15	.6	.2	.3750	100	Tr 4	17	20						15	2											124	1855	Reaming								
5-28	112	9.1	69	43	17	17	11	18	105						Tr534								Mid Day Check											0	1865	Reaming to 302'									
5-29	218	9.1	88	63	23	26	12	26	105	10	.9	.4	.6900	100	1/2 6	24	30							2		1									53	1938									
5-30	294	RUNNING CASING (20") TO 294'																					17	1														111	2055						
5-31	280	CASING SET AT 280' - NIPPLED UP B.O.P. - W.O.C. TO SET																																					253	2302					
6-01	300	8.5	63	30	4	2	2	2	110	47	.2	.3	.4400	200	1 1/2							.74														0	2302								
6-02	320	8.7	83	37	11	8	7	13	120	46	1.8	.9	1.2700	150	3/4 3	135	135					.66	.59			1		3							98	2400	Sharp cut								
6-03	588	9.0	118	46	16	10	6	3	105	36	.7	.3	.713K	100	1/2 5 1/2	19	280					.69	.78			50									259	2660									
6-04	711	9.0	83	43	6	3	2	5	110	19	.7	.35	.717K	100	Tr 5 1/2	16	31					.74	.55		39	3	3								305	2965									
6-05	899	8.9	125	35	9	6	5	9	105	21	.7	.3	.721K	100	1/2 4 1/2	17	23					.68	.12		4	2	1								78	3043									
6-06	1089	8.9	100	35	7	4	2	6	110	20	.3	.6	.615K	100	0 4 1/2	17	23					.71	.67		22	3	3								217	3260									
6-07	1233	W.O.C.; LOST CIRCULATION AND ENCOUNTERED H ₂ S (AVG 500 ppm) AT 1233', 9:50 p.m.															50		2	2																		525	3786						
6-08	1233	W.O.C. - NO DRILLING ACTIVITY																																				0	3786						
6-09	1240	8.6	85	34	8	1	2	3	110	16	1.1	.6	.9400	<40	Tr 2.4	159	579					.9	.51													0	3786	W.O.C.							
6-10	1253	LOST ALL MUD, 6 CEMENT PLUGS SET (UNABLE TO TAG)																																				309	4095						
6-11	1253	12TH CEMENT PLUG (UNABLE TO TAG)																																					269	4365					
6-12	1253	DRILLED 88' CEMENT, LOST ALL RETURNS AT 1253', W.O.C.																																						404	4769				
6-13	1230	CEMENT PLUG #16 IN PLACE																																							558	5326			
6-14	1230	CEMENT PLUG #16 TAGGED AT 1230', DRILLED OUT WITH 33 VISCOSITY MUD																																									775	6102	
6-15	1230	8.5	78	35	7	4	2	6	125	40	1.2	.11	.4700	50	1.2	129						.71	.67		125	6	3	1		5						1326	7428								
6-16	1400	8.5	105	36	6	12	4	6	115	41	2.5	.85	1.01K	40	Tr 1 1/4	112	7					.41	.713		74	2	6	1	3	2					777	8205									

Operator Union Oil of California
 Well CFSU 31-33
 Contractor Loffland S
 Engineer R.W. Bowie

Location Sec. 31, 25S-6W
 County Millard
 State Utah
 Elevation _____

MAGCOBAR DIVISION
DRILLING MUD LOG
 Page 2 of 3

Hole Size	Casing Size	Interval Length
_____ inch	_____ inch	_____ ft.
26 inch	20 inch	280 ft.
17 1/2 inch	13 3/8 inch	1455 ft.
12 1/4 inch	OPEN inch	3486 ft.
_____ inch	_____ inch	_____ ft.

Spud Date 5-25-78
 Under Surface Date 6-2-78
 Finish Date 7-21-78
 Total Depth 5221 ft.
 Mud Cost \$ 72,436.74

DATE	DEPTH	MUD PROPERTIES																		MATERIALS										COST		REMARKS																	
		WT. LBS./GAL.	SAMPLE TEMP.	VISC. SEC./DT.	PLASTIC VISC.	YIELD POINT	INITIAL	10 MIN.	PH	FILTRATE API	HT. V.P. API	Alkalinity Pm	Alkalinity Pt	Alkalinity Ml	Chloride ppm	Calcium ppm	Sand % Vol.	Solids % Vol.	Oil % Vol.	#/bbl Bentonite	#/bbl Drill Solids	Zinc Carbonate	in Value	KI Value	SODIUM SILICATE	MAGCOCEL	SPERSENE	CAUSTIC SODA	TANNATHIN	Lime	Sodium Bicarbonate		Zinc Carbonate	Mud Fibers	Chip Seal	SI-1000	Aluminum Sulfate	Margonol	PER DAY	TO DATE									
6-17	1553	8.5	80	31	3	3	2	4	115	36	2.3	57	1.0	700	(40)	165	935	546	.2	.58	80		72		3	3	1											972	9177										
6-18	1460	8.5	75	36	8	6	4	6	120	197	235	1.2	1.75	900	(40)	128	193	1.4	.65	122		245		10	2	2			3	20								2370	11547										
6-19	1646	8.5	110	32	5	7	4	11	115	34	2.3	1	1.3	850	(40)	Tr	939	546	1.1	.5	267		55		6	8	1		2		1						1390	12938											
6-20	1730	LOST CIRCULATION										NO MUD IN PITS																												2488	15426								
6-21	1730	CEMENT PLUG #21 and #22																																								1555	16981						
6-21	1650	8.5	110	32	4	6	3	2	115	37	2.3	1.1	1.4	600	(40)	1-1/4																									0	16981							
6-22	1600	8.4	101	39	6	7	4	6	120	34	1.1	1.3	1.6	700	(40)	1-1/4																									365	17346							
6-23	1735	8.5	85	39	8	5	5	6	110	37	1.1	1.0	1.3	700	(50)	1/2	1-3/4			.68	96		6		5	6		4													313	17660	Run 13 3/8 casing						
6-24	1735	NIPPLED UP B.O.P. (13 3/8")																																							0	17660							
6-25	1735	DRILLED OUT DV TOOL AT 1115																																								0	17660						
6-26	1770	8.5	115	30	5	10	4	6	125	42	5.5	2.1	2.5	650	(100)	1	1-1/4																										1241	18900	Pits Seaming				
6-27	1935	8.4	110	30	5	4	4	12	115	41	5.5	1.4	2.1	700	(40)	1/2	1																										1203	20103	Severe foaming				
6-28	2100	LOST ALL FLUID AT 1530 HOURS; RIGGED UP FOR AERATED WATER																																									418	20522					
6-29	2100	AERATED WATER																																									23	20545					
6-30	2462	AERATED WATER																																									279	20825					
7-01	2755	AERATED WATER																																										736	21560				
7-01	2920	AERATED WATER																																										838	22399	Fishing			
7-03	2920	AERATED WATER																																										270	22668				
7-04	3276	AERATED WATER																																										233	22901				
7-05	3634	AERATED WATER																																											396	23297			
7-06	3725	AERATED WATER																																											1064	24364			
7-07	4085	AERATED WATER																																												8229	32591		
7-08	4540	AERATED WATER																																												9302	41593		
7-09	4606	AERATED WATER																																													5466	47350	



ANNULAR FLOW DYNAMICS

WELL NAME: CFSU 31-33
 LOCATION: Sec. 31, 25S-6W
 CONTRACTOR: Loffland 5

DATE: 6-27-78 DEPTH: 1972'

HYDRAULICS AND RHEOLOGY DATA: 10.19 BPV

PUMP No. 1: D-500 SIZE 6 1/2 x 16 @ 56 S.P.M. 428 G.P.M.

PUMP No. 2: D-500 SIZE 5 1/2 x 16 @ S.P.M. G.P.M.

Hole Size: D.P. Hyd. Ann. Eff. Ann. Shear Rate

12.5" 4.5" 8.0" 77 ft/min 23 sec⁻¹ 34 cps 72 psi
 12.5" 8" 4.5" 114 ft/min 61 sec⁻¹ 30 cps 299 psi
 12 1/2" 8" 4.25" 164 ft/min 92 sec⁻¹ 40 cps 637 psi

V.G. R.P.M. DIAL EFF. VIS. FUNNEL VIS. 31 BOTTOM HOLE ASSEMBLY

600 13 6.5 CPS A.V. 5

300 8 8 CPS P.V. 3

200 CPS Y.P. 2

100 CPS In. Gel. 9

6 CPS 10 Min. Gel. 9


3 CPS Sample Temp. 105°F BIT

MUD WT. 8.55 FLOWLINE TEMP. 110

TOTAL ANNULAR ΔP 2.87 PSI E.C.D. 8.55

REMARKS: 'n' = .70 'K' = 52
 APL = .03 #/gal

MUD ENGINEER: Ralph W. Bowle, Jr.



BY THE OILFIELD PRODUCTS DIVISION TECHNICAL GROUP. IF OOPS APPEAR, PLEASE CONTACT THE OILFIELD PRODUCTS DIVISION. REPRODUCTION IN ANY FORM NOT PERMITTED. THIS CHART AND THE DATA PLACED THEREON ARE SUBJECT TO THE PROVISIONS ON THE REVERSE SIDE.



Hydraulics Work Sheet

Security Division • Dresser Industries, Inc. • P.O. Box 6504 • Houston, Texas 77005 • (713) 784-6011

OPERATOR Union Oil of California CONTRACTOR Loffland RIG NO. 5 DATE 6-27-78
 WELL NAME CFSU NO. 31-33 COUNTY Millard STATE Utah

WELL DATA:

Hole size 12.5 from Surface to 1735 Drill pipe size 4 1/2 wt. 16.60 t.j. type XH length 1435
 Drill collar length 300' OD x ID 8 X 2.5 Mud wt. 8.55 Min. annular velocity (drill pipe) 77

PUMP DATA:

Make EMSCO Liner size 6 1/2 X 16 / / /
 Model D-500 Press. Rating 1317 / / /
 SPM 56 Oper. Press. limit 1200 / / /

- | | | |
|--|------|---------|
| 1. Maximum Operating Pressure (Table 1) | 1200 | psi |
| Volumetric Discharge (Table 1) | 7.64 | gal/stk |
| 2. Circulation Rate (Table 2A or 2B) | 428 | gpm |
| 3. Annular Velocity: (a) Drill pipe (Table 3A) | 77 | ft/min |
| (b) Drill collars (Table 3B) | 164 | ft/min |
| 4. Surface Equipment Type (Table 4) | 2 | |



SYSTEM PRESSURE LOSSES:

- | | | |
|---|--------------------------------|-----------|
| 5. Surface Equipment (Table 5) | 54.0 | psi |
| 6. Drill Pipe Bore (Table 6): loss per 1000 ft. X length | $\frac{75}{1000} \times 1735$ | 130.0 psi |
| 7. Drill Pipe Annulus (Table 7): loss per 1000 ft. X length | $\frac{1}{1000} \times 1735$ | 1.7 psi |
| 8. Drill Collar Bore (Table 8): loss per 100 ft. X length | $\frac{53}{100} \times 237$ | 125.6 psi |
| 9. Drill Collar Annulus (Table 9): loss per 100 ft. X length | $\frac{1}{100} \times 237$ | 2.4 psi |
| 10. System pressure loss (excluding nozzles): add lines 5 thru 9 X $\frac{\text{Mud Wt.}}{10}$ | $313.7 \times \frac{8.55}{10}$ | 268.2 psi |
| 11. Pressure available for nozzle selection: line 1 minus line 10 X $\frac{10}{\text{Mud Wt.}}$ | $931.8 \times \frac{10}{8.55}$ | 1090 psi |

JET NOZZLE SELECTION:

- | | | |
|---|-------------------------------|---------|
| 12. Jet Nozzle Size (Table 10) | 14 | 32nd |
| 13. Pressure loss through jet nozzles (Table 10): pressure loss X $\frac{\text{Mud Wt.}}{10}$ | $8.37 \times \frac{8.55}{10}$ | 715 psi |
| 14. Jet Velocity (Table 11) | 305 | ft/sec |
| 15. Total pressure expenditure for system: (add line 10 and line 13) | 983 | psi |

16. % HHP at bit: $\frac{\text{line 13}}{\text{line 15}} \times 100 = \frac{715}{983} \times 100 = 73\%$

Actual H Power = $\frac{715 \times 428}{1714} = 178.5$



CORROSION REPORT

DATE 6-21-78 CORROSION REPORT NO F-14510

A-979-2		FROM	
Union Oil of California		MAGCOBAR DIVISION	
		FIELD CORROSION LAB:	
		XXXXXX 1020 Atherton Dr., Suite C-201	
(Loffland Rig 5)		CITY, STATE AND ZIP CODE	
		Salt Lake City, Utah 84107	
SUBJECT WELL		NUMBER	AREA
C.F.S.U. 31-33			Salt Lake
COPY TO		COPY TO	
Harold Moss Steve Pye		Dee Thomas Jim Fox ✓ Tom Cox	
COPY TO		COPY TO	
Bernie Sansing Ralph Bowie		Art Vincent Dee Slauch Bob Perkins	

THIS WILL CONFIRM THE CONVERSATION CONCERNING THE CORROSION RING(S) FROM THE SUBJECT WELL.

COUPON NUMBER 19341 PULLED AT A DEPTH OF 1241 pulled 6-7-78 FT. SHOWED A CORROSION RATE OF
 Approx 1.4* LB/FT²/YR. trace CARBONATE positive SULFIDE.

COUPON NUMBER _____ PULLED AT A DEPTH OF _____ FT. SHOWED A CORROSION RATE OF
 _____ LB/FT²/YR. _____ CARBONATE _____ SULFIDE.

COUPON NUMBER _____ PULLED AT A DEPTH OF _____ FT. SHOWED A CORROSION RATE OF
 _____ LB/FT²/YR. _____ CARBONATE _____ SULFIDE.

The measured corrosion rate on this ring was 1.7; however, at least 20% of the weight loss was due to mechanical erosion by sand solids, giving a true corrosion rate of about 1.4 lb/ft²/yr. H₂S was encountered two days before this ring was pulled. Zinc carbonate has been used to treat for H₂S during drilling since that time.

Following are the conversion rates between the various units for steel coupons (specific gravity 7.86):

- mpy = 24.62 × lb/ft²/yr
- mpy = 5.03 × kg/m²/yr
- lb/ft²/yr = 0.04 × mpy
- lb/ft²/yr = 0.20 × kg/m²/yr
- kg/m²/yr = 0.20 × mpy
- kg/m²/yr = 4.90 × lb/ft²/yr

PLEASE CONTACT THE OPERATOR AND CONTRACTOR CONCERNING THIS REPORT.

SEND	<i>Bob Perkins</i>	TITLE	AREA CODE	PHONE NUMBER
		Sales Engineer	801	262-9954

DISTRIBUTION:

- 1 - AREA ENGINEER
- 2 - FILE
- 3 - ENG. MANAGER
- 4 - ENGINEER
- 5 - FIELD
- 6 - FILE
- 7 - EXTRA COPY



Corrosion Lab
P.O. Box 1407
Houston, Texas 77001
Bldg. 1-A, Rm. 352

CORROSION RING REPORT

DATE _____

OILFIELD PRODUCTS DIVISION—DRESSER INDUSTRIES INC.

TITE HOLE YES NO

OPERATOR UNION OIL OF CALIF.		CONTRACTOR LOFFLAND		RIG NO. 5	
ADDRESS RIG		ADDRESS RIG		SPUD DATE 5-24-78	
PORT FOR MR. HAROLD MOSS		REPORT FOR MR. BERNIE SANSING		SECTION, TOWNSHIP, RANGE 33-25S-6W	
WELL NAME AND NO. C.F.S.U. 31-33		FIELD OR BLOCK NO. W/C		COUNTRY, PARISH, OR OFFSHORE AREA MILLARD	
STATE OR PROVINCE UTAH		OPERATION		CIRCULATION DATA	
PRESENT ACTIVITY		CASING		ANNULAR VEL. (FT./MIN.)	
SURFACE		MUD VOLUME (BBL)		HOLE PITS	
20 IN. AT 280 FT.		PUMP SIZE		5 1/2 16	
INTERMEDIATE		TOTAL CIRCULATING VOLUME		PUMP MAKE	
IN. AT FT.		870		EMSCO	
PRODUCTION OR LINER		IN STORAGE		MODEL	
IN. AT FT.		BBL/STROKE STROKE/MIN.		D-500	
DRILL PIPE SIZE		CIRCULATING PRESSURE PSI		1000	
4 1/2		TYPE		BOTTOMS UP (MIN.)	
XH		MUD		SYSTEM	
7"		GEL & WATER		TOTAL (MIN.)	
DRILL COLLAR SIZE		MUD TYPE			
7"					

SAMPLE FROM <input type="checkbox"/> FLOWLINE <input type="checkbox"/> PIT		MUD PROPERTIES		CORROSION RING DATA			
DOWNLINE TEMPERATURE _____ °F		INSERT COUPON		COUPON NUMBER: 19341 4 1/2 FH K=207			
Time Sample Taken		REMOVE COUPON		INSTALL DATE 6-1-78 TIME 6:00 AM			
Depth (ft.)		1100		REMOVE DATE 6-7-78 TIME 10:00 AM			
Weight (ppg) <input type="checkbox"/> (lb./cu. ft.) <input type="checkbox"/>		8.6		HOURS 136 NO. DAYS 5 1/2			
Mud Gradient (psi/ft.)		34		INSTALL DEPTH (ft.) 280			
Funnel Viscosity (sec./qt.) API at _____ °F		8		REMOVE DEPTH (ft.) 1241			
Plastic Viscosity cps at _____ °F		1		LOCATION IN DRILL STRING-DEPTH			
Yield Point (lb./100 sq. ft.)		1 2/3		KELLY SUB: CHANGE OVER: <input checked="" type="checkbox"/>			
C-I Strength (lb./100 sq. ft.) 10 sec./10 min.		11.5		INHIBITOR ADDED: NONE			
<input checked="" type="checkbox"/> Strip <input type="checkbox"/> Meter		16		TUBING STRING <input type="checkbox"/> DRILL STRING <input type="checkbox"/> PITTED <input type="checkbox"/> SCALE <input type="checkbox"/> RUSTED <input type="checkbox"/>			
Filtrate API (ml./30 min.)		2		COUPON SIZE (circle one) PIN OR BOX FAILURE OTHER			
HP-HT Filtrate (ml./30 min.) _____ °F		1.1		3 3/4 (4 1/2) 5 1/2 INCHES 138.9280			
Couple Thickness 32nd in. API <input checked="" type="checkbox"/> HP-HT <input type="checkbox"/>		400		I.F. E.H. (F.H.)			
Alkalinity, Mud (Pm)		40		GRADE DRILL PIPE PLASTIC COATED <input type="checkbox"/> YES <input type="checkbox"/> NO			
Alkalinity, Filtrate (Pf/Mf)		TR		CORROSION TEST REPORT			
Iron <input type="checkbox"/> ppm Chloride <input type="checkbox"/> ppm		2.4		COUPON CORROSION RATE APPROX 1.4 * lb./ft.²/yr.			
Calcium <input checked="" type="checkbox"/> ppm <input type="checkbox"/> Gyp (ppb)		97.6		TYPE DEGREE			
Sand Content (% by Vol.)		-		Fe S CO ₂ MECHANICAL DAMAGE <input type="checkbox"/> GENERAL <input type="checkbox"/> LOW <input checked="" type="checkbox"/>			
Water Content (% by Vol.)		-		+ - + - SCALE TR <input checked="" type="checkbox"/> LIGHT <input type="checkbox"/> MODERATE <input type="checkbox"/>			
Methylene Blue Capacity <input type="checkbox"/> (ml/ml mud) (equiv. #/bbl. bent.)		-		<input type="checkbox"/> PITTING <input type="checkbox"/> RATHER HIGH <input type="checkbox"/>			
Sulfides <input type="checkbox"/> ppm Phosphate <input type="checkbox"/> ppm		-		<input type="checkbox"/> LOCALIZED <input checked="" type="checkbox"/> SEVERE <input type="checkbox"/>			
Sulfite Residual <input type="checkbox"/> ppm		-		BY BOB PERKINS			

REMARKS—Give operation depth and nature of any problems encountered		MUD TREATMENT:	
<input type="checkbox"/> Drilling @ 138.9280 g		GEL, CAUSTIC, TANNATHIN	
<input type="checkbox"/> Salt Water flow @ 137.7841 g			
<input type="checkbox"/> Gas kick @ 1.1439 x 207 = 1.7 *			
<input type="checkbox"/> Stuck pipe @ 136 hrs.		* AT LEAST 20% OF THE WEIGHT LOSS WAS DUE TO EROSION BY MUD SOLIDS. THE ACTUAL CORROSION RATE WAS APPROX. 1.4 lb/ft²/yr. OR LESS.	
<input type="checkbox"/> Tight hole @			
<input type="checkbox"/> Sloughing Shale @			
<input type="checkbox"/> Lost Returns @			
ENGINEER RALPH BOWIE		PHONE	
ADDRESS			

PRINTED IN U.S.A.

THIS REPORT IS SUBJECT TO THE TERMS AND CONDITIONS AS SET FORTH ON THE REVERSE SIDE



CHILLING FLUID SERVICES

OILFIELD PRODUCTS GROUP - DRESSER INDUSTRIES INC.

**COMPOSITE
CORROSION RING REPORT**
TITE HOLE YES NO

C. O. S. I. O. D. U. P. BOX HO. I. V. T. 770
 FIELD CORROSION LAB. CITY

PM-1017

NUMBER

Page

OPERATOR UNION OIL CO. OF CALIFORNIA			SURVEY SEC. 33 T 25 S. R 6 W		SURFACE CASING SIZE 20" DEPTH 280'		BIT SIZE											
WELL C.F.S.U. 31-33			FIELD WILDCAT		INTERMEDIATE CASING SIZE 13 3/8"		DEPTH 1735'											
CONTRACTOR LOFFLAND BROS. - RIG #5			COUNTY MILLARD															
ENGINEER RALPH BOWIE			STATE UTAH															
COUPON NUMBER	DEPTH INSTALL REMOVE	DATE	WEIGHT	FUNNEL VISCOSITY	PV	YP	GELS	PH	A.P.I. F.L. (CC)	PI/MF	Cl PPM.	Ca PPM.	SO ₃ PPM	ppm	NO. DAYS	LB./FT. ² YR.	PLASTIC COATED <input type="checkbox"/> YES <input type="checkbox"/> NO	
																	MUD TREATMENT	
19341	280	6-1													5 1/2	1.4	TR. CO ₃ (X-O SUB) GEL, CAUSTIC, TANNATHIN	
	1241	6-7	8.6	34	8	1	2	3	11.5	16.0	6/9	400	40				TR. CO ₃ (X-O SUB)	
479	1734	6-25	8.5	30	3	3	3	5	12.5	55.0	19/23	650	440		2	0.2		
	2019	6-27	8.6	31	5	3	2	9	11.3	33.0	8/13	700	440					
708	2941	7-3	AERIATED		WATER			11.7	MECH. DAMAGE - ACTUAL					2	42.78	(X-O) SCALES: CaCO ₃ , IRON CARBONATE, MAGNETITE		
	3728	7-5						10.7	RATE > 30 LB/FT ² /YR.									
1768	3728	7-5	AERIATED		WATER			10.7							2 1/2	8.01	(X-O) SCALE - SAME AS #708	
	4570	7-8						11.7		15/19	5250	440						
19326	3728	7-5	AERIATED		WATER			10.7							2 1/2	8.42	(TOP X-O SUB) SAME SCALES	
	4540	7-8						11.7		15/19	5250	440						
470	4540	7-8	AERIATED		WATER			11.7		15/19	5250	440			2 1/2	8.01	(X-O) IRON CARBONATE, MAGNETITE, FeS.	
	4828	7-11						11.0										
1767	4828	7-11						11.0							2 1/2	7.48	(X-O)	
	5009	7-13						11.0										

DATE SPUD: 5-24-78 DATE T.D.: 7-18-78 B.H.T.



CORROSION REPORT

DATE 6-21-78 CORROSION REPORT NO F-14510

Form with fields for Union Oil of California, Magco Bar Division, Field Corrosion Lab, Loffland Rig 5, C.F.S.U. 31-33, and contact information for Harold Moss, Steve Pye, Dee Thomas, Jim Fox, Tom Cox, Bernie Sansing, and Ralph Bowie.

THIS WILL CONFIRM THE CONVERSATION CONCERNING THE CORROSION RING(S) FROM THE SUBJECT WELL:

COUPON NUMBER 19341 PULLED AT A DEPTH OF 1241 FT. SHOWED A CORROSION RATE OF Approx 1.4 LB/FT²/YR. trace CARBONATE positive SULFIDE.

COUPON NUMBER PULLED AT A DEPTH OF FT. SHOWED A CORROSION RATE OF LB/FT²/YR. CARBONATE SULFIDE.

COUPON NUMBER PULLED AT A DEPTH OF FT. SHOWED A CORROSION RATE OF LB/FT²/YR. CARBONATE SULFIDE.

The measured corrosion rate on this ring was 1.7; however, at least 20% of the weight loss was due to mechanical erosion by mud solids, giving a true corrosion rate of about 1.4 lb/ft²/yr. H2S was encountered two days before this ring was pulled. Zinc carbonate has been used to treat for H2S during drilling since that time.

Table with conversion rates between various units for steel coupons (specific gravity 7.86): mpy = 24.62 x lb/ft²/yr, mpy = 5.03 x kg/m²/yr, lb/ft²/yr = 0.04 x mpy, lb/ft²/yr = 0.20 x kg/m²/yr, kg/m²/yr = 0.20 x mpy, kg/m²/yr = 4.90 x lb/ft²/yr

PLEASE CONTACT THE OPERATOR AND CONTRACTOR CONCERNING THIS REPORT.

Signature block for Bob Perkins, Sales Engineer, Area Code 801, Phone Number 262-9954.

- DISTRIBUTION: 1 - AREA ENGINEER, 2 - FILE, 3 - ENG. MANAGER, 4 - ENGINEER, 5 - FIELD, 6 - FILE, 7 - EXTRA COPY



CORROSION REPORT

DATE _____ CORROSION REPORT NO. **F-14516**

1-079-2		FROM	
Union Oil Co.		MAGCOBAR DIVISION	
		FIELD CORROSION LAB:	
		PO BOX 1020 Atherton Dr., Suite C-201	
(Loffland Rig 5)		CITY, STATE AND ZIP CODE	
SUBJECT WELL		Salt Lake City, Utah 84107	
C.F.S.U. 31-33		NUMBER	AREA
COPY TO		Salt Lake	
Harold Moss Steve Pye		COPY TO	
COPY TO		Dee Thomas Jim Fox Tom Cox	
Bennet Smith Ralph Bowie		COPY TO	
		Art Vincnet Dee Slaugh Bob Perkins	

THIS WILL CONFIRM THE CONVERSATION CONCERNING THE CORROSION RING(S) FROM THE SUBJECT WELL:

COUPON NUMBER 479 PULLED AT A DEPTH OF 2019 pulled 6-27-78
 FT. SHOWED A CORROSION RATE OF
0.2 LB/FT²/YR. trace CARBONATE negative SULFIDE.

COUPON NUMBER 708 PULLED AT A DEPTH OF 3728 pulled 7-5-78
 FT. SHOWED A CORROSION RATE OF
42.78 LB/FT²/YR. positive CARBONATE negative SULFIDE.

COUPON NUMBER 1768 PULLED AT A DEPTH OF 4570 FT. SHOWED A CORROSION RATE OF
8.01 LB/FT²/YR. positive CARBONATE negative SULFIDE.

Ring #708 was run after switching to air drilling with water injection. Ammonia, caustic, and Unisteam were used for corrosion control during this interval. Some of the weight loss on ring #708 was due to mechanical damage. The actual corrosion rate was estimated to be something over 30 lb/ft²/yr. During the run of ring #1768, sodium nitrite and caustic were used for corrosion control. Both #708 and #1768 were scaled with calcium carbonate, iron carbonate, and Magnetite.

Following are the conversion rates between the various units for steel coupons (specific gravity 7.86):

mpy = 24.62 x lb/ft²/yr
 mpy = 5.03 x kg/m²/yr
 lb/ft²/yr = 0.04 x mpy
 lb/ft²/yr = 0.20 x kg/m²/yr
 kg/m²/yr = 0.20 x mpy
 kg/m²/yr = 4.90 x lb/ft²/yr

PLEASE CONTACT THE OPERATOR AND CONTRACTOR CONCERNING THIS REPORT.

PREPARED BY	TITLE	AREA CODE	PHONE NUMBER
<i>Bob Perkins</i>	Sales Engineer	801	262-9954

- DISTRIBUTION:
- 1 - AREA ENGINEER
 - 2 - FILE
 - 3 - ENG. MANAGER
 - 4 - ENGINEER
 - 5 - FIELD
 - 6 - FILE
 - 7 - EXTRA COPY



CORROSION REPORT

DATE _____ CORROSION REPORT NO. **F-14536**

M-979-2		5	
Union Oil Co.		FROM MAGCOBAR DIVISION	
		FIELD CORROSION LAB:	
		XXXXXXXX 1020 Atherton Dr., Suite C-201	
(Loffland Rig 5)		CITY, STATE AND ZIP CODE Salt Lake City, Utah 84107	
SUBJECT WELL C.F.S.U. 31-33		NUMBER	AREA Salt Lake
COPY TO Harold Moss Steve Pye		COPY TO Dee Thomas Jim Fox Tom Cox	
COPY TO Bennet Smith Ralph Bowie		COPY TO Art Vincent Dee Slaugh Bob Perkins	

THIS WILL CONFIRM THE CONVERSATION CONCERNING THE CORROSION RING(S) FROM THE SUBJECT WELL.

COUPON NUMBER 19326 PULLED AT A DEPTH OF 4540 pulled 7-8-78
8.42 LB/FT²/YR. positive CARBONATE negative SULFIDE. FT. SHOWED A CORROSION RATE OF


COUPON NUMBER 470 PULLED AT A DEPTH OF 4828 pulled 7-11-78
8.01 LB/FT²/YR. positive CARBONATE positive SULFIDE. FT. SHOWED A CORROSION RATE OF

COUPON NUMBER 1767 PULLED AT A DEPTH OF 5009 pulled 7-13-78
7.48 LB/FT²/YR. positive CARBONATE negative SULFIDE. FT. SHOWED A CORROSION RATE OF

Rings #19326 and #1767 were scaled with Iron Carbonate, Calcium Carbonate, and Magnetite. #470 had small amounts of FeS on its surface - an indication of H₂S in the system. #470 was also scaled with Iron Carbonate and Magnetite.

Following are the conversion rates between the various units for steel coupons (specific gravity 7.86):
 mpy = 24.62 × lb/ft²/yr
 mpy = 5.03 × kg/m²/yr
 lb/ft²/yr = 0.04 × mpy
 lb/ft²/yr = 0.20 × kg/m²/yr
 kg/m²/yr = 0.20 × mpy
 kg/m²/yr = 4.90 × lb/ft²/yr

PLEASE CONTACT THE OPERATOR AND CONTRACTOR CONCERNING THIS REPORT.

SIGNED 	TITLE Sales Engineer	AREA CODE 801	PHONE NUMBER 262-9954
---	-------------------------	------------------	--------------------------

- DISTRIBUTION:
- 1 - AREA ENGINEER
 - 2 - FILE
 - 3 - ENG. MANAGER
 - 4 - ENGINEER
 - 5 - FIELD
 - 6 - FILE
 - 7 - EXTRA COPY

D. S. Pye



To: Mr. G. W. Hendricks
Mr. D. L. Ash
From: D. S. Pye
W. C. Allen

Memo: E&PP 78-110M

Date: August 29, 1978

Division: Exploration & Production Research

Project: 638-18810
638-67226

Subject: CORROSION CONTROL ON CFSU #31-33,
LABORATORY TESTS AND FIELD RESULTS

Supervisor: R. F. Krueger

cc: Library (2)
Patent

Carl Cron
M. M. Ellis
R. O. Engebretsen
P. W. Fischer
D. E. Pyle

During the drilling of CFSU #42-7, corrosion was recognized as a severe problem during aerated water drilling, and various chemical methods of inhibition were attempted. Unfortunately, the problem did not respond to any of the treatments, and the drill pipe was severely damaged. During the time lapse between the completion of CFSU #42-7 and the drilling of CFSU #31-33, various methods of corrosion control were studied in the laboratory, and the most practical method was selected for use during the drilling of CFSU #31-33. This report summarizes the laboratory studies and the field test in CFSU #31-33.

CORROSION WAS REDUCED, BUT NOT CONTROLLED
WITH SODIUM NITRITE (NaNO₂) AND CAUSTIC
- DEVELOPMENT OF AN INERT GAS SYSTEM IS RECOMMENDED

Our laboratory studies showed that using sodium nitrite (NaNO₂) and maintaining a high pH with caustic was the most cost effective of the corrosion control methods that would be available by the time well CFSU #31-33 was drilled. This method effectively reduced the corrosion rate while drilling this well from 43 lbs/ft²/yr (obtained with a standard inhibitor system) to 8 lbs/ft²/yr. However, this corrosion rate is still unacceptably high (allowable rates are 2#/ft²/yr), especially since this oxygen corrosion problem forms pits which accelerate drill

pipe damage far beyond what would occur if the corrosion occurred uniformly. Consequently, 33 joints of drill pipe were downgraded at the end of this well due to corrosion pits, even though we spent over \$68,000 on chemicals to control this corrosion. However, we have estimated that 120 joints would have been downgraded, and fishing jobs would have resulted* had we allowed the corrosion to continue at the 43 lb/ft²/yr rate.

There are a number of possible explanations for the higher corrosion rates and the drill pipe loss. They are listed below from the most probable cause to the least probable cause:

- 1) Loss of pH in the return fluid due to CO₂ stripping, formation water dilution, and reaction with drill cuttings.
- 2) Reduced inhibitor effectiveness caused by both the concentration and type of dissolved solids in the drilling fluid.
- 3) Inability to maintain the desired pH and NaNO₂ concentrations 100% of the time due to occasional system upsets.

Since 1 and 2 are not usually controllable in a drilling operation, we will be unable to economically control corrosion with chemical inhibitors in many cases, and we will not be able to predict ahead of time when or if corrosion can be controlled.

Consequently, we believe that a more universally usable system should be developed. The one that appears most economically feasible at this time is the use of combustion gas, and we recommend that a commercial system be developed and tested as soon as possible.

CHEMICAL TREATMENT FOR OXYGEN CORROSION DURING THE AERATED DRILLING OF CFSU WELL #31-33

Well CFSU #31-33 was drilled without using air assist down to 2019 feet, and air assist was initiated at this point. The initial corrosion control program consisted of maintaining a pH at the suction in excess of 11, and injecting approximately 2000 ppm of Unisteam (a proprietary corrosion inhibitor) and 2000 ppm of concentrated NH₄OH. This was a program which had been used successfully in another area, and we wanted to utilize this method until the corrosion rates justified converting to the sodium nitrite (NaNO₂) method which would be much more costly.

The corrosion ring data for the aerated portion of this well is summarized in TABLE 1. The portion of the hole from 2019 to 3728 used the Unisteam, NH₄OH, caustic system. Corrosion was fairly well controlled by this system from 2019 to 2920, but went completely out of control in the interval from 2941 to 3728. The sodium nitrite program was instituted at 3728, and markedly reduced the corrosion rates (from 43 to 8#/ft²/yr). However, the corrosion rates (8#/ft²/yr) were still well above the acceptable limit of 2#/ft²/yr.

* Besides our own calculations presented in this memorandum, a similar opinion was reached by the drilling contractor¹.

POSSIBLE REASONS WHY THE CORROSION RATE
DID NOT REACH ACCEPTABLE LEVELS

There are two possible reasons why the corrosion rates were not reduced to acceptable levels:

1. Upset conditions which allowed the concentrations of NaNO_2 and/or pH to drop below the critical level part of the time.
2. Differences between the chemical composition of the drill water in CFSU #31-33 and the test solutions used in the laboratory. The differences made the corrosion problem more severe in CFSU #31-33.

TABLES 2 and 3 list data from monitoring and chemical analyses of the drilling fluid during drilling.

Although we did not have a continuous monitor of NaNO_2 concentration, estimates made from TABLE 2 would indicate that the NaNO_2 concentration at the suction line was below 1.5 lbs/bbl, 7% of the time during bit run 1 (7/5-7/8) and 0% of the time during bit run 2 (7/8-7/11). We did have a continuous monitor on pH, which indicated the pH at the suction was below 10.0, 2% of the time during bit run one and 6% of the time during bit run 2. The return pH was below 10, 100% of the time, and the return NaNO_2 concentrations were below 1.5, 50% of the time during bit run 1 and 0% of the time during bit run 2. Although having the concentrations below the desired amounts part of the time may be partly responsible for the higher corrosion rates, the large quantities of totally dissolved solids (TDS) and chloride ion (Cl^-) content were more likely candidates. As shown in TABLE 3, the TDS was as high as 10,000 ppm. A total analysis was not made as frequently as Cl^- analysis, and TABLE 2 shows a maximum Cl^- concentration of 5500 ppm. This was considerably higher than the concentrations in CFSU #42-7 which reached a maximum TDS of 9,400 ppm and Cl^- concentration of 2450 ppm.

Since the literature indicates^{2,3} that an increase in Cl^- is one of the primary problems in controlling oxygen corrosion, we increased the NaNO_2 concentration, but without knowing how high we should go to achieve control. From the corrosion rates observed, one might conclude that we did not go high enough, or that NaNO_2 will not be able to control the corrosion in the presence of the dissolved salts encountered in the drill water in CFSU #31-33.

One of the major problems in controlling the corrosion was the inability to control or maintain a high pH in the returning fluid as shown in TABLE 2. Although we were able to obtain reasonable concentrations of NaNO_2 in the return fluid, the pH was always below that required for adequate inhibition. There are a number of probable causes for this pH reduction.

- 1) dilution with formation water
- 2) reaction with drill cuttings

3) reaction with gas (primarily CO₂) produced from the well.

Based on the observed reductions in NaNO₂ concentrations, dilution with formation waters would not be adequate to explain the pH reductions encountered, but it is undoubtedly responsible for part of it. Reaction with the drill cuttings is an unknown. Reaction with CO₂ is a definite possibility since the produced CO₂ concentrations were high, but both the CO₂ effect and the reactions with the cuttings are difficult to quantify.

From these data (TABLE 2), we know the pH in the return fluid was always below that required for inhibition at the surface, and was almost always high enough to achieve inhibition at the bit (since no loss in pH should occur going down the drill pipe). What we don't know is the pH profile in the annulus, and where the pH dropped below the critical point. Consequently, we don't know how severe the corrosion problem was on the outside of the drill pipe, because our coupon measurements were all made on the inside of the drill pipe where the pH is controlled. As will be seen in the next section, the damage to the drill pipe exceeded that which would be expected from the average metal loss determined from the coupons, and an increase in exterior corrosion due to low pH would be one of two plausible explanations for this difference. The other explanation involves the difference between an average metal loss (uniform over the surface area as calculated from the coupons) compared to the metal loss being concentrated over a smaller pitted area. Pitting is characteristic of oxygen corrosion.

DRILL PIPE LOSS AND ECONOMICS

At the end of this well, 33 joints of pipe were downgraded due to pitting caused by corrosion (TABLE 4). We estimated that 120 joints would probably have been lost if the NaNO₂ inhibitor procedure had not been used. Since approximately \$68,000 in chemicals were used in this corrosion control attempt, the cost is about at the break-even point compared to purchasing drill pipe. However, the damage would have been so severe on some of the drill pipe (2 joints went to junk as it is) that failures of the drill string (fishing jobs) probably would have occurred, along with damage to the casing. Because of the possibility of fishing jobs and casing damage, the corrosion control costs were economic, but large increases in chemical costs beyond what was spent on this well would probably not be justified.

ESTIMATING DRILL PIPE LOSS FROM COUPON RESULTS, AND A COMPARISON TO ACTUAL DRILL PIPE DAMAGE ENCOUNTERED

TABLE 5 shows the number of joints that would experience a given thickness reduction, both for the present well CFSU #31-33 and the last well CFSU #42-7.

TABLE 4 shows the amounts of drill pipe that were downgraded for each well.

Comparing TABLE 4 and TABLE 5, drill pipe was downgraded when the average metal loss exceeded about 9 mils in CFSU #42-7, and 12 mils in CFSU #31-33. When drill pipe is downgraded, on the basis of pitting, the transition between premium and grade II is specified as approximately a 70 mil loss from nominal thickness, the transition between grade II and grade III occurs with approximately a 120 mil loss from nominal thickness and the transition from grade III to junk occurs with approximately a 155 mil loss from nominal thickness. Since the drill pipe was downgraded at an average loss between 10 and 12 mils, either the pitting was very severe, or the coupons do not accurately reflect the corrosion rate on the exterior of the pipe. What has actually occurred is probably a combination of both explanations, but oxygen corrosion is a pitting type corrosion, and it would not be unreasonable to expect that the majority of the average metal loss was actually occurring over only 15% of the surface area, which would explain the amount of drill pipe lost when only a 10 to 15 mils average metal loss occurred.

One final uncertainty should be noted from TABLE 1. The corrosion rates based on air time decreased significantly when NaNO_2 was introduced, but climbed when the air time/total time was reduced. This indicates there are other factors contributing to corrosion besides oxygen, and that some corrosion rate exists ($2-4\#/ft^2/yr$) even with no oxygen present. This assumes that no oxygen was present when air was not injected, because an oxygen scavenger was used during these times. However, these rates may also be due to an inefficiency in the oxygen scavenger, as we didn't measure residual oxygen contents, and there may still have been residual oxygen present.

THE CORROSION PROBLEM INCREASES IN SEVERITY WHEN AERATED WATER IS USED AS THE DRILLING FLUID

Oxygen corrosion is a problem in almost all drilling operations. Normally the oxygen is present in only small quantities due to oxygen in the air dissolving in the drilling fluid at ambient conditions, and corrosion is normally curtailed by removing the oxygen from the drilling fluid by either chemical or mechanical means.

When well conditions dictate that air be injected with the drilling fluid, then oxygen is present in solution in large quantities due to the increased solubilities of oxygen at the elevated pressures that exist downhole. Neither chemical nor mechanical removal systems are operable under these circumstances, and inhibitors must be used. An inhibitor in this case is defined as a chemical which prevents the oxygen from reaching or reacting with the surface of the pipe, but does not remove the oxygen from the drilling fluid.

CORROSION CONTROL OPTIONS THAT WERE CONSIDERED, AND THE LABORATORY TESTING OF PROMISING SOLUTIONS

Numerous methods of controlling corrosion were considered. Candidates were rejected based on:

- 1) Cost - when the cost exceeded the replacement cost of the drill pipe, the method was considered uneconomic.

- 2) Availability - the method had to be operational for the drilling of CFSU #31-33.
- 3) Ease of Use - The method had to be safe as far as personnel hazards and the environment.
- 4) Wide Range Tolerance - Since the conditions (temperature, pressure, chemical composition of the water, etc.) were expected to vary widely, the method should not be overly sensitive to these changes.

Non-Oxygen Containing Gases

One certain way of preventing oxygen corrosion is to use a non-oxygen containing gas to replace air as the gas phase in the drilling system. Three candidates were considered: natural gas, nitrogen, and combustion gas.

Natural gas was discarded because:

1. It is not readily available.
2. It represents a potential personnel hazard.
3. It is costly.

Nitrogen was discarded because:

1. Its cost would exceed the value of the drill pipe.
2. It was marginal whether an adequate continuous supply of the required volume could be maintained.

This left combustion gas. Combustion gas is readily available from the diesel engines on the rig (no cost), and it is not hazardous to handle. However, it does contain oxides of carbon, sulfur and nitrogen, residual hydrocarbons and unreacted oxygen. Therefore, it requires treatment to make it a truly non-oxygen containing gas. It also requires treatment before it can become a tolerable charging gas for compressors. (The gas used in these drilling systems must be compressed up to 800 psi in order to be injected into the drilling fluid.) The effect of the acid gas components must be negated, or they will cause mechanical problems with the compressors. Although the technology for this system is theoretically available, no such system now exists, and there was no way to build an operating system within the allowable time frame.

Consequently, we were again forced to rely on chemical inhibition for corrosion control.

Chemical Corrosion Inhibitors

TABLE 6 summarizes the results of our laboratory inhibitor studies. Since we are not reproducing the field system in the laboratory, these corrosion rates should be compared relatively and not assumed to be the exact rates we would expect to find in the field. There are a number of interesting observations which can be made from these data.

First, the concentrations required to achieve inhibition are many orders of magnitude above the concentrations the literature indicates is applicable. However, the drilling fluid used in these tests was simulated from an analysis of the waters present in CFSU #42-7, and these waters contain dissolved solids, including chloride salts. The literature does show that inhibitor effectiveness is reduced, and concentrations must be raised when chlorides are present, but the concentrations found in the literature are still well below those we found required in our test work.

Consequently, we can conclude that none of the chemical inhibitors will pass our fourth criteria, wide range tolerance, because they are sensitive to drilling water composition which we know will fluctuate from past experience. However, since use of chemical inhibitors is the only viable method at this time, we designed the concentrations to provide inhibition under the worst conditions encountered in CFSU #42-7. Unfortunately, this turned out to cause problems, because the conditions in CFSU #31-33 were more severe than the worst conditions in CFSU #42-7.

Sodium nitrite was selected as the inhibitor for the field test, based on the data in TABLE 6. This conclusion is also supported by data that Dresser Industries obtained for us in their test system which is entirely different⁴.

Of the other candidates:

- 1) Amines were eliminated because they were not effective at practical concentration levels.
- 2) Chromates were eliminated because they create environmental problems, and they are not cost effective compared to nitrites.
- 3) Caustic (high pH) was eliminated because it causes personnel hazards. At pH levels exceeding 13, chemical burns will result from even short duration skin contact.
- 4) Silicates were eliminated because:
 - a) they resulted in an increase in the corrosion when an under-treated condition existed
 - b) very high concentrations were required
 - c) they are difficult to handle
 - d) they may cause unknown precipitation problems.

LABORATORY TESTS ON SODIUM NITRITE (NaNO_2).

Once NaNO_2 was selected as candidate inhibitor, more extensive tests were conducted to define the important parameters which control its effectiveness. Unfortunately, there was insufficient time to do all the desired test work prior to drilling CFSU #31-33. The important parameters are:

- 1) The composition of the drilling fluid, which was set at the worst conditions encountered in CFSU #42-7 for these tests.
- 2) The concentration of the NO_2^- ion.
- 3) The pH of the drilling fluid (the OH^- ion concentration).

TABLE 6 and FIGURE 1 show the results of the data we accumulated on NO_2^- concentration and pH. These indicate that a minimum specification would be a concentration of 1.5 #/bbl NaNO_2 and a pH of 10.0.

However, due to the shape of the corrosion rate versus concentration curves, an adequate margin of safety must be incorporated. The data show that the corrosion is either controlled, or proceeding at an extremely rapid rate. Since there will be concentration fluctuations due to system variations and upsets, the target concentration must be high enough to allow the fluctuations to occur without the minimum concentrations falling below the crucial level. Consequently, the initial target concentrations were set at 2.6 lbs/bbl NaNO_2 and 11.5 pH.

More testing is needed and should be done before nitrite is used as an inhibitor again. The concentrations of the dissolved solids, NO_2^- , and OH^- are all interrelated. We should develop a ternary diagram defining the concentrations of OH^- and NO_2^- which result in effective inhibition in drilling fluids with various dissolved solids contents. We currently only have sufficient data to define one point on this curve.

REFERENCES

1. Letter from H. E. Mallory of Loffland Brothers Company, Tulsa, Oklahoma to Stephen Pye, Union Oil Company, Brea, California, dated August 21, 1978.
2. M. J. Pryor and M. Cohen, "The Inhibition of the Corrosion of Iron by Some Anodic Inhibitors", Jo. of the Electrochemical Society, Vol. 100, No. 5, 205 (1953).
3. O. L. Riggs, Jr., J. D. Sudbury and Merle Hutchison, "Effect of pH on Oxygen Corrosion at Elevated Pressures", Corrosion-National Association of Corrosion Engineers, Vol. 16, 94 (June 1960).
4. Letter from Tom Cox of Dresser Industries, Houston, Texas to Stephen Pye, Union Oil Company, Brea, California, dated June 21, 1978.






TABLE 1
CORROSION COUPON TEST RESULTS

Coupon Number	In		Out		Depth in	Depth out	Original Weight grams	Final Weight, grams	Total Hours	Corrosion Rate, lb/sq.ft./yr	Remarks	Time Spent Drilling (including connections)		Trip	Other	Corrosion Rate Based on Air Injection Time
	Date	Time	Date	Time								with air	without air			
19351	6/28	2200	7/1	2000	2019	2920	138.3556	136.8368	70	4.49	CaCO ₃ , FeCO ₃ magnitite light pitting	62.0	-	6	2	4.8
708	7/3	1030	7/5	1620	2941	3728	135.8783	123.9178	54.8	42.78	Mechanical damage Same scale	45.5	0	9.3	0	51.5
1768	7/5	1630	7/8	0800	3728	4540	133.2101	130.6132	63.5	8.02	Same scale	48	0	16	0	10.6
19326	7/5	1930	7/8	0800	3728	4540	137.6394	135.1797	60.5	8.42	Same scale	48	0	12.5	0	10.6
470	7/8	1300	7/11	0200	4540	4828	135.6897	133.1959	61	8.01	FeS, other scale the same	25 3/4	0	27	8 1/4	19.0
1767	7/11	0200	7/13	1600	4828	5009	133.6703	131.3051	62	7.48	Same scale	5	9	22	26	92.7
1771	7/14	1400	7/18	1000	5009	5221	134.2887	133.7432	92	1.16	CaCO ₃ --no air injection during this time, drill pipe pulled in casing during "other".	0	30	30.5	31.5	∞

TABLE 2

CHEMICAL MONITORING OF THE DRILLING FLUID

Date	Time	Depth	NaNO ₂ Concentration, pounds/barrel		pH		Cl ⁻ Concentration, ppm		Remarks
			Suction	Returns	Suction	Returns	Suction	Returns	
7/5	2100		3.6			12			
	2220		3.8						
	2230				11.8				
	2300		2.04		11.1				
	2330		2.82	1.08	11.2	7.8			
	2400		1.74	1.26	10.7	7.9			
7/6	0030		1.80	1.68	11.4	7.8			
	0100		2.28		11.4				
	0130		2.58	1.02	11.5	8.3			
	0200		2.82		11.4				
	0230		1.92	1.02	11.1	7.9			
	0300		2.52		11.3				
	0400		3.00		11.6				
	0430			2.04		7.8			
	0500		3.54		11.7				No returns.
	0600		2.10		11.8				
	0700		1.74		10.5				Tripping jet sub.
	1200		1.38	1.56	11.4	7.4			Intermittent returns.
	1300		3.24		11.0				
	1400		3.78		12.1				
	1500		1.98		11.8		1000		
	1550			1.92		8.1		2500	
	1600		3.6		11.7		600		
	1700		0.6		11.7				
	1800		2.91		11.5				
	1815								Started injecting ammonia
		1900		1.5		11.4			
		1915			1.38		8.1	1750	
		1940			0.96		7.6	2600	
		1950			1.20		7.7	3000	
		2005			1.05		7.8	3300	
		2015		2.16	1.05	11.0	7.9	2000	3500
		2100		1.80	0.75	10.0	7.4	2700	3800
	2130		2.4	1.26	11.2	8.0	3100	4600	
	2200		2.4	1.65	11.0	8.5	3400	4300	
	2300		2.1	1.20	11.1	8.1	3700	4800	
	2400	4073	2.25	1.35	10.9	7.4	3800	4600	
7/7	0100	4096	2.43	1.86	11.2	8.3	3300	3800	Two compressors on at 0145.
	0200	4107	3.00	2.40	11.5	10.4	3400	3500	
	0300	4125	2.85	1.65	10.6	8.6	3500	4000	
	0400	4136	2.70		11.0		3900		One compr. at 0400.
	0430	4148		1.35		8.2		4400	
	0500	4158	2.85	1.05	11.4	8.5	3800	4600	Two compressors at 0530.
	0600	4172	2.46	2.25	11.6	9.6	3600	4100	
	0700	4196	2.58	1.65	11.5	8.8	3900	4200	
	0800	4215	3.00	1.59	10.5	8.8	3900	4400	
	0900	4237	3.45	2.01	11.0	8.8	4150	4450	
	1000	4255	3.78	1.80	10.8	8.6	4200	4800	
	1100	4269	2.10	1.26	10.8	8.3	4500	5250	
	1200	4293	2.61	1.56	10.7	8.9	4500	5000	
	1300	4309	3.00	1.80	10.3	8.6	5000	4350	
	1400	4325	3.30	1.35	11.0	8.6	4500	5500	
	1500	4340	3.51	1.95	11.3	8.7	4340	4750	
	1600	4350	3.33	1.44	11.6	9.0	4450	4750	
	1700	4382	3.45	1.50	10.8	9.0	5200	5300	
	1800	4397	2.88	1.80	10.4	8.5	5000	5200	
	1900	4422	2.94	1.56	11.1	8.9	4900	5100	
	2000	4436	3.00	1.68	11.2	9.0	5000	5100	
	2100	4460	2.58	1.50	11.8	8.5	5400	5300	
	2200	4481	2.64	1.56	11.5	8.7	5300	5200	
2300	4491	2.25	1.20	12.4	8.6	5300	5100		
2400	4510	3.45	1.20	10.4	8.3	5000	5200		

TABLE 3

CHEMICAL ANALYSIS* OF RETURN FLUIDS FROM
CFSU WELL #31-33

Data are in milligrams/liter unless otherwise noted

Date	June 30	July 1	July 5	July 7	July 20
Depth, feet	2455	2825	3720	4170	3000
Turbidity, NTU	150	260	200	390	80
Conductivity, umhos/cm	11,700	11,780	12,300	15,380	2035
pH	8.77	7.38	7.94	9.79	7.44
TDS	7600	7655	8000	10,000	130
Alkalinity as CaCO ₃	836	394	210	1440	200
As	0.970	0.379	1.131	5.707	2.991
HCO ₃	888.1	480.6	256.2	658.8	244
Ba	0.07	0.29	0.16	0.47	0.15
B	0.15	0.30	0.25	0.50	0.20
Cd	0.004	0.006	0.007	0.045	0.040
Ca	5.60	200	62.4	14.4	74.4
CO ₃	64.8	<0.01	<0.01	540	<0.01
Cl	3440	3550	3410	3900	502
Cr	<0.001	<0.001	0.048	0.006	<0.001
Cu	0.065	0.049	0.077	0.166	0.914
Surfactants	<0.05	<0.05	<0.05	<0.05	<0.05
F	3.10	3.20	2.90	3.60	1.03
Li	12.05	12.46	11.62	13.31	1.164
Hardness as CaCO ₃	24.0	560	188	20.0	266
Fe	3.20	8.78	11.1	10.6	2.154
Pb	0.345	0.350	0.345	0.420	0.006
Mg	2.40	14.40	7.68	3.36	19.2
Mn	0.249	2.084	0.328	0.016	0.043
Hg	<0.0002	0.0002	<0.0002	0.0007	<0.0062
Ni	0.685	0.680	0.688	0.975	<0.001
NO ₂	0.04	0.03	0.02	<0.01	0.45
NO ₃	<0.01	<0.01	<0.01	<0.01	<0.01
K	423	452	465	443	56.2
Se	<0.001	<0.001	<0.001	0.007	<0.001
Si	77.5	25.5	64	79	
Ag	0.026	0.032	0.030	0.037	<0.001
SO ₄	272	720	1000	760	187
Na	2530	2475	2916	4000	355
Zn	0.084	0.231	0.051	0.41	0.104

* Analysis was made by Ford Laboratories,
Salt Lake City, Utah.

TABLE 4

DRILL PIPE LOSS

CFSU Well 31-33

238 joints were inspected

<u>Joints downgraded</u>	<u>Starting Grade</u>	<u>Ending Grade</u>
17	Premium	2
3	Premium	3
1	Premium	5
11	2	3
1	2	5
<u>33</u> Total		

CFSU Well 42-7

218 joints of premium pipe were inspected

<u>Joints downgraded</u>	<u>Starting Grade</u>	<u>Ending Grade</u>
82	Premium	2
28	Premium	3
7	Premium	5
<u>117</u> Total		

TABLE 5

NUMBER OF JOINTS EXPERIENCING A PARTICULAR
LOSS IN AVERAGE WALL THICKNESS AS CALCULATED
FROM THE CORROSION COUPON RESULTS

CFSU Well 31-33		CFSU Well 42-7	
Number of Joints	Thickness Lost, mils	Number of Joints	Thickness Lost, mils
33 ^a	0	33 ^a	0
7	0.3	4	
8	1.6	4	2.9
18	3.0	11	3.9
27	4.5	19	5.3
29 ^b	11.2	21	7.4
15 ^b	12.1	15	8.4
		14 ^b	9.4
		21	10.2
		22	12.1
		12	13.6
		11	14.8
		13	15.7
		21	16.8

a Calculation assumes the top 1000 feet of pipe suffered no metal loss, and that the remaining pipe suffered a loss equivalent to the loss measured by the corrosion coupons which were positioned at the top of the drill collar during the time that those joints of pipe were in the hole. The total number of joints of pipe in the hole at any time was assumed to be (average depth less 500 feet of drill collars and tools) ÷ 30. It was also assumed that no corrosion occurred on the pipe before air drilling was initiated, and that corrosion only occurred on the exterior of the pipe (the interior was plastic coated). If the internal coatings failed and there was corrosion on both surfaces, the average thickness lost would be twice that in the table.

b This is the approximate point where the number of joints that were down-graded (TABLE 4) would fall, between 11 and 12 mils on CFSU Well 31-33 and 8 and 9 mils on CFSU Well 42-7.

TABLE 6


CHEMICAL CORROSION INHIBITOR TESTS
IN THE LABORATORY


Compounds Used	Concentrations Used pounds/barrel	Corrosion Rate lb/sq.ft/yr	pH		
			Initial	Final	
Blank	--	19.2 20.8	9.8	9.8	
Unisteam ^R , Ammonium hydroxide, organic phosphonate	0.39, 0.39, 0.12, 3.9, 3.9, 1.2	22.3 5.5	11.5	8.8	
NaCrO ₄	0.7	7.4	9.7	8.7	
	1.24	1.1	9.7	9.6	
	1.75	0.8	9.6	9.2	
Caustic	Quantity of caustic required was not measured. Sufficient quantity was added to obtain the desired initial pH.	50.0 0.8 1.0 0.2	11.0 13.0 13.5 14.0	12.4 12.9 13.2 11.0	
	Na ₂ SO ₃	3.2	49.0	10.5	12.2
	Na ₂ SiO ₃ 37.6% active ³	4.8	36.8	10.4	10.1
		9.7	0.2		
NaNO ₂	0.35	22.1	10.5	10.9	
	1.1	4.6	10.5	9.9	
	1.1	11.5	10.5	10.6	
NaNO ₂ at different pH	1.75	31.9	8.0	12.4	
	1.75	24.6	8.5	11.0	
	1.75	10.9	9.0	10.1	
	1.75	10.0	9.5	10.3	
	1.75	0.4	10.0	9.7	
	1.75	0.4	10.5	9.8	
	1.75	0.6	11.5	10.8	
NaNO ₂ , NH ₄ OH	1.75, 3.5	0.3	10.5	10.1	
NaNO ₂ , Na ₂ SO ₃	1.75, 0.35	0.3	10.5	9.2	
NaNO ₂ , Na ₂ SO ₃ , organic phosphonate	1.75, 0.35, 1.2	0.3	10.5	9.1	
NaNO ₂ , Na ₂ SO ₃ , organic phosphonate, NH ₄ OH	1.75, 0.35, 1.2, 3.5	0.5	10.5	10.1	
NaNO ₂	2.6	0.4	10.5	9.8	
	3.5	0.2	10.5	9.5*	
	3.5	0.1	10.5	11.0	

* This test was run for 64 hours.

Tests were conducted at 600-700 psig oxygen pressure at 450°F for 24 hours. The test solutions consisted of a synthetic produced water from CFSU 42-7 plus the added compounds. Coupons of J-55 were placed in the solutions inside Teflon^R bottles, and the coupons were used to determine the corrosion rates.

FIGURE 1
CORROSION RATE VERSUS NaNO_2 CONCENTRATION AND pH





Ford Chemical LABORATORY, INC.

Bacteriological and Chemical Analysis

40 WEST LOUISE AVENUE

SALT LAKE CITY, UTAH 84115

PHONE 485-5761

Don Ash

Date: August 10, 1978

Name Union Oil Co. of California

Address P.O. Box 6854

Santa Rosa, Ca. 95401


CERTIFICATE OF ANALYSIS

78-1803-1

CFSU 31-33, 6-30-78, 2455 ft., received 7-11-78


Analysis started on:

Turbidity	<u>150.0</u> NTU	Total Hardness as CaCO ₃	<u>24.0</u> mg/l
Conductivity	<u>11,700</u> umhos/cm	Iron as Fe (Total)	<u>3.200</u> mg/l
pH	<u>8.77</u> Units	Iron as Fe (Filtered)	<u>0.347</u> mg/l
Total Dissolved Solids at 180°C.	<u>7,600</u> mg/l	Lead as Pb	<u>0.345</u> mg/l
Alkalinity as CaCO ₃	<u>836.0</u> mg/l	Magnesium as Mg	<u>2.40</u> mg/l
Arsenic as As	<u>0.970</u> mg/l	Manganese as Mn	<u>0.249</u> mg/l
Bicarbonate as HCO ₃	<u>888.16</u> mg/l	Mercury as Hg	<u><0.0002</u> mg/l
Barium as Ba	<u>0.07</u> mg/l	Nickel as Ni	<u>0.685</u> mg/l
Boron as B	<u>0.15</u> mg/l	Nitrate as NO ₃ -N	<u>0.04</u> mg/l
Cadmium as Cd	<u>0.004</u> mg/l	Nitrite as NO ₂ -N	<u><0.01</u> mg/l
Calcium as Ca	<u>5.60</u> mg/l	Potassium as K	<u>423.0</u> mg/l
Carbonate as CO ₃	<u>64.8</u> mg/l	Selenium as Se	<u><0.001</u> mg/l
Chloride as Cl	<u>3,440</u> mg/l	Silica as SiO ₂	<u>77.50</u> mg/l
Chromium as Cr (Total)	<u><0.001</u> mg/l	Silver as Ag	<u>0.026</u> mg/l
Chromium as Cr (Hex)	<u><0.001</u> mg/l	Sulfate as SO ₄	<u>272.0</u> mg/l
Copper as Cu	<u>0.065</u> mg/l	Sodium as Na	<u>2,530</u> mg/l
Surfactants MBAS	<u><0.05</u> mg/l	Zinc as Zn	<u>0.084</u> mg/l
Fluoride as F	<u>3.10</u> mg/l		
Lithium as Li	<u>12.05</u> mg/l		


Ford Chemical Laboratory, Inc.

All reports are submitted as the confidential property of clients. Authorization for publication of our reports, conclusions, or extracts from or regarding them, is reserved pending our written approval as a mutual protection to clients, the public and ourselves.

1 liter = .966 kg



Ford Chemical LABORATORY, INC.

Bacteriological and Chemical Analysis

40 WEST LOUISE AVENUE
SALT LAKE CITY, UTAH 84115
PHONE 485-5761

Don Ash

Name Union Oil Co. of California

Date: August 10, 1978

Address P.O. Box 6854

Santa Rosa, Ca. 95401

CERTIFICATE OF ANALYSIS
78-1803-2


CFSU 31-33, 7-1-78, 2825 ft., received 7-11-78

Analysis started on:

Turbidity	260.0 NTU	Total Hardness as CaCO ₃	560.0 mg/l
Conductivity	11,780 umhos/cm	Iron as Fe (Total)	8.786 mg/l
pH	7.38 Units	Iron as Fe (Filtered)	1.920 mg/l
Total Dissolved Solids at 180°C.	7,655 mg/l	Lead as Pb	0.350 mg/l
Alkalinity as CaCO ₃	394.0 mg/l	Magnesium as Mg	14.40 mg/l
Arsenic as As	0.379 mg/l	Manganese as Mn	2.084 mg/l
Bicarbonate as HCO ₃	480.68 mg/l	Mercury as Hg	<0.0002 mg/l
Barium as Ba	0.29 mg/l	Nickel as Ni	0.680 mg/l
Boron as B	0.30 mg/l	Nitrate as NO ₃ -N	0.03 mg/l
Cadmium as Cd	0.006 mg/l	Nitrite as NO ₂ -N	<0.01 mg/l
Calcium as Ca	200.0 mg/l	Potassium as K	452.0 mg/l
Carbonate as CO ₃	<0.01 mg/l	Selenium as Se	<0.001 mg/l
Chloride as Cl	3,550 mg/l	Silica as SiO ₂	25.50 mg/l
Chromium as Cr (Total)	<0.001 mg/l	Silver as Ag	0.032 mg/l
Chromium as Cr (Hex)	<0.001 mg/l	Sulfate as SO ₄	720.0 mg/l
Copper as Cu	0.049 mg/l	Sodium as Na	2,475 mg/l
Surfactants MBAS	<0.05 mg/l	Zinc as Zn	0.231 mg/l
Fluoride as F	3.20 mg/l		
Lithium as Li	12.46 mg/l		


Ford Chemical Laboratory, Inc.

All reports are submitted as the confidential property of clients. Authorization for publication of our reports, conclusions, or extracts from or regarding them, is reserved pending our written approval as a mutual protection to clients, the public and ourselves.



Ford Chemical

LABORATORY, INC.

Bacteriological and Chemical Analysis

40 WEST LOUISE AVENUE
SALT LAKE CITY, UTAH 84115
PHONE 485-5761

Don Ash

Date: August 10, 1978

Name Union Oil Co. of California

Address P.O. Box 6854


Santa Rosa, Ca. 95401

CERTIFICATE OF ANALYSIS
78-1803-3


CFSU 31-33- 7-5-78, 3720 ft., received 7-11-78

Analysis started on:

Turbidity	200.0	NTU	Total Hardness as CaCO ₃	188.0	mg/l
Conductivity	12,300	umhos/cm	Iron as Fe (Total)	11.100	mg/l
pH	7.94	Units	Iron as Fe (Filtered)	8.660	mg/l
Total Dissolved Solids at 180°C.	8,000	mg/l	Lead as Pb	0.345	mg/l
Alkalinity as CaCO ₃	210.0	mg/l	Magnesium as Mg	7.68	mg/l
Arsenic as As	1.131	mg/l	Manganese as Mn	0.328	mg/l
Bicarbonate as HCO ₃	256.2	mg/l	Mercury as Hg	<0.0002	mg/l
Barium as Ba	0.16	mg/l	Nickel as Ni	0.688	mg/l
Boron as B	0.25	mg/l	Nitrate as NO ₃ -N	0.02	mg/l
Cadmium as Cd	0.007	mg/l	Nitrite as NO ₂ -N	<0.01	mg/l
Calcium as Ca	62.4	mg/l	Potassium as K	465.0	mg/l
Carbonate as CO ₃	<0.01	mg/l	Selenium as Se	<0.001	mg/l
Chloride as Cl	3,410	mg/l	Silica as SiO ₂	64.0	mg/l
Chromium as Cr (Total)	0.048	mg/l	Silver as Ag	0.030	mg/l
Chromium as Cr (Hex)	<0.001	mg/l	Sulfate as SO ₄	1,000	mg/l
Copper as Cu	0.077	mg/l	Sodium as Na	2,916	mg/l
Surfactants MBAS	<0.05	mg/l	Zinc as Zn	0.051	mg/l
Fluoride as F	2.90	mg/l			
Lithium as Li	11.62	mg/l			


Ford Chemical Laboratory, Inc.

All reports are submitted as the confidential property of clients. Authorization for publication of our reports, conclusions, or extracts from or regarding them, is reserved pending our written approval as a mutual protection to clients, the public and ourselves.



Ford Chemical

LABORATORY, INC.

Bacteriological and Chemical Analysis

40 WEST LOUISE AVENUE
SALT LAKE CITY, UTAH 84115
PHONE 485-5761

Don Ash

Name Union Oil Co. of California

Date: August 10, 1978

Address P.O. Box 6854


Santa Rosa, Ca. 96501

CERTIFICATE OF ANALYSIS
78-1803-4


CFSU 31033, 7-7-78, (4170 ft., received 7-11-78

Analysis started on:

Turbidity	390.0 NTU	Total Hardness as CaCO ₃	20.0 mg/l
Conductivity	15,380 umhos/cm	Iron as Fe (Total)	10.600 mg/l
pH	9.79 Units	Iron as Fe (Filtered)	0.108 mg/l
Total Dissolved Solids at 180°C.	10,000 mg/l	Lead as Pb	0.420 mg/l
Alkalinity as CaCO ₃	1,440 mg/l	Magnesium as Mg	3.36 mg/l
Arsenic as As	5.707 mg/l	Manganese as Mn	0.016 mg/l
Bicarbonate as HCO ₃	658.8 mg/l	Mercury as Hg	0.0007 mg/l
Barium as Ba	0.47 mg/l	Nickel as Ni	0.975 mg/l
Boron as B	0.50 mg/l	Nitrate as NO ₃ -N	< 0.01 mg/l
Cadmium as Cd	0.045 mg/l	Nitrite as NO ₂ -N	< 0.01 mg/l
Calcium as Ca	14.40 mg/l	Potassium as K	443.0 mg/l
Carbonate as CO ₃	540.0 mg/l	Selenium as Se	0.007 mg/l
Chloride as Cl	3,900 mg/l	Silica as SiO ₂	79.0 mg/l
Chromium as Cr (Total)	0.006 mg/l	Silver as Ag	0.037 mg/l
Chromium as Cr (Hex)	< 0.001 mg/l	Sulfate as SO ₄	760.0 mg/l
Copper as Cu	0.166 mg/l	Sodium as Na	4,000 mg/l
Surfactants MBAS	< 0.05 mg/l	Zinc as Zn	0.041 mg/l
Fluoride as F	3.60 mg/l		
Lithium as Li	13.31 mg/l		


Ford Chemical Laboratory, Inc.

All reports are submitted as the confidential property of clients. Authorization for publication of our reports, conclusions, or extracts from or regarding them, is reserved pending our written approval as a mutual protection to clients, the public and ourselves.



Ford Chemical
LABORATORY, INC.
Bacteriological and Chemical Analysis

40 WEST LOUISE AVENUE
SALT LAKE CITY, UTAH 84115
PHONE 485-5761

August 10, 1978

CERTIFICATE OF ANALYSIS
78-1803-5

Union Oil Co. of California
Union Geothermal Division
P.O. Box 7600
Los Angeles, Ca. 90051

Attn: Mr. Neil Stefanides

Gentlemen:


The following analysis is on samples of water received on July 11, 1978.

Sample: water

	Silica as SiO ₂ mg/l
Blank #1	5.0
CFSU 31-33 Depth 2455' 6-30-78 9:1 Dil	15.0
Blank #2	5.4
CFSU 31-33 Depth 2825' 7-1-78 9:1 Dil	22.0
CFSU 31-33 Depth 3720' 7-5-78 9:1 Dil	26.0
CFSU 31-33 Depth 4170' 7-7-78 9:1 Dil	29.0


Sincerely,

FORD CHEMICAL LABORATORY, INC.


Lyle S. Ford

All reports are submitted as the confidential property of clients. Authorization for publication of our reports, conclusions, or extracts from or regarding them, is reserved pending our written approval as a mutual protection to clients, the public and ourselves.

LSF:ka



Ford Chemical

LABORATORY, INC.

Bacteriological and Chemical Analysis

40 WEST LOUISE AVENUE
SALT LAKE CITY, UTAH 84115
PHONE 485-5761

DON L. ASH
AUG 22 1978

Date: August 18, 1978

Name Union Oil Company-Geothermal Division

Address 2099 Range Avenue, Box 6854

Santa Rosa, CA 95401


CERTIFICATE OF ANALYSIS

Well water labeled "Depth 3000 feet, 7-20-78" received on July 26, 1978:

Analysis started on: July 26, 1978

Turbidity	<u>80.0</u> NTU	Total Hardness as CaCO ₃	<u>266.0</u> mg/l
Conductivity	<u>2,035</u> umhos/cm	Iron as Fe (Total)	<u>2.154</u> mg/l
pH	<u>7.44</u> Units	Iron as Fe (Filtered)	<u>1.976</u> mg/l
Total Dissolved Solids at 180°C.	<u>1,320</u> mg/l	Lead as Pb	<u>0.006</u> mg/l
Alkalinity as CaCO ₃	<u>200.0</u> mg/l	Magnesium as Mg	<u>19.20</u> mg/l
Arsenic as As	<u>2.991</u> mg/l	Manganese as Mn	<u>0.043</u> mg/l
Bicarbonate as HCO ₃	<u>244.0</u> mg/l	Mercury as Hg	<u>< 0.0002</u> mg/l
Barium as Ba	<u>0.15</u> mg/l	Nickel as Ni	<u>< 0.001</u> mg/l
Boron as B	<u>0.20</u> mg/l	Nitrate as NO ₃ -N	<u>0.45</u> mg/l
Cadmium as Cd	<u>0.040</u> mg/l	Nitrite as NO ₂ -N	<u>< 0.01</u> mg/l
Calcium as Ca	<u>74.40</u> mg/l	Potassium as K	<u>56.20</u> mg/l
Carbonate as CO ₃	<u>< 0.01</u> mg/l	Selenium as Se	<u>< 0.001</u> mg/l
Chloride as Cl	<u>502.0</u> mg/l	Silica as SiO ₂	<u>64.5</u> mg/l
Chromium as Cr (Total)	<u>< 0.001</u> mg/l	Silver as Ag	<u>< 0.001</u> mg/l
Chromium as Cr (Hex)	<u>< 0.001</u> mg/l	Sulfate as SO ₄	<u>187.0</u> mg/l
Copper as Cu	<u>0.914</u> mg/l	Sodium as Na	<u>355.0</u> mg/l
Surfactants MBAS	<u>< 0.05</u> mg/l	Zinc as Zn	<u>0.104</u> mg/l
Fluoride as F	<u>1.03</u> mg/l		
Lithium as Li	<u>1.164</u> mg/l		

Doyle Ford (VH)
Ford Chemical Laboratory, Inc.



Ford Chemical
LABORATORY, INC.
Bacteriological and Chemical Analysis

40 WEST LOUISE AVENUE
SALT LAKE CITY, UTAH 84115
PHONE 485-5761

August 18, 1978

CERTIFICATE OF ANALYSIS
78-1956-2

Union Oil Company
Geothermal Division
2099 Range Avenue
Box 6854
Santa Rosa, CA 95401

Gentlemen:

The following analysis is on samples of water received on
July 26, 1978:

Sample: Water

	Silica as SiO ₂
3000 feet, 9:1 Dilution	34.5 mg/l
Blank	22.5 mg/l

Sincerely,

FORD CHEMICAL LABORATORY, INC.

Lyle S. Ford (UH)
Lyle S. Ford

LSF:vh

CFSU #31-33

8/9/78


	<u>TEMPERATURE</u>	<u>PRESSURE</u>
0	min	0
500'	195°	0
1000'	200°	0
1500'	202°	0
2000'	263°	30
2460'	265°	210
		394


Fluid level = 1400'

Pickup = 2464'

WHP = 0

WHT = min





UNION

GEOHERMAL DIVISION

SUBSURFACE SURVEY

Field Work Sheet

CFSU 31-JJ-SI-PT

OWNER Union Oil Company FIELD Cove Fort WELL NAME CFSU 31-33
 CASING 30" @ 52' 20" @ 280' ELEV. DATE: 8/19/78
 LINER DESCRIPTION: 1 3/8" @ 1733 ZERO POINT SWAB GATE (GL)
2 7/8" @ 2559 DEPTH 2559 (KB)

REMARKS: FLUID LEVEL ± (1900')

PURPOSE GRADIENT SURVEY

ELEMENT Temp SERIAL NO. 10172 CLOCK 17498 TURN STABILIZATION PERIOD
PRESS 12833 17499

ENGAGE STYLUS 1138 DISENGAGE STYLUS 1348 MAX. °F
 COR. CSG. PRESS. 0

PICKUP @ 2464

WELL STATUS

SHUT IN: ON PRODUCTION:

Open Swab Gate
Close Swab Gate

Temp						Press											
TIME	DEPTH	DEFL.	PT	GRAD.	/D	TIME	DEPTH	DEFL.	PT	GRAD.	/D	TIME	DEPTH	DEFL.	PT	GRAD.	/D
	0		min						min								
	500		195						min								
	1000		200						min								
	1500		202						30								
	2000		263						210								
	2460		265						394								

COMMENTS: 17500 FT of wire on drum

BY: Sam Timmons

76


union

GEOTHERMAL DIVISION
SUBSURFACE TEMPERATURE SURVEY

OWNER Union Oil Company FIELD COVE FORT WELL NAME CFSU 31-JJ
 CASING _____ ELEV _____ DATE: 8/9/78
 LINER DESCRIPTION: _____ ZERO POINT SWAB GATE
 _____ DEPTH 2559

HOLE DESCRIPTION: _____ INSTRUMENT 104-768 FAHR
 _____ SERIAL NO 10172


PURPOSE GRADIENT SURVEY MAX TEMP 265 °F @ 2460
 REMARKS: _____



STABILIZATION PERIOD _____

PRESSURED	GAUGE	BOMB	
CASING, PSI	<u>0</u>	<u>0</u>	
DEPTH	TEMP.	DEPTH	TEMP.
0	MIN		
500	195		
1000	200		
1500	202		
2000	263		
2460	265		

BY: Sam Timmons



union

GEO THERMAL DIVISION


SUBSURFACE PRESSURE SURVEY

OWNER Union Oil Company FIELD Cove Fort WELL NAME CFSU 31-33
 CADING _____ ELEV _____ DATE 8/9/78
 LINER DESCRIPTION: 2 7/8" Tbg To 2559 ZERO POINT SWAB GAUGE
 DEPTH 2559

HOLE DESCRIPTION: _____ INSTRUMENT 4100 PSIG
 SERIAL NO 12833

PURPOSE GRADIENT SURVEY MAX TEMP 265 °F @ 2460

REMARKS: _____



STABILIZATION PERIOD _____

PRESSURES	GAUGE	BOMB
CASING PSI	0	0

DEPTH	PRESSURE	GRADIENT
0	min	
500	min	
1000	min	
1500	30	
2000	210	
2460	294.4	

Handwritten calculations and notes:
 379
 26.4
 20
 17.6
 6.8
 250

Handwritten notes:
 433
 435

BY: Sam Timmons

COVE FORT SULPHURDALE UNIT #31-33

H₂S SAFETY PROCEDURES

Protection of all people on and around the Cove Fort Sulphurdale #31-33 location from possible H₂S gas poisoning was of the utmost importance to Union Oil Company of California.

With the help of R. F. Smith Company, Union Oil implemented a state of the art safety program to ensure the safety of everyone. The safety equipment and personnel consisted of:

- 1) Safety trailer with 15 - 300 C.F. cylinder cascade air supply system.
- 2) Two thousand feet of low pressure air line hose with quick connects.
- 3) High pressure air compressor.
- 4) Five low pressure manifolds.
- 5) Fourteen air line masks with escape cylinders.
- 6) Thirteen 30 minute self contained oxygen units.
- 7) Two head-fixed H₂S monitor systems.
- 8) Warning sirens and revolving amber light.
- 9) Three wind socks.
- 10) First aid kit.
- 11) Two resuscitators with cylinders (oxygen powered).
- 12) Flare gun with shells.
- 13) Gas detector (pump type).
- 14) Safety supervisor.

There were three H₂S gas monitors on the location: one was located on the rig floor, one under the rig floor at the flow nipple, and one at the mud shakers. The monitors were set to detect H₂S concentrations in excess of 10 ppm and automatically activate a warning siren and revolving amber light. In addition, a sampling system collected vapors at the flow nipple and transported them to the R. F. Smith trailer where they were analyzed continuously by a gas chromatograph.

In the event of a warning, the men on the rig floor were instructed to immediately put on air breathing apparatus with escape cylinders and alternate reserve air line. Air was supplied to the masks through manifolds from the cascade air supply system. If for some reason there was a malfunction in the air supply system, the masks were equipped with escape cylinders which would supply air for sufficient time to allow a person to leave the area.

After it was determined that everyone was wearing a mask, either a safety supervisor or drilling foreman would check the area for H₂S using a hand operated gas detector. One of the 30 minute self-contained units was worn by the foreman and/or supervisor so that he could move safely around the location while making the check. If an H₂S concentration of over 10 ppm was found in or around the work area, the men were required to work wearing masks. If less than 10 ppm H₂S was found, the men could continue work normally. Constant monitoring was continued until the gas dissipated.

Three wind socks were located strategically around the location. If the warning siren sounded when an employee was away from either a self-contained air unit or air line mask, he could observe the wind sock and move quickly up wind escaping the gas.

In addition to the above, two oxygen resuscitators and a flare gun were on location at all times. The resuscitators were to be employed to revive any individual overcome by H₂S. If it was determined that any H₂S leak was adequate to endanger human or animal life in an area adjacent to the location, use of the flare gun would be a last resort measure to ignite and eliminate the gas.

All personnel required to be present or perform any type of service on or in the proximity of the CFSU #31-33 location were given instruction relating to safe operating procedures in the presence of H₂S gas. Safety instruction was conducted in all cases by a qualified representative of R. F. Smith Corporation. In addition to instruction, an inspection for broken eardrums was made by an M.D. and all personnel were required to be cleanly shaven to ensure an airtight fit of the available breathing apparatus.

Many scheduled and unscheduled H₂S drills were conducted, exposing each person associated with the drilling operation to at least one drill. The drills were triggered by manual activation of the H₂S alarm system.

The H₂S alarms were activated once when steam and vapors were seen to be coming out of the rotating head rubber, while drilling the interval 1236' to 1241'. All personnel on the location followed prescribed H₂S safety procedures at this point.

Immediately following the activation of the alarms, manual measurements of H₂S were made on the rig floor, indicating concentration on the order of 10 ppm H₂S. A brisk wind was blowing at the time, and the gas was quickly dispersed. The gas chromatograph sampling vapors from the flow nipple did not detect any H₂S during this event.