







CASING  
COLLARS →  
12ft deep



3700

3800

3900





4000

4100

4200


4300

130  
140

140  
150

ONAN GENERATOR

FAILED  
STOPPED IN HOLE






4300



4400

4500

4600








160

170

4700

4800


4900







5000

5100


5200













5900

6000

6100








6200

6300

6400


6500



180

190





REDUCED  
SCALE  
TEMP

CASING  
COLLARS  
RECORDED  
12ft  
DEEP

CASING  
COLLARS  
WIRELINE  
DEPTH

Temp

6800

6700

6600

6500




180

190

190


200













7400

7500

7600









7100

7800

7900






8000

8100

8200







8300

8400

8500






8600

230  
240

240  
250

8700

8800





8400


9000


9100

9200

240  
250

250  
260






9200

9300

9400

9500





9600

250


260

260

270

9700

9800



260

270


270

280


9900

10000

10100







THIS ANOMALY IS  
DUE TO REHEATING  
OF THE PROBE AND  
IS NOT VALID.

10500

280

290



GL02571  
FILE\_CAB\_15\_DRAWER\_1