GL04428_6

Dresser Atlas

DRESSER

BHC ACOUSTIC FRACLOG®

FILE NO.

API NO.

FIELD PRINT

COMPANY G.E.O. (NEWBERRY)
WELL N NO.1
FIELD NEWBERRY
COUNTY DESCHUTES STATE OR.

LOCATION:
3600 FT. WEST & 2758 FT. NORTH
OF SE CORNER

SEC 25 TWP 22S RGE 12E

OTHER SERVICES
GR.IEL,AC

PERMANENT DATUM GL ELEV. 5840
LOGGING MEASURED FROM GL 0 FT. ABOVE P.D.
DRILLING MEASURED FROM GL

ELEVATIONS
KB --
DF --
GL 5840

DATE	11/3/85		
RUN	1		
SERVICE ORDER	33975		
DEPTH-DRILLER	4550		
DEPTH-LOGGER	4542		
BOTTOM LOGGED INTERVAL	4538		
TOP LOGGED INTERVAL	1788		
CASING - DRILLER	3 1/8	@ 1800	@
CASING - LOGGER	1788		
BIT SIZE	3 3/4		
TYPE FLUID IN HOLE	WATER		
DENSITY / VISCOSITY	-	-	
PH / FLUID LOSS	-	-	
SOURCE OF SAMPLE	N/A		
RM AT MEAS. TEMP.	-	@ -	@
RMF AT MEAS. TEMP.	-	@ -	@
RMC AT MEAS. TEMP.	-	@ -	@
SOURCE OF RMF / RMC	-	-	
RM AT BHT	-	@ 176	@
TIME SINCE CIRCULATION	12 HRS		
MAX. REC. TEMP. DEG. F	176		
EQUIP. NO. / LOC.	6406	SACRAMENTO	
RECORDED BY	M. HINDS		
WITNESSED BY	MR. DANSART&SWANBERG		

FOLD HERE

IN MAKING INTERPRETATIONS OF LOGS OUR EMPLOYEES WILL GIVE CUSTOMER THE BENEFIT OF THEIR BEST JUDGEMENT, BUT SINCE ALL INTERPRETATIONS ARE OPINIONS BASED ON INFERENCES FROM ELECTRICAL OR OTHER MEASURMENTS, WE CANNOT, AND WE DO NOT GUARANTEE THE ACCURACY OR CORRECTNESS OF ANY INTERPRETATION. WE SHALL NOT BE LIABLE OR RESPONSIBLE FOR ANY LOSS, COST, DAMAGES, OR EXPENSES WHATSOEVER INCURRED OR SUSTAINED BY THE CUSTOMER RESULTING FROM ANY INTERPRETATION MADE BY ANY OF OUR EMPLOYEES.

@		@
@		@
@		@
@		@
@		@

REMARKS RUN (1)

EQUIPMENT DATA

RUN	TRIP	TOOL	SERIAL NO.	SERIES NO.	POSITION
1	1	AC	72572	1605	FREE
1	1	GR			
1	1	CAL			

G.E.O.
N NO. 1
SERVICE KC204A FILE 2