Page 3

BACA PROJECT

DATA AND REPORTS

WELLS

No.	Transfer Date	Release Date	Title
1.	Α	A	Summary sheet for Baca Wells No's 1-3.
2.	λ	A	Baca Wells No's 4-16 summary sheet.
3.	А	A	Well summary reports and Drilling Histories Baca Wells No's 4-16.
4.	В	В	Lithology logsBaca Wells No's 4-16.
5.	Α	A	Temperature and Pressure SurveysBaca Wells No's 4-8 and 10-16.
, .	В	В	Electric logs for Baca Wells No's 10-14.

ISACA 5-

BACA #5 Sept. 19

38D 6973'TD 113' drld. 6-1/2hrs. drld. 2-1/4hrs trip 15-1/4hrs others Formation Baliza Canyon. Flow line temp. 255°. Drld. from 6860' to 6973'TD. POOH, ran temp. survey. Pressure bomb failed. Laying down drillpipes.

5 hrs. bottom hole temp. survey as follows:

45001	362°
6100'	330°
6600'	408°
6350'	430°
6970 '	435°

Total cost to date \$274,026.00

BACA #5 Sept. 20

3D 24hrs. others. 3973'TD

Finished laying down drillpipes & drill collars. Strip cellar. Dismantled blooie line. Off report

Total cost to date \$276,526.00

BACA #5 Sept. 18

37D 6860' 239' drld. 9-3/4hrs drld. 5-1/2hrs trip 8-3/4hrs others Drld. to 6793', POOH. Ran temp. & press. surveys. Maited 5 hrs. ran temp. & press. surveys. Ran back in hole. Drlg. ahead. Injecting 8 bbls. water per hour with 6 gallons soap & 5 gallons unisteam. Formation Baliza Canyon. Flow line temp. 240°.

3-1/2hrs. bottom hole temp. & pressure survey as follows:

4500'	362°	981#
6100'	381°	1583#
6300'	397°	1659#
6500 '	415°	1734#
6700 '	424°	1805#
6786 '	445°	1847 <i>#</i>

8-1/2hrs. bottom hole temp. & pressure survey as follows:

6786'	454°	- clock	stopped	on	bomb.
4500 '		981/	7		
6100'		1583#	¥		
6300		1656#	1 F		
6500 '		1729#	l F		
6700'		1806#	ŧ		
6750'		1829/	ŧ		
6736'		1835#	ŧ		

Total cost to date \$269,326

Sept. 17, 1971

BACA #5

36 D	111' Drld.
6621'	5hrs. drld
	12-1/2hrs trip
	6-1/2hrs others

Formation Bandelier Tuff. Flow line temp. 225°. Drld. to 6540', POOH, ran temp. survey. Ran back in hole, reamed 6406' - 6540'. Drld. to 6555'. POOH, changed bits. Ran back in hole with circ. sub at 4500'. sub has one 1/8" & one 3/16' port. Drlg. ahead. Injecting 6 bbls. water per hour w/8 gallons soap & 5 gallons unisteam.

Well closed in 3-1/2 hrs.temp. survey as follows:

4500' 360° 5655' 373° 6106' 386° 6520' 393° 6540' 397° Temp. recorded was 406° at some depth between 6106' - 6520'

Total cost to date \$264,276.00

SEPT. 16, 1971

BACA #5

35D 6510' 360' Drld. 16-1/2Hrs. drlg. 5-3/4Hrs. trip 1-3/4Hrs. other Formation Bandelier/tuff. Flow line temp. 240°, orifice size 8-3/4, 23# pressure. Drld. to 6226' & POOH. R.I. w/new bit w/l/4" circulating port @ 4370'. Unloaded hole 5700'. Ran back to bottom. Now drlg. ahead. Injecting 6 bbls./hr. w/8 gals. soap and 5 gals. unisteam.

Total cost to date - \$258,276

Sept. 15, 1971

BACA ∦5

34D

·6150'

75' drld. 4-3/4hrs. drld. 5 hrs. trip 14-1/4hrs. others

1.

Formation Bandelier tuff. Flow line temp. 233°. Drld. to 6107', bit locked up. POOH, ran bottom hole temp. survey. Waited 5 hrs. ran another bottom hole temp. survey. RIH with 1/4" circ. port at 4250', unloaded hole & reamed from 6022' - 6107'. Drlg. ahead this a.m. Injecting 6 bbls. water per hour with 4 gallons soap & 1-1/2 gallons unisteam.

Temp. surveys as follows:

Depth.	Tem-4-1/2hrs.	tem-9-1/2hrs.
4500'	350°	31;2°
5655'	367°	369°
6000'	375°	380°
6090'	398°	400°
6106'	395°	405°

Total cost to date \$253,376.00

Sept. 14, 1971 ,

BACA #5

33D

6075'

53' drld. 4hrs. drld. 8-3/4hrs. trip 11-1/4hrs. others Ran bottom hole pressure & bottom hole tamp. surveys. RIH w/jet circ. sub at 4000'. Reamed 5958' to 6022'. Drld. 6022' - 6027', unable to clean hole. PU & took circ. sub out, ran back to bottom, drlg. ahead. Injecting 6 bbls. water per hour with 4 gallons soap & 1-1/2 gallons unisteam.

Survey as follows: 4500' 336° 5300' 358° 5655' 368° 6000' 380° 6012' 385°

Pressure survey, well closed in 3-1/2hrs. 3000' 399# 4000' 794# well closed in 6-1/4hrs. 4000' 807#

Total cost to date \$249,376.00

Sept. 13, 1971

BACA #5

32D 412' 6022' 12-3 7-3/

412' drld. 12-3/4hrs. drld. 7-3/4hrs. trip 3-1/2hrs. others Drld. to 5683'. POOH, ran in temp. survey. RIH, drld. to 6022'. Now Pulling out of hole for Bit change & Temp. survey.

Temp, surveys as follows:

344°
362°
375°
377°

Total cost to date \$244,776.00

BACA #5 Sept. 11

370' drld. 30D 5170' 13-3/4hrs. 6-3/4hrs trip 2-1/2hrs others

Formation Bandelier tuff. Flow line temp. 155°. Hole dusted to 5010'. Started making approx. 10 gallons per minute of water after drlg. break from 5010' - 5016'. Started injecting 6 bbls. water per hour with 3 gallons of soap & 1-1/2 gallons unisteam. POOH at 5065'. Ran in temp. survey and pressure survey. Picked up 29 jts. 4-1/2" drillpipe. RIH, reamed 55' to bottom. Drld. ahead. Injecting 8 bbls. water with 2 gallons of soap and 1-1/2 gallons unisteam per hour.

Survey as follows

D	Temp.	Pressure
4000 '	233 [°]	14#
4500'	237°	15#
5050'	303°	241#

Total cost to date \$234,426.00

BACA #5 Sept. 12

4401 5610' 15-1/2hrs. drld. 5hrs. trip 3-1/2hrs. others Formation Bandelier tuff. Flow line temp. 175°. Drld. to 5330'. Large increase in water from 5290' - 5296' & 5306' - 5310'. Probably 60 bbls. per hour of water. POOH, ran in Temp. & pressure survey. RIH, drlg. ahead, injecting 6 bbls. water per hour with 2 gallons soap & 1-1/2 gallons unisteam.

Survey	as	follow	S
D	Τe	emp.	Pressure
4500 '	33	39°	930#
5016'	35	540	
5300'	36	53°	1152#
5315'	36	;30	

31D

Sept. 10, 1971

BACA #5

29D

4800'

400'.drld. 9-3/4hrs. lhr. trip

9-3/4hrs. drld. lhr. trip 13-1/4hrs. others Formation Bandelier tuff. Flow line temp. 95°. Went back in hole, washed & drld. cement out to 2850', POOH. Picked up 14 drill collars, RIH, found top of cement inside liner at 3940'. Drld. out cement float collar & float shoe to bottom of liner at 4400'. Hole dry & dusting from 4400' to 4800'. No water & no steam, drlg. ahead.

Totat cost to date \$229,426.00

SEPT. 9, 1971

BACA #5

28D 4400' 0' drld. Ohrs. drld. Ohrs. trip 24hrs. others MOC 6 a.m. 9/8/71 to 1:30 a.m. 9/9/71. Ran Baker FBRC. Baker on bottom of drill pipe. Set Baker at 2300', loaded annulus w/water. Pumped in 140 bb1s. of water down drill pipe flwd. by 293 sks. of class "C" cement and 293 sks. diamix M (700 cu. ft.) neat. Displaced with 82 bb1s. of water, squeezed to 2000 psi. Let set 15 minutes, held 0.K. Left 120' of cement in 13-3/8" csg. above top of liner. POOH

Total cost to date \$225,376.00

SEPT. 8, 1971

BACA #5

27D 4400' 0' Drld. Ohrs. Drld. 5hrs. trip 19hrs. others

RIH to bottom, circ. 9 a.m. to 2:30 p.m. POOH, ran Baker float shoe on bottom, flwd. by 2 jts. of 9-5/8" - new - 40# - K-55 seal lock smls. csg. flwd. by Baker float collar flwd, by 38 jts. of above flwd. by Burns plain type liner hanger with cement in slots - 1707.76'. Setting at 4400', top of liner 2692.24', over laps 13-3/8" csg. 135'. Pumped 200 bbls. of mud flwd. by 20 bbls. of water. Mixed & pumped in 470 sks. of class "C" emt. w/470 sks. of diamix plus .8% R-6 retarded to 300°F. 1127 cu. ft. of slurry displaced w/165 bbls. of water. Bumped plug with 1500 psi. Released pressure, POOH, took off setting tool, RIH open ended to 2750'. Mashed out top of liner, POOH. WOC at 6 a.m. 9/8/71.

Total cost to date \$217,276.00

BACA #5 Sept. 6

25D 4067' 97' Drld. 4-3/4hrs drld. 8hrs trip 10-1/4hrs others Drld. to 4065'. Formation Bandelier tuff. Flow line temp. 170°. POOH, ran temp. survey. put on new bit, ran back in hole drld. from 4065' to 4067'. Rotating table locked up. POOH, repaired rotating table, ran temp. survey at 4067', Going back in hole.

Well closed 2-1/2hrs. ran in to bottom of hole. temp. as follows; 3206' 280° 3600' 263° 4026' 256°

Well closed l0hrs. ran in to bottom of hole. Temp. as follows; 2800' 307° 3600' 264' 4025' 269°

Total cost to date \$190,406.00

BACA #5 Sept. 7

26D 4400' 333' Drld. 11-1/2hrs drld. 4-1/2hrs trip 8hrs. others

Formation Bandelier tuff. Flow line temp. 185°. Went back in hole drld. to 4400'. POOH, ran temp. and pressure survey after well had been closed in for 5 hours. Going back in hole to make wiper run in preparing to run 9-5/8" liner.

SURVEY AS FOLLOWS

D	Temp.	Pressure
2800'	297°	420#
3600'	277°	745#
4025'	273°	916#
4375'	269°	1054#
Total	cost to date	\$194,781.00

BACA #5 Sept. 4

2 3 D	Ohrs	drld.
3427'	Ohrs	trip
	24hrs	others

Laid down 9 plug drill collars, picked up 9 drill collars. Went in hole, circ. w/water. Drld. cement retainer from 2727' - 2730' and drld. cement from 2730'- 3427'. Had same amount of water as before squeezing.

Total cost to date \$182,756.00

BACA #5 Sept. 5

24 D	543' Drld.
3970'	19-1/2hrs drld.
•	2hrs trip
	2-1/2hrs others

Formation Bandelier tuff. Flow line temp. 165°. POOH, put on new bit, went back in hole. Drlg. ahead. Had increases in water and steam at 3860'. Injecting 8 bbls. water per hour with 3 gallons of soap and 1-1/2 gallons of unisteam.

Total cost to date \$186,156.00

SEPT. 3, 1971

BACA #5

22D		Ohrs.	Drld,
3427'		6hrs.	Trip
	. · ·	18hrs.	others

NOC 8 a.m. to 2 a.m. Ment in hole to 2700'. Turned air on to unload hole. Scale of cement inside drill pipe. Turned loose and plug drill collars. P.OOH, will unplug collars and drill out cement and retainer.

Total cost to date \$178,556.00

Sept. 2, 1971

BACA #5

21D 205' Drld. 3427' 11-1/4Hrs Drld. 5-1/2Hrs trip 7-1/4Hrs Others Survey 2° at 3418'

Formation Bandelier Tuff. Flow line temp. 158°F. Drld. to 3427'. PU in csg. & let set 30 minutes. Went back to bottom, no bridges & no fill. POOH, RI temp. survey bottom hole temp. at 3000' 311°F. RI HOWCC EST drill SB retainer on bottom of drill pipe & set at 2727'. Loaded annulus with water, pumped in 180 bbls. of water flwd by 1438 cu. ft. of 1-1 class "C"Cmt. & diamix with 1.6% R-11 & 2% D-19 flwd by 250 sks. (330 cu. ft. of class "C" cmt. with 1.2% R-1, retarded to 275°). Displaced down drill pipe with 43 bbls. of water drill pipe waited full. PO & closed valve hole retainer & dumped 25 sks. cmt. on top of retainer. JC 8 a.m. 9/2/71. POOH, waiting on cement.

Total cost to date \$174,956.00

Sept. 1, 1971

BACA #5

20D 3222' 132' drld. llhrs. drld. 6hrs. trip 7hrs. others Formation Bandelier tuff. Flow line temp. 158°. WOC 8 a.m. to 9 am. RIH & drld. cmt. & float collars & had cmt. from 2684' to 3000'. CO from 3000' - 3090'. Blew hole 45 min. making approx 1/2 to 3/4 bbls. water per min. with small amount of steam. POOH, RI & drlg. ahead. Injecting 8 bbls, water per hour with 2 gallons soap and 1-1/2 gallons unisteam.

Total cost to date \$161,906.00

Aug 31, 1971

BACA #5

MOC 8 a.m. to 5 p.m. Went in hole found cement at 2674'. Dusted w/air 19D 0' Drld 3II trip without rotating and 10-15# of weight 2111 others from 2674'-2684'. POOH, waiting on

cement.

Total cost to date \$157,606.00

3090'

AUG. 28,29,30

BACA #5, Aug. 28

16D	Ohrs.	drlg.
3090'	Ohrs.	trip
	24hrs.	other

Ran Texas pattern guide shoe w/teeth on bottom of float, flwd. by 2 jts. (79.49') of 13-3/8" O.D. 61# K55 smls. csq., flwd. by one float collar, flwd. by 39 jts. (1448.97') of 61# K55 smls. csg., flwd. by 32 jts. and one piece (1277.30') of 13-3/8" 54.50# K55 smls. csg. set @ 2827.81' KOB measurements. Mixed and pumped in 850 bbls, mud w/8% LCM. Mixed and pumped in 1435 sx. of thermal 660 cmt. w/l cu. ft. of perlite per sack (yields 2.29 cu. ft. per sack), flwd. by 565 sx. of thermal 660 cmt. neat displaced w/336 bbls. water. Circulated out 600 cu. ft. cmt. and left 600 ft. in csq. Pressured up to 2200 psi at end of job. Job complete 5:30 p.m. 8/27/71.

Cost to date - \$148,256.

.CA #5, Aug. 29

17D	Ohrs. drlg.	Pulled up hydril, rotary head and blooie
3090'	Ohrs. trip 24hrs. other	line. Repaired blooie line. Instlg. BOE and nippling up.

BACA #5, Aug. 30

18D	Ohrs.	drlg.
3090'	3hrs.	trip
	21hrs.	other

Finished nippling up and instlg. BOP @ 6 p.m., 8/29/71. Ran drillpipe in hole and found top of cmt. @ 2212. Drld. hard cmt. from 2212'-2222'. Found liquid cmt. from 2222'-2674'. POOH. WOC this a.m. Checking w/Halliburton regarding setting time at various temps.

Aug. 27, 1971

BACA #5

15D		Ohrs.	drld.
3090'		0hrs.	trid
		24hrs.	other

Finished P.OOH, RI temp. bomb to 935', unable to go thru bridge. RI open ended drill pipe to 1135'. RI temp. bomb to bridge at 1730'. Unable to get bomb thru bridge. POOH, rigged up to RI 13-3/8" casing; Running in 13-3/8" casing.

Total cost to date \$83,706.00

Aug. 26, 1971

BACA #5

14D 232' Drld. 3090'

12hrs. Drld. 5-1/2hrs trip 6-1/2hrs others

Formation Bandelier tuff. Flow line temp. 180°. Drld. to 3090', blooie line cut out at flange under floor. Pulled up to 600', well flowed for 4hrs, and died. Mixed 600 bbls. mud to pump ahead of cement. RIH after letting set for 6hrs., found no bridges. Pulled back up to 600' then let set for 3hrs, RIH, found no bridges. POOH to run casing.

Total cost to date \$79,306.00

Aug. 25, 1971

BACA #5

13D 2858' 153' Drld. 7hrs Drld. 7-1/2hrs trip 9-1/2hrs others Formation Bandelier tuff. Flow line temp. 180°. Changed stripper rubber. RIH, hit bridge from 935' to 940'. Drld. from 2705' to 2815', water *& steam increased. Blooie line cut out under floor. POOH, killed well, repaired blooie line. RIH, small bridge at 935'. Drlg. ahead. Injecting 14 bbls. of water per hour with 6 gallons of soap and 2-1/2 gallons of unisteam.

Total cost to date \$74,056.00

AŬG. 24, 1971

BACA #5

12D 2705' 367' Drld. 18-1/2hrs Drld. 2-3/4hrs trip 2-3/4hrs others survey: 3-3/4° at 2380', 5° at 2507', 4-1/4° at 2705'. Formation Bandelier tuff. Flow line temp. 170°. Injecting 12 Barrels water per hour w/5 gallons of soap and 2 gallons of unisteam. Produced water increase to estimated 75 barrels per hour with flashing steam from 2375' to 2705'. RI deviation survey at 2705', wire line broke. POOH to recover instrument and change bit. Now out of hole.

Total cost to date \$66,931.00

BACA #5 AUG 21

9D 1770' 290' Drld. 21 Hrs Drld. 2-1/2Hrs trip 1/2H others survey 2-1/4° at 1667' Formation Bandelier tuff. Flow line temp. 172°. Mist Drlg. Injecting 12 barrels of water per hour with 4 gallons of soap and 2-1/2 gallons of Unisteam.

Total cost to date \$54,581.00

BACA #5 AUG 22

10D375' Drld.Formation Bandelier tuff. Flow2145'22-3/4Hrs Drld.line temp. 170°. Injecting 121-1/4Hrs otherbarrels water per hour with 5Survey 5° at 1982',gallons of soap and 2 gallons5-1/2° at 2107',of Unisteam. Reduced wt. on4-1/4° at 2192'.bit from 40,000# to 28,000# at

Total cost to date \$57,831.00

2023'.

BACA #5 Aug 23

11D 2338' 193' Drld. 11-1/2Hrs drld. 5-1/2Hrs trip 7Hrs other Survey 5° at 2265'

Formation Bandelier tuff. Flow line temp. 170°. Reduced wt. from 28,000# to 20,000# at 2147'. Increased wt. on bit to 25,000# at 2223'. POOH at 2319'. RI temp, bomb to bridge at 1045'. Line parted and left bomb in hole. Made grapple and recovered all of line and bomb. Bomb was not damage. Temp. at 1045' was 235°. Welded on rotating head drive for 2 hrs. Went. in hole, hit and drld. out bridge from 1045' to 1065' and another bridge from 1682' to 1742'. Drlg. ahead.

Totat cost to date \$61,631.00

AUG. 20, 1971

BACA #5

8D 1480' 380' Drld. 23-1/2H Drld. 1/2H Other survey 3/4 of 1° at 1352'. Formation Bandelier Tuff. Flow line temp. 179°. Hit small amount of hot water and steam at 1229'. Commenced injecting 4 barrels of soap & 1-1/2 gallons of unisteam per hour mixed with 12 barrels of water. Drlg. ahead this a.m.

Total cost to date \$47,881.00

Aug. 19, 1971

BACA #5

7D ,1100' Drld. 13-3/4H Trip 3-1/2H Other 6-3/4H survey 3/4° at 1069' Formation Bandelier Tuff. Flow line temp. 100°. Drlg. w/air - dusting. Drld. to 1100'. Drlg. ahead this a.m.

Aug. 18, 1971

BACA #5

6D 736**'** 60' Drld 2-1/2H Drld. 4H Trip 17-1/2H Others Formation Bandelier Tuff. Flow line temp. 84°. 8 a.m. to 12 midnight nippled up and installed BOE. Drld. mouse hole. RIH found top of cement at 597'. Blew hole dry. Drld. plug and 80' of cement. Drlg. ahead w/air. Injecting 12 barrels of water per hour with 2 gallons of soap.

total cost to date \$37,373.00

August 17, 1971

ORIGINAL HOLE TO BE REFERRED TO AS BACA 5A. NEW HOLE TO BE CALLED BACA #5.

BACA #5

5D

676'

3' Drld. 1/4H Drld. 3-1/4 H Trip 2-1/2 H Other Formation Bandelier Tuff. RI drill pipe in hole, drld. from 673' to 676'. Circ. 1H. POOH, rigged up. RI 20" casing including guide shoe on bottom on 21 jts. plus 1 piece of 20" - 94# - H40 - seamless - S.T.&C. to 676'. Overall length 660.24. Mixed & pumped in 1330 sks. of Class "A" neat cement. Followed by 330 sks. Class "A" cement with 2% CaCl₂, Displaced with 220 barrels of water, Good returns to surface CIP 9:35 pm 8/16/71. Landed 20" casing at 3:00 am. Installing B.O.E.

Total cost to date \$33,873.00

AUG. 14,15,16

BACA #5-A, Aug. 14

2D		169
236'	Dev.	1/4°
		Drlg.
		Othor

169' Drld. v. 1/4° @ 204' Drlg. hrs. 7-1/4 Other hrs.16-3/4

Drld. from 67-236'. Formation caldera/cofill. Bit #1, 26" Smith K2 #273 ran 9-1/4H. Bit wt. 30,000#, 60-90 rpm. Mud wt. 8.5, visc. 54. Water loss 17. Filter cake 2/32, TH 7.2, 1/2 of 1% sand. Laid down small collars. Picked up 8-1/2" drill collars & Drilco free pt. reamer. Reamed from surface to 67'. Recmtd. conductor w/25 sx. cmt. & 12% calcium chloride. Repacked swivel. Conductor washed out again. Drlg. w/jet in cellar.

Total cost to date \$13,350.

BACA #5-A, Aug. 15

D D	305' Drld.	
541'	Drlg. Hrs. 22-3/4	
	Others $1-1/4$	

Drld. from 236-541' in 22-3/4H. Formation caldera & bandelier tuff. (Top of tuff @ 450'.) Temp. 109°. Bit #1, 26" Smith K2 32 hrs. total. Bit wt. 30,000#, 60-90 rpm. Mud wt. 9.5, visc, 44. Water loss 11.2, filter cake 2/32, TH 7.4, 1/2 of 1% sand. Lost 1H going thru pump & 1/4H repairing mud line.

Total cost to date \$15,670.

BACA #5-A, Aug. 16

4D	132' Drld.
673'	Dev. 1/2° @ 655'
	Drlg. Hrs. 18-1/2
	Others 5-1/2

Drld. from 541'-673' in 18-1/2H. Formation bandelier Tuff. Flow line temp. 112°. Bit #1, Smith 26" K2, 50-1/2H. Bit wt. 10-40,000#, 90-150 rpm. Mud wt. 9.6, visc. 64. Water loss 11.2, filter cake 2/32, TH 7.4, 1/2 of 1% sand. Repaired cellar jet line 1/2H. Circulated 1H. Ran Topco 1/2H. Scrapped drillpipe out of hole. Removed rotary table. Pulled conductor pipe. Prep. run 20" csg.

Total cost to date. \$18,149.

August 13, 1971

BACA #5A

1D 67' 67' Drld, 2H 22H other Formation Caldera fill. Mud 8.4#. Visc. 52. Finished rigging up. Drld. rathole. Spudded in with 26" bit at 5 a.m., 8/13/71. Estimated cost to date \$10,400. Now drlg. ahead.

AUGUST 11, 1971

BACA #5

25D

0' Drld. Other 8Hrs. Finished tearing down rig. Started moving to new location 100' East of No. 5 at 7 a.m.

August 10, 1971

BACA #5

24D

Footage made 0 Hrs drilled 0 Other 24Hrs RI drillpipe in hole. Open end & found top of cement plug at 350'. Pull up to 90' & mixed & pumped in 100 sacks of Class C cemt. w/ 2% CaCl₂. Had full returns during cementing. Laid down drill collars & drillpipe. Commence tearing down rig.

August 9, 1971 -

BACA #5

23D

Finished running in hole with overshot, unable to engage fish. The interval 412' to 452'. Unable to go below 452' do to fill. POOH with tool, RI with drilling assembly, cleaned out 452' to 472', Hole caving slightly. Circ. 1H to condition hole. POOH, RI hole with wall hook, overshot bent jt. & knuckle jt. Unable to engage fish. POOH and laid down fish tools. RI with open-end drillpipe to bridge at 465', Pull up to 463' & circ. 15 minutes. Mix & pump 200 sacks thermal 660 cement with 1 cu. ft. perlite/sack. Followed by 150 sacks class C cement with 2% calcium chloride added. Had fill returns during job. POOH with drillpipe, cement in place at 4:30a.m. 8/9/71. Prep. to RI and tag plug this a.m.

BACA #5 August 6, 1971

20D 2878'D

BACA #5 August 7, 1971

21D 2878'D

BACA #5 August 8, 1971

22D 2878'D Stood cmt'd 6 hrs. Filled hole w/45 Barrels water thru 4-1/2" d.p. at 345'. Hole stood full 15 minutes. then dropped away. Mixed & pumped 425 sks. Class C cmt. w/2% CaCl₂. Had partial returns while mixing last 75 sks. cmt. C.I.P. 12:15 a.m. W.O.C. 6 hrs filled hole w/ 17 barrels water. Tested to 250' psi for 30 min. RI w/ 17-1/2" drlg. assm. Now mixing mud.

Stood cmt'd. 21 hrs. loc. top of cmt. at 242'. Drld. hd. cemt.to 345' & cemt. & unipole alignment tool 345' to 384'. CO fill w/scattered cmt stringers 384'432' with full returns. Loc. top of fish @ 432'. PO, RI 11" o.s. w/15" skirt on 9" d.c. unable to get over fish. PO, RI ditto, assm. w/ bent jt. 5" d.p. unable to get over fish. RI 5" rotary shoe. CO by fish 6'.

RI w/6-1/4" shoe on 5-1/2" d.p. CO by fish to 552' and L.C. RE w/15" skirt on ll" o.s. on bent single unable to engage fish. Pumped 300 Bbls. mud w/ no returns. RI 17-1/2" bit and CO to 472'. Regained circ. slight indication of top of fish 0 432'. RI wall hook on o.s. on knuckle jt. on bent sg. unable to engage fish - could loc. at 432' - RI ditto assm, w/ knuckle jt on top of bent single - unable to engage fish. RI 15" skirt on 11" o.s. on bent single on knuckle it. Unable to engage fish. RI wall hook - 11" o.s. - knuckle jt. - bent single -U.T.L.F, Now RI wall hook - 11" o.s. straight jt. - knuckle jt.

Aug 5, 1971

BACA #5

19D

2878'

Mix and pumped 500 barrels additional salt-jel. No returns. RI 4-1/2" open end drill pipe, located top of fill at 346'. Circ. fill from 346' to 387' with 300 barrels of salt-jel. No returns. Let stand 1 hr. and relocated top of fill at 387'. RI 19" by 42' fir casing alignment tool. Stop at 355', pull out tapered nose of alignment tool from 12" to 5-1/2". RI and set alignment tool from 345' to 387'. Cemented hole with 200 sacks pozlanic cement followed by 400 sacks class G cement. CIP 5 a.m. Fluid level while cementing rose to 20' from surface. Now standing cemented

BACA #5 August 2, 1971

16D 2878' Cleaned out fill 304' to 425' with air and mist for 20 hrs. The hole was sluffing and unable to keep clean below 400'. The mist pump broke down, repair same this a.m.

BACA #5 August 3

17D 2878'

BACA #5 August 4

18D 2878' POOH with the bit. Installed mud lines and pumped in 1000 barrels of gel-mud and LCM, unable to load hole. Capacity of hole 300 barrels. Mixing mud and LCM this a.m.

POOH with bit to check fluid level. Fluid level at 300'. Mix & pump 500 additional barrels of mud containing LCM. Hole did not fill. RI to check fill, unable to go below 348'. Apparentl casing parted. POOH to check fluid level, fluid level at 325'. Mix and pump additional 1000 barrel of mud containing LCM. Hole did not fill. Total mud pump 2500 barrels. Mix 500 barrels of saltjel and LCM this morning.

	BACA #5	July 30,	1971	
	13D 2519'		258' drld. 12-1/4 hrs drlg. 1-1/2 hrs trip 10-1/4 hrs other	Formation tuff. Temp. 160°F deviation 2° at 2345'. 6 compressors at 2800CFM. Finished mig nopping at 9:20 a m
			10-1/4 hrs other	Finished rig repairs at 8:30 a.m. 7/29/71. Ran temp. survey to 395'. Unable to work through bridge at 395'. RI with open
				end drill pipe and worked through bridge and ran to 460'. Temp. at 2200' 264°F while flowing. POOH
				with drill pipe and RIH with drill assembly. Cleaned out 40' of fill. Drlg. at 2519' this a.m.
		,		
	BACA #5	July 31		
C.	14D 2878'		359' drld. 18-1/2 hrs drld. 1-1/2 hrs trip 4 hrs other	Formation tuff. Temp. 165°F deviation survey 2-3/4° at 2693'. Drld. to 2878'. Trip for new bit and repaired blooie line, had
				steam and water increases from 2700' to 2878'. While POOH at 2332' flow from well ceased, and while PO at 480' to 390' had to work through bridges.
	BACA #5	August 1	·	
	15D 2878'			Repaired the blooie line and installed 8-3/4" orifice. RIH with drilling assembly. Work through bridges from 415' to 420' and 2157' to 2220'. RI to 2850'.

installed 8-3/4" orlfice. RIH
with drilling assembly. Work
through bridges from 415' to 420'
and 2157' to 2220'. RI to 2850'.
Un-loaded and circulated hole
clean at 2850'. PO to 2835' and
pipe parted at 376'. Fish consists
of 17-1/2" bit, 9" o.d. float sub,
1-9-1/4" drill collar, 1 - 9" drill
collar, 1 crossover, 9 - 7-3/4"
drill collars, 1 crossover, 68 jts.
1 pc 5" drillpipe. RIH with
fishing tools and found fill at
304'.

BACA #5 July 27

10D	159' drld.	Formation tuff. Temp.165°F
1990'	15-1/2 hrs drld.	deviation 1° at 1905'. 6
	4-1/2 hrs trip	compressors at 2900 CFM.
	4 hrs other	Drld to 1846'. Trip for new
		bit. Drlg. at 1990' this a.m.
		25' fill on the trip.

BACA #5 July 28

11D 2261'	271' drld. 14-1/4 hrs drld. 1 hr trip 8-3/4 hrs other	Formation tuff. Temp. 165°F deviation 2° at 2188'. 6 compressors at 2900 CFM. Drld. to 2261". Trip for new bit. Pulled to 1561' and the nig broke down
		to 1561' and the rig broke down. Repairing rig this a.m. Rig was down at 10:30 p.m. 7/27/71

BACA #5 July 23

12D 2261'

Repairing Rig 24 hrs.

BACA #5 July 24, 1971

7 D	591' Drld.	Formation tuff. Flow line Temp.
1428'	Drld. 22-1/4 hrs.	120°F deviation survey 3/4° at
	1-3/4 hrs other	954' and $1/2^{\circ}$ at 1230' in steam.
		Using 6 compressors and 2900 CFM.
		Drld. to 1428' with bit #4. The
		water flow below the casing shoe

decreased and first steam entry at 1200' at a volume to small

bit, had fill from 1550' to 1650'.

to measure.

BACA #5 July 25

9D 1650'	222' Drld. 13-1/2 hrs drlg. 3 hrs trip 7-1/2 hrs other	Formation tuff. Temp. 160°F deviation survey 1° at 1560'. 6 compressors and 2900 CFM. Drld. to 1538' with bit #5,
		trip for new bit. Welded a jet in the blooie line and tie downs on the rotary head. Stood back 9" collars. RI with a new

BACA #5 July 26

9D	181' Drld.	Formation tuff. Temp. 160°F
1831'	23-1/2hrs drlg.	deviation survey 1° at 1680'
	1/2 hr other	6 compressors at 2800 CFM. Continue drlg. this a.m. to

1831'

BACA #5 July 21		
4D 390'	24 hrs. no drlg.	WOC 7 hrs., welded up 26" conductor and 20" casing and welded on 20" flange. Nippling up BOE this a.m.
BACA #5 July 22		
5 D 3 9 0 '	1/2hr drlg. 1 hr trip 22-1/2 others	Drlg. with air, 6 low 2 high and 2800 CFM. Finished nippling up BOP and blooie lines. Tested BOP to 500' psi for 15 minutes. O.K. RIH with the drlg. assembly. Drlg. cement this a.m.
BACA #5 July 23		
6 D 8 3 7 '	447' Drld. 15-1/2 hrs Drld 2-3/4 hrs trip 6 hrs other	Formation tuff. Deviation 3° at 700' Drlg. with air compressor, 6 low 2 high at 2900 CFM. Drld. 40' of cement and float shoe, unable to dust below shoe because of water entry. Approx 400 GPM. Drlg. with soap and water and air. Formation very unconsolidated to 621'. Trip for new bit at 621' because of formation change. Drlg. this a.m. at 837'.

(

BACA #5July 181D107' Drld.107'Drld. 7-3/4 hrs.16-1/4 hrs other1/4° @ 86'. Mud wt. 8.7# viscosity68. Moved in, rig up LofflandBrothers rotary tools. cmtd. at 15'.Drld. rat hole and mouse hole andspudded in at 11 p.m.

BACA #5 July 19

2D 390'	283' Drld. Drld. 4-3/4 hrs, trip 1 hr, 18-1/4	Formation surface fill. 1/4° @ 296'. Surface mud wt. 9# per casing viscosity 76. Drld. 15' hole to
	hrs other	390', circulated 1 hr. POOH pick up the 26" hole opener with a 15" pilot bit. Open 15" hole to 26" from 0 to 296.

BACA #5 July 20

3D 390'

No drlg. hrs. Md wt 9.1# viscosity 72. Open 15" hole to 26" from 296' to 390'. Circulated to condition hole for casing. POOH. Rig to run 20" casing. Ran casing to bridge at 86'. Unable to work through bridge. POOH with the casing, ran drilling assembl Cleaned out bridge. POOH with the drld. assembly, ran and cemented 9 joints and one piece of 40# seamless 20" casing at 390' with 850 sacks class C cement with 2% calcium chloride. Had good cement returns to surface. Did not bump plug. Float held O.K. CIP & JC at 8:15 a.m.