

INTER-OFFICE MEMORANDUM

SUBJECT: Notifications of activities on Young Life Ranch
Mt. Princeton (640) Project

DATE September 19, 1977

TO: Files


cc: D. A. Edgerton

FROM: H. J. Olson

Prior to any activities on the Young Life Ranch be sure to contact

George Chisman, Property Manager
P. o. Box K
Buena Vista, Colorado 81211
(303) 396-2461 office
395-2358 home

Chisman also has personal property to the NE of the deep gradient drill site, we be sure to contact him regarding any activity in the vicinity of the drill site.


Harry J. Olson

Frontier Ranch -

SE 1/4 NW 1/4 Sec 13 T15S R79W

Call Mon Sep 22

will have a backhoe for us at 3 - stop
at ranch as we go in.

1) Explained that reason we were in difficult spot was because of problems with private land owner on original route

2) Explained since the hole was on private land we had been working directly with owner as far as access - tree removal - digging of mud pits

3) Also explained that when hole is completed and ready for abandonment the necessary cleaning of stock - cutting of stumps etc will be taken care of

4) explained spill of cement was operator error - will be cleaned up before hole abandoned.

5) explained a subsiding mud pit would be dug to take care of future overflow

6.) explained rock is fairly
picked up or as is needed -
that we did have truck barrels
etc.

7.) A shift bench will be dug
for sanitation needs.

8.) Agreed to meet with the BLM
Friday Oct 14 for lunch
at Helambu Digest - asked that
Dabbe be present

9.) In future they want to have
contractor on site for excavations

a) I replied that we couldn't
have contractor present until
permits approved

b.) They was will have two
sub excavations

10.) In future want the site
geologist at the excavations

Oct 7 Burma Vista

Arrive at 4:00 pm. Check in - meet Dethie. Dethie relates the results of BLM inspection of Hole 640-28. The environmental specialist was man who made inspection

1.) Very disturbed because we went in by different route than we showed them

(2) Unhappy with the way the tree clearing was done - says we are supposed to scatter the slash around through the trees

3.) Says we should have called them regarding the diggers of traps with backhoe

4.) Says we have to reinforce the berm around mud pit

5.) Unhappy over the cement spill says ran down one drainage for 300 meters.

6.) Sogs have no sanitation facilities

7.) Sogs have no trash receptacle and should haul all mud and any immediately.

8.) Sogs we must either pump all mud out and dispose of it close A dump or

9.) allow mud to dry in pits then fill the pits back in. if we allow mud to dry in the pit will have to place a fence around the pit.

after talking with Debbie I called Tony Hall - talked with him then called Ben and had a conference call with a.) District Manager and b.) environmental man who made suggestions.

a.) Right that because of
nature of operations the well
geological core is area only
when hole approved and
ready to drill

b.) Right then well subjected
could be present at second
situation when contractor
arrives.

c.) We will have to stand
strong that BLM must be
ready to go on site from
immediately over phone
call if they cannot on the
second site then.

11.) We must maintain open
line of communication with BLM

It seems that we should contact
the appropriate people in Washington
to establish what control
BLM has on land with several
mineral rights.