


OL 2464 2



BHC ACQUISITION

FILE NO. _____
 WELL NO. _____
 FIELD _____
 COUNTY _____
 LOCATION: _____
 SECTION: _____

COMPANY: G.E.O. (MERRY)
 N.O. 1
 COMPANY: MERRY
 N.O. 1
 COUNTY: MISSISSIPPI
 LOCATION: 2753 FT. NORTH
 SECTION: 14-23S

PERMIT/DOWN LOG _____
 DRILLING MESSAGES FROM _____
 SERVICE ORDER _____
 DATE: 11/1/85

TO LOGGED INTERVAL: 4528
 FROM LOGGED INTERVAL: 1189

TYPE FLUID IN HOLE: _____
 RIG SIZE: 3 7/8
 OTHER SERVICES: _____

IN HAVING INTERPRETATION OF LOGS, ONE SHOULD BE AWARE THAT THE LOGS DO NOT INCLUDE INTERFERENCES FROM ELECTRICAL OR OTHER SOURCES. THE COMPANY AND LOGGERS ASSUME NO LIABILITY FOR ANY LOSS OF DATA OR INTERFERENCES FROM ANY SOURCE. INTERFERENCES FROM ANY SOURCE SHOULD BE REPORTED TO THE COMPANY BY THE CUSTOMER AT THE TIME OF THE LOGGING OPERATION.

REMARKS RUN (1)

RUN	TRIP	TOOL	SERIAL NO.	SERIES NO.	POSITION
1	1	LOG	2552	1662	FREE
1	1	CFL			

COMPANY: G.E.O.
 WELL NAME: N NO.1
 SERVICE: K0284R
 REVISION: FVSFAL OX3 0007 UER 5

RUN: 1
 TRIP: 1
 DATE: 11/1/85
 TIME: 16:51:15
 MODE: PLAYBACK

