

A WITHDRAWAL

power outage 3-3-79 16:08 - no significant change in
 ≈ 15 min. temperature.

Temp. held reasonably constant at 289°F
 (min. fluctuations 2° during first 48 hrs.)

3-27 lightning caused pump failure.

3-30-79 12:00 increased flow line p. 71 to 74 psi.

B. INJECTION

— address the warm-up flow.

out in late injection.

outage 16:13 to 16:27, 3-27 (lightning)