


GL02867-3 of 10

CI-1 ✓

Abandoned 10-27-89

Degrees F



□ 6.6 F/100'(394-492)

Feet (10-24)
+ 6.8 F/100'(394-492)


(10-12)

10-27-89

1/10/9


CL-6
CL-7
CL-12
CL-1
CL-2
CL-3
CL-4
CL-11

CI-2



□ 19.9 F/100' 443-492
+ See 10-12 Survey

CI-2



□ 19.9 F/100' 443-492

(10-12)


Feet (11-9)
+ See 10-12 Survey

0150000000

CI-3

Abandoned 10-27-89

Degrees F




$\frac{dT}{dF} = 12.8$
90-60m

□ 12.5 F/100' 130-190

(10-16) Feet ()
+ 12.8 F/100' 140-190

CI-4

Degrees F



□ 20.0 F/100' 180-190

(10-16)

Feet ()


+ 20.9 F/100' 170-190

19.2 (?)

CI-5

Abandoned 10-24-89

Degrees F



□ 9.9 F/100' 300-490

(10-19)

Feet


(10-24)

+ 9.7 F/100' 300-480

00000000

CI-6

Abandoned 10-24-89




□ 14.1 F/100' 420-490

(10-19)

Feet (10-24)
+ 13.0 F/100' 430-480


2014060701

CI-7



CI-8

Degrees F



□ 4.7? F/100' 40-197.

(10-23)

Feet


(11-9)

+ Isothermal

CONFIDENTIAL

CI-9

Degrees F




□ 4.4 F/100' 120-197

(10-23) Feet ()
+ 4.7 F/100' 120-190

CI-10

Abandoned 10-27-89

Degrees F



$\frac{dT}{dz} = 6.3^\circ F$
45-60m


□ 6.1 F/100 164-197

(10-24) Feet ()
+ 6.4 F/100' 150-190

CI-11

CI-11

Abandoned 10-27-89



(10-24) Feet ()

□ 9.0 F/100' 180-230

+ 9.7 F/100' 190-220