



Field Section
2 of 2

Back Flow Test 2.5
Oct 23 data
GL02974-21




100 90 80 70 60 50 40 30 20 10 0




PRINTED IN U.S.A.
CHART NO. LIC-0100-0025

PRINTED IN U.S.A.

CHART NO. LIC-0100-0025





PRINTED IN U.S.A.
CHART NO. LIC-0100-0025


0 10 20 30 40 50 60 70 80 90 100


10-23-82 Test 2-D Backflow
0027
RRGP#5
Chart speed = 5cm/min.
ch 1 PH
2 conductivity
3 ORP
(28)

0 10 20 30 40 50 60 70 80 90 100

100 90 80 70 60 50 40 30 20 10 0

0 10 20 30 40 50 60 70 80 90 100





15:55
START 145-150 RPM
BRAX FLOW.

17:00
162745

16:00

1546
Turn pump off 154130

mashed
filter

15:00

feller plugged

13:00

12:00

11:00

← 9:53

Tracer injection
on 9:40

Oct 22/82
Test 20

Oct 22/92
Test 20

100 90 80 70 60 50 40 30 20 10 0

08:00

07:00

06:00

0 10 20 30 40 50 60 70 80 90 100

05:00


04:00

03:00

100 90 80 70 60 50 40 30 20 10 0

02:17

01:10



24:21

24:05
10-22-82

24:21

23:00

22:10


21:00

20:00





19:00

18:00



17:00



100 90 80 70 60 50 40 30 20 10 0



0 10 20 30 40 50 60 70 80 90 100



10-21-82

Start of Section 2 of 2