



6107315\_2

OBSERVED DOWNHOLE DRAWDOWN!  
AT RRGE #1 MILE RESERVOIR TESTING  
RRGE #2 AT ~ 400 GPM




OBSERVED DOWNHOLE DRAWDOWN!  
AT RRGE #1 MILE RESERVOIR TESTING  
RRGE #2 AT ~ 400 GPM






OBSERVED DOWNHOLE DRAWDOWN!  
AT RRGE #1 MILE RESERVOIR TESTING  
RRGE #2 AT ~ 400 GPM




OBSERVED DOWNHOLE DRAWDOWN  
AT RRGE #1 WHILE RESERVOIR TESTING  
RRGE #2 AT ~ 400 GPM





OBSERVED DOWNHOLE DRAWDOWN!  
AT RRGE #1 MILE RESERVOIR TESTING  
RRGE #2 AT ~ 400 GPM



OBSERVED DOWNHOLE DRAWDOWN  
AT RRGE #1 MILE RESERVOIR TESTING  
RRGE #2 AT ~ 400 GPM

